A Division of General Dynamics Corporation San Diego, California

SPEC NO: ZD-22-00	3	DATE:			
CUSTOMER: Delta Ai	r Lines Inc.	MCL 10,158 Dtd			
CHANGE NO:100	1	MODEL: (880) 22-2			
TITLE: Tinted In	nterior Cabin Windows,	Installation of			
ORIGIN: TWA requested, Reference: TWA TWX dated 15 October 1957; and Convair proposed for Delta. NEASON FOR CHANGE:					
lieu of o	clear plexiglass.	n interior cabin windows in			
	EFFECT ON WEIGHT *	EFFECT ON BALANCE *			
Guar. Wt. Smpty	Oper. Wt. Empty				
0	0	O Inch Lb.			
EFFECT ON GUARANTEI	D PERFORMANCE: *				
	None				
* Negligible Change Totals Reflected	* Negligible Changes Will be Accumulated and Totals Reflected in a Future Change Proposal				
	is Change is Dependent of the Following Chan				
		Engineering Approval			
LATEST DATE OF ACCE	PTANCE: AIRP	LANES AFFECTED:			
SPECIAL PROVISIONS:		CT ON PRICE PER AIRPLANE:			
	Non-	rring:			
No.	Tota	1:			
ACCEPTED:	CONV	AIR, A Div. of Gen. Dyn. Corp.			
BY:	DV				
	, ————————————————————————————————————	hief of Contract Administration			

Delta Air Lines Inc. CONVAIR: SD Change No. 100

Tinted Interior Cabin Windows, Installation of Title:

Origin: TWA requested, Reference: TWA TWX dated 15 October 1957;

and Convair proposed for Delta.

Reason for Change: To provide tinted plexiglass in interior cabin windows in lieu of clear plexiglass.

Description of Change:

Page 28, Paragraph 3.7.1.4 WINDOWS:

Add the following to the end of the paragraph:

"All interior cabin windows shall be tinted with a "cast-in" grey color, equivalent to ROHM-HAAS Plexiglass Grey 2094".

Effect on Weight Empty: 0 Effect on Balance: 0 Effect on Performance: None

CONVAIR

S CIVISION OF GENERAL DYNAMICS CORPORATION HAN OUT SO, CALIFORNIA

SPEC NO. ZD- 22-903		DATE:
CUSTOMER: Delta Air Lines Inc.		MCL 10,155 DTD 28 October 1957
HAMGE NO. 99A		MODEL: (880) 22-2
TITLE 52-Inch Wide Passenger So	ats, In	stallation of
Santa Monica on 22 July 1	1958	
REASON FOR CHANGE. To provide a seat	in acc	ordance with Customer comments.
EFFECT ON WEIGHT .	4-	EFFECT ON BALANCE *
See attached sheet.	•	INCH LB.
EFFECT ON GUARANTEED PERFORMANCE: "	None	
PRIOR ACCEPTANCE OF THIS CHANGE IS DEPENDENT UPPLIER ACCEPTANCE OF THIS CHANGE IS DEPENDENT UPPLIER ACCEPTANCE OF THE FOLLOWING CHANGE	POSAL	
PROJECTOR PARTY OF THE BECOMING CITALS	Aug Wi	ENGINEERING APPROVAL
CATEST DATE OF ACCEPTANCE:	AIRPL	ANES AFFECTED:
SPECIAL PROVISIONS	RECUP HON-R	ET ON PRICE PER AIRPLANE. RRING: ECURRING:
) GOET LOS	CONV	AIR, A DIVISION OF SELERAL DYNAMICS CORP.
BY:		
DATE		Control of Arteria

WEIGHT DATA

PROPOSAL "A"

Effect on Guaranteed Weight Empty: #98.0 pounds Effect on Operating Weight Empty: Effect on Balance:

Effect on Performance:

498.0 pounds 485,848 inch-pounds

None

PROPOSAL "B"

Effect on Guaranteed Weight Empty: /123.0 pounds Effect on Operating Weight Empty: Effect on Balance:

Effect on Performance:

/123.0 pounds

≠107,748 inch-pounds

None

PROPOSAL "C"

Effect on Guaranteed Weight Empty: /131.0 pounds Effect on Operating Weight Empty:

Effect on Balance: Effect on Performance:

#131.0 pounds
#114,756 inch-pounds

None

PROPOSAL "D"

Effect on Guaranteed Weight Empty: /156.0 pounds

Effect on Operating Weight Empty: Effect on Balance: Effect on Performance:

≠156.0 pounds

#136,656 inch-pounds

None

CONVAIR: SD

Delta Air Lines Inc. Change No. 99A

Page 1 of 5

52-Inch Wide Passenger Seats, Installation of Title:

Joint Convair and National Seating Meeting with Delta at Santa Origin:

Monica on 22 July 1958

Reason for Change: To provide a seat in accordance with Customer com-

ments.

Description of Change:

PROPOSAL "A"

Page 104. Paragraph 3.19.1.1.6 PASSENGER SEATS:

Add the following to the end of the paragraph:

"Hole provisions on seat base shall be made for the future incorporation of optional two-position tubular foot rest."

Figure 1-2, INBOARD PROFILE AND PLAN VIEW:

Revise figure to show the following seat width and spacing:

"a. 52.0 inches - total width

3.2 inches - side arm width 5.0 inches - center arm width b.

20.2 inches - clearance between arms, each seat."

Figure 1-3, ALTERNATE SEATING ARRANGEMENT:

Revise Standard Section of "Mixed Seating Arrangement" of figure in same manner as Figure 1-2.

Enclosure: (A) One copy sketch "CONVAIR 880 52" SEAT", Sheets 1 through 4 (for information only)

Effect on Weight Empty: Effect on Balance: Effect on Performance: 498.0 pounds

485.848 inch-pounds

None

The following shall not appear in the Specification language:

See CCP No. 138, Cabin Interior Modification and 12-Place Club Area, for revision of four cabin double seats and two lounge double CONVAIR: SD

Delta Air Lines Inc.
Change No. 99A

Page 2 of 5

seats to four double and one quadruple club area seats.

Equipment interchangeability for standard seats is covered in CCP
No. 138.

The increase represented by Proposal "A" is for the following:

a. Increased structure and trim of center arm rest.
b. Increased width of each back structure and padding.
c. Increased width of each bottom structure and cushions.
d. Increased width of each food tray and food tray supporting structure.

Plug-in food trays shall be provided for four seat places aft of club area partition. Plug-in food trays shall be shipped as loose equipment for four seat places aft of movable coat dividers. Plug-in receptacles shall be installed on two rows of cabin seats per airplane. Mounting provisions shall be made for plug-in receptacles on all cabin seat places. Plug-in receptacles shall be shipped as loose equipment for all cabin passenger seats except those as installed above.

CONVAIR: SD

Delta Air Lines Inc. Change No. 99A

Page 3 of 5

PROPOSAL "B"

Same as Proposal "A" except, add the following to the end of paragraph 3.19.1.1.6 PASSENGER SDATS:

"The following shall be provided: wide outside arms."

Effect on Weight Empty: #123.0 pounds
Effect on Balance: #107,748 inch-pounds
Effect on Performance: None

CONVAIR: SD

Delta Air Lines Inc. Change No. 99A

Page 4 of 5

PROPOSAL "C"

Same as Proposal "A" except add the following to the end of paragraph 3.19.1.1.6 PASSENGER SHATS:

"The following shall be provided: hydraulic recline locks."

Effect on Weight Empty: #131.0 pounds
Effect on Balance: #114,756 inch-pounds
Effect on Performance: None

CHIVAIR: SD

Delta Air Lines Inc. Change No. 99A


Page 5 of 5

PROPOSAL "D"


Same as Proposal "A" except add the following to the end of paragraph 3.19.1.1.6 PASSINGEL SLATS:

"The following shall be provided: wide outside arms and hydraulic recline locks."

Effect on Weight Empty: /156.0 pounds Effect on Balance: /136,656 inch-pounds Effect on Performance: None




CONVAR 880 52 SEAT - DELTA



CONVAIR 660 52 SEAT - DELTA

Enclosure to CCP No. 99A



CONVAIR 880 52" SEAT

A Division of General Dynamics Corporation San Diego, California

SPEC NO: ZD-22-003	•	DATE: Rev. 12 December 1957			
CUSTOMER: Delta Air Lines Inc.		MCL 10,156A Dtd 18 November 1957			
CHANGE NO: 98		MODEL: (880) 22-2			
TITLE: Refueling	Illumination Ligh	ts, Installation of			
ORIGIN: Reference:	Delta comments and 22 August 1 Customer reques	Rejected			
	EFFECT ON WEIGH				
Guar. Wt. Empty	oper. Wt. Empty				
+3.3 lbs	+3.3 lbs	+2937 Inch lb.			
FFFECT ON GUARANTEE	D_PERFORMANCE: *	None			
* Negligible Change Totals Reflected Acceptance of the Prior Acceptance	es Will be Accumu in a Future Chan is Change is Depe of the Following	ndent Upon			
LATEST DATE OF ACC	EPTANCE:	AIRPLANES AFFECTED:			
SPECIAL PROVISIONS:		EFFLOT ON PRICE PER ATRPLANE: Recurring: Non-Recurring Total:			
ACCEPTED:		CONVAIR, A Div. of Gen. Dyn. Corp.			
BY:DATE:		BY: Chief of Contract Administration Commercial			

Delta Air Lines Inc. Change No. 98

CONVAIR: SD

Title: Refueling Illumination Lights, Installation of

Origin: Reference: Delta comments on Mock-Up reviews of 27 February

& 22 August 1957.

Reason for Change: Customer requested.

Description of Change:

Page 75, add the following new paragraphs to the page:

"3.16.8.1.7 REFUELING ILLUMINATION LIGHTS: A white light, not to exceed 15 cp, shall be installed, one each in the inboard pylon wing fairings to provide illumination at the wing lower surface refueling points.

3.16.8.1.7.1 CONTROL: Control of the refueling illumination lights shall be through the existing micro-switches, located one each in the refueling panels on the left and right hand inboard pylons, for automatic energizing of the refueling illumination lights when the refueling panel doors are opened."

Effect on Weight Empty: +3.3 pounds

Effect on Balance: +2937 inch-pounds

Effect on Performance: None

A Division of General Dynamics Corporation San Diego, California

01110 110. 20-22-00 3		PATE:		
CUSTOMER: Delta Air Lines Inc.		MCLDtd_		
CHANGE NO: 97		HODEL: (880) 22-2		
TITLE: Specification	on Administrative Char	nge		
ORIGIN: Convair init	tiated			
REASON FOR CHANGE: To incorporate Convair Standard Wiring Specification No. 0-09001 into the Detail Specification as a replacement for Wiring Specification No. ZM-256.				
Guar. Wt. Empty	FFFECT ON WEIGHT *	EFFECT ON BALANCE *		
O	Oper. Wt. Empty			
U	0	O Inch Lb.		
DFFECT ON GUARANTEE	ED PERFORMANCE: * None			
* Negligible Change Totals Reflected	es Will be Accumulated in a Future Change P	l and reposal		
Acceptance of thi Prior Acceptance	is Change is Dependent of the Following Char	Upon nges:		
		Engineering Approval		
LATEST DATE OF ACCEPTANCE: AIRPLANES AFFECTED:				
SPECIAL PROVISIONS:		CCT ON PRICE PER AIRPLANE: Recurring		
ACCEPTED:	CON	MATR, A Div. of Gen. Dyn. Corp.		
BY: DATE:		hief of Contract Administration Commercial		

Title: Specification Administrative Change

Origin: Convair initiated

Reason for Change: To incorporate Convair Standard Wiring

Specification No.0-09001 into the Detail Specification as a replacement for Wiring

Specification No. ZM-256.

Description of Change:

Page 7, Paragraph 2.1 APPLICABLE SPECIFICATIONS:

Change third item in Specification list as follows:

From: Convair Electrical and Electronic Installation Specification ZM-256".

To: "Convair Installation of Aircraft Electrical and Electronics Wiring Specification No. 0-09001".

Delete "ZM-256" where appearing in the following Specification sections, and substitute "0-09100".

Page 66, Paragraph 3.16.3, in third line.

Page 67, Paragraph 3.16.5.1, in fourth line.

Page 68, Paragraph 3.16.5.6, in third line.

Page 70, Paragraph 3.16.6, in fourth line.

Page 92, Paragraph, 3.17.1.3, in second line.

Paragraph, 3.17.1.3.2, in third line.

Page 94, Paragraph, 3.17.1.3.8, in second line

Effect on Weight Empty: 0 Effect on Balance: 0 Effect on Performance: None

A Division of General Dynamics Corporation San Diego, California

SPISC NO: ZD-22-003		DATE:
CUSTOMER: Delta Air Lines Inc.		MCL Dtd
CHANGE NO: 96		MODEL: (880) 22-2
TITLE: Specificat	tion Administrative Ch	ange
ORIGIN: Convair in	nitiated.	
REASON FOR CHANGE:	To clarify the inten	t of the Specification.
Chan III in	EFFECT ON WEIGHT *	EFFECT ON BALANCE *
Guar. Wt. Empty O	Oper. Wt. Empty O	O Inch Lb.
EFTECT ON GUARANTEE	ED PERFORMANCE: * None	
* Negligible Change Totals Reflected	es Will be Accumulated in a Future Change Pr	and oposal
Acceptance of thi Prior Acceptance	s Change is Dependent of the Following Chan	Upon ges:
		Engineering Approval
LATEST DATE OF ACCE	PTANCE: AIRP	LANES AFFECTED:
SPECIAL PROVISIONS:	Recu Non-	CT ON PRICE PER AIRPLANE: rring: Recurring
ACCEPTED:		ATR, A Div. of Gen. Dyn. Corp.
BY:	BY:	4 10 Feb 20 10 20 10 Feb There employees a 10 page of 4 disease senter and productions observed accordance.
DATE:		nief of Contract Administration Commercial

Title: Specification Administrative Change

Origin: Convair initiated.

deason for Change: To clarify the intent of the Specification.

Description of Change:

Page 96, Paragraph 3.17.1.7 CIRCUIT PROTECTION:

avise third sentence as follows:

From: "All circuit breakers shall have switch type handles."

"All circuit breaker switches shall be of the push-pull type."

Effect on Weight Empty: O Effect on Balance: O Effect on Performance: None

C () N V A I R A Division of General Dynamics Corporation San Diego, California

SPEC NO: ZD-22-00	3	DATE:
CUSTOMER: Delta Air Lines Inc.		_ MCL Dtd
CHANGE NO: 95		MODEL: (880) 22- 2
TITLE: Flush Type	e Mooring Attachm	ents, Deletion of
ORIGIN: Reference	: Delta Letter,	File 142, dated 4 April 1957
REASON FOR CHANGE:	Customer reques	ted.
	EFFECT ON WEIG	
Guar. Wt. Empty	Oper. Wt. Empt	y
-4.0 lbs	-4.0 lbs	-4004 Inch Lb.
EFFECT ON GUARANTEI	ED PERFORMANCE: *	
	N	one
* Wegligible Change Totals Reflected	es Will be Accumu in a Future Chan	lated and ge Proposal
Acceptance of the Prior Acceptance	is Change is Depe of the Following	ndent Upon Changes:
		Engineering Approval
LATEST DATE OF ACC	EPTANCE:	AIRPLANES AFFECTED:
SPECIAL PROVISIONS		EFFECT ON PRICE PER AIRPLANE: Recurring: Non-Recurring Total:
ACCEPTED:		CONVAIR, A Div. of Gen. Dyn. Corp.
BY:		BY: Chief of Contract Administration Commercial

Delta Air Lines Inc. Change No. 95

CONVAIR: SD

Flush Type Mooring Attachments, Deletion of Title:

Origin: Reference: Delta Letter, File 142, dated 4 April 1957

Reason for Change: Customer requested.

Description of Change:

Page 124, Paragraph 3.22.3 MOORING PROVISIONS:

Delete the first sentence and substitute the following: "Special mooring attachments shall not be provided."

Effect on Weight Empty: -4.0 pounds Effect on Balance: -4004 inch-pounds

Effect on Balance: -4004 Effect on Performance: None

A Division of General Dynamics Corporation San Diego, California

SPEC NO: <u>ZD-22-00</u> 3			DATE:		
CUSTOMER: Delta Air Lines Inc.		1	MCL 10,167	Dtd 5 Dece	ember 1957
CHANGE NO 93A			MODEL: (880) 22-2	
FITHE: Applicable I	rederal Regulation	ons			
ORIGIN: Contractor	r initiated.				
REASON FOR CHANGE: To incorporate all applicable Federal Regulations, which relate to CAA certification of the airplane, into the Detail Specification; and revision to CCP No. 93.				tions, plane, to CCP	
	EFFECT ON WEIG		EFF	ECT ON BAL	ANCE *
Guar. Wt. Empty	Oper. Wt. Emp	ty			
+2.5 lbs	+2.5 lbs			+1,438 In	ch lib.
REFECT ON GUARANTEI	ED PERFORMANCE:				
* Negligible Change Totals Reflected	es Will be Accum in a Future Cha	ulated nge Pro	and posal		
Acceptance of the Prior Acceptance	is Change is Dep of the Followin	endent g Chang	Upon es:		
			Er	ngineering	Approval
LATEST DATE OF ACC	EPTANCE:	AIRPL	ANES AFFECTI	ED:	
SPECIAL PROVISIONS:		EFFECT ON PRICE PER AIRPLANE: Recurring: Non-Recurring Total:			
ACCEPTED:		CONVA	IR, A Div.	of Gen. Dyr	. Corp.
BY:		BY:	e and any in the second second	ya nagangingan	
DATE:		Ch	ief of Cont	ract Admini nmercial	stration

Delta Air Lines Inc. Change No. 93A

CO WATE: SD

Applicable Federal Regulations Title:

Origin: Contractor initiated.

Reason for Change: To incorporate all applicable Federal Regulations,

which relate to CAA certification of the airplane, into the Detail Specification; and revision to CCP

No. 93.

Description of Change:

Page 7, Paragraph 2.1 APPLICABLE SPECIFICATIONS:

Delete paragraph title and the first ten lines of the paragraph and substitute the following:

"2.1 APPLICABLE FEDERAL REGULATIONS: Civil Air Regulation Part 4b as amended to 31 December 1953 and amendments:

4b-1 adopted 13 April 1954

4b-2 adopted 20 July 1955

4b-3 adopted 7 February 1956 4b-4 adopted 25 February 1957

4b-5 adopted 5 March 1957 8 July 1957 4b-6 adopted

4b-7 adopted 12 September 1957; and

Special Civil Air Regulation SR-422 adopted 23 July 1957 to the extent that Part 4b, said amendments and Special Civil Air Regulation apply to turbo-jet powered transport land type airplanes, and special rulings as necessary to obtain an airworthiness type certificate in the transport category. Civil Air Board Regulations, amendments and special regulations and Civil Aeronautics Administration rules, policies and interpretations which become effective after 27 August 1957 shall be subject to the change order procedures in the Purchase Agreement."

Add the following new paragraph to Page 74:

"3.16.8.1.2.2 LANDING LIGHT INDICATOR LIGHTS: An indicator light for each landing light shall be provided in the pilots' compartment. Indicator lights shall be illuminated when the landing lights are not fully retracted."

Effect on Weight Empty: +2.5 pounds Effect on Balance: +1,438 inch-pounds

None Effect on Performance:

A Division of General Dynamics Corporation San Diego, California

SPEC NO: ZD-22-003	DATE:		
CUSTOMER: Delta Air Lines Inc.	MCLDtd		
CHANGE NO: 92	'MODEL: (880) 22-2		
TITLE: VHF Communication Antenna,	Relocation of		
ORIGIN: Contractor Initiated			
REASON FOR CHANGE: To provide better location.	performance and a more favorable		
· · EFFECT ON WEIGHT	* EFFECT ON BALANCE *		
Guar. Wt. Empty Oper. Wt. Empty			
0 0	0 Inch Lb.		
EFFECT ON GUARANTEED PERFORMANCE: *			
Non	le .		
* Negligible Changes Will be Accumulated and Totals Reflected in a Future Change Proposal			
Acceptance of this Change is Depender Prior Acceptance of the Following Ch	ent Upon nanges:		
	Engineering Approval		
LATEST DATE OF ACCEPTANCE: AIRPLANES AFFECTED:			
Re No	EFFECT ON PRICE PER AIRPLANE: Recurring: Non-Recurring Total:		
ACCEPTED: CO	ONVAIR, A Div. of Gen. Dyn. Corp.		
BY: BY	Chief of Contract Administration Commercial		

Delta Air Lines Inc. Change No. 92

CONVAIR: SD

Title: VHF Communication Antenna, Relocation of

Origin: Contractor Initiated

Reason for Change: To provide better performance and a more favorable

location.

Description of Change:

Page 97, Paragraph 3.17.2.1.1 ANTENNA:

Revise the first sentence to read as follows:

"One faired-in type antenna shall be installed on the top centerline of the fuselage."

Page 46, APPENDIX I-C, ELECTRONIC EQUIPMENT:

Change under VHF Communication Antenna:

From: 1 Antenna (Flush Type) Collins 37R-1


To: 1 Antenna (Faired-in Type) Convair

Figure 3.17-3 RADIO GENERAL ARRANGEMENT

Delete: The above present Figure 3-17-3 and replace with . Enclosure (A).

Enclosure: (A) One (1) copy Page 102C, Antenna Arrangement Illustration

Effect on Weight Empty: 0
Effect on Balance: 0
Effect on Performance: None



C O N V A I R A Division of General Dynamics Corporation San Diego, California

SPEC NO: ZD-22-003		_ DATE:	DATE:		
CUSTOMER: Delta Ai	r Lines Inc.	MCL	Dtd		
CHANGE NO: 91A		MODEL: (880) 22-2		
TITLE: Structura	l Provisions for	Overwater Opera	ation		
ORIGIN: TWA reque	sted and Convair	proposed for De	elta.		
REASON FOR CHANGE: To provide additional strength in underside of fuse- lage in event water ditching of airplane is neces- sary; and revision to CCP No. 91.					
	EFFECT ON WEIG		EFFECT ON BALANCE *		
Guar. Wt. Empty	Oper. Wt. Empt	A			
0	0		0 Inch Lb.		
EFFECT ON GUARANTE	ED PERFORMANCE: *				
	None				
* Negligible Change Totals Reflected	* Negligible Changes Will be Accumulated and Totals Reflected in a Future Change Proposal				
Acceptance of the Prior Acceptance	is Change is Deper of the Following	ndent Upon Changes:			
Engineering Approval					
LATEST DATE OF ACCEPTANCE: AIRPLANES AFFECTED:					
SPECIAL PROVISIONS:		EFFECT ON PRIC	E PER AIRPLANE:		
		Non-Recurring			
ACCEPTED:		Total:			
ACCEPTED: BY:		Total: CONVAIR, A Div BY:			

Delta Air Lines Inc. Change No. 91A

CONVAIR: SD

Structural Provisions for Overwater Operation Title:

Origin: TWA requested and Convair proposed for Delta

To provide additional strength in underside of Heason for Change:

fuselage in event water ditching of airplane is

necessary; and revision to CCP No. 91.

Description of Change:

Page 24, Paragraph 3.7.1.1 DESCRIPTION:

Add the following sentences to the end of paragraph:

"Structural provisions shall be made, in the fuselage below the cabin floor level only, to permit the airplane to withstand water ditching loads compatible with the results obtained from NACA model tests. The structural provisions shall include reinforcement to the frames, hinges and latches of the following closures:

Two cargo doors

Electronic compartment access door

3. Hydraulic compartment access door 4. Door at the top of nose wheel well Door at the top of nose wheel well

5. Two miscellaneous equipment access doors (Sta. 221, L. & R.)

Additional local doublers and reinforcement as required shall be provided on the longerons adjacent to the doors."

Effect on Weight Empty: O pounds
Effect on Balance: O inch-pounds

Effect on Performance: None

A Division of General Dynamics Corporation San Diego, California

20-55-00	5	DATE:	The state of the s
CUSTOMER: Delta A	r Lines Inc.	MCL	Dtd
CHANGE NO: 90		MODEL:_	(880) 22-2
TITLE: Specificati	on Administrative (hange	
ORIGIN: Contractor	initiated		
REASON FOR CHANGE:	To clarify present	specificat	tion
	EFFECT ON WEIGHT	*	EFFECT ON BALANCE *
Guar. Wt. Empty	Oper. Wt. Empty		
0	0		O Inch Lb.
EFFECT ON GUARANTE	ED PERFORMANCE: *		
	None		
* Negligible Change Totals Reflected	es Will be Accumula in a Future Change		
	is Change is Depend of the Following C		
			Engineering Approval
LATEST DATE OF ACCE	EPTANCE: A	IRPLANES AF	FECTED:
SPECIAL PROVISIONS:	R N	ecurring:on-Recurrin	ICE PER AIRPLANE:
ACCEPTED:	C	ONVAIR, A D	iv. of Gen. Dyn. Corp.
BY:	В	Y:	
DATE:		Chief of	Contract Administration Commercial

CONVAIR: S.D.

Delta Air Lines Inc. Change No. 90

Page 1 of 1

Title: Specification Administrative Change

Origin: Contractor Initiated

Reason For Change: To clarify present specification

Description of Change:

Page 74, Paragraph 3.16.8.14 ANTI-COLLISION LIGHTS:

Revise the third sentence to read as follows:

"Drainage provisions shall be made in the lower light to assure fluid drainage as a result of accumulation of condensed moisture or other fluids which may become trapped".

Add the following after the third sentence:

"The installation of the upper light shall be sealed to prevent condensation and the entrance of moisture".

Effect on Weight Empty: 0
Effect on Balance: 0
Effect on Performance: None

A Division of General Pynamics Corporation San Diego, California

SPEC NO: ZD-22-00	3	_ DATE:	<u> </u>		
CUSTOMER: Delta Ai	r Lines Inc.	MCL	Dtd		
CHANGE NO: 89		_ MODEL:_	(880) 22- 2		
TITLE: Specification	on Administrative	Change			
ORIGIN: Contractor	initiated				
REASON FOR CHANGE:	To clarify inte	ent of the Spe	ecification		
	EFFECT ON WEIG	HT *	EFFECT ON BALANCE *		
Guar. Wt. Empty	Oper. Wt. Empt	У			
0	0		o Inch Ib.		
EFFECT ON GUARANTEE	EFFECT ON GUARANTEED PERFORMANCE: *				
	None		THE STREET OF THE STREET		
* Negligible Changes Will be Accumulated and Totals Reflected in a Future Change Proposal					
Acceptance of thi Prior Acceptance	s Change is Depe of the Following	ndent Upon Changes:			
			Engineering Approval		
LATEST DATE OF ACCE	PTANCE:	AIRPLANES AF	FECTED:		
SPECIAL PROVISIONS:			RICE PER AIRPLANE:		
		Recurring: Non-Recurring			
		Total:			
ACCEPTED:		CONVAIR, A	Div. of Gen. Dyn. Corp.		
BY:		BY:			
DATE:		Chief of	Contract Administration Commercial		

Delta Air Lines Inc. Change No. 89

CONVAIR: SD

Title: Specification Administrative Change

Origin: Contractor initiated

Reason for Change: To clarify intent of the Specification

Description of Change:

Page 123, Paragraph 3.20.33 PRESSURE CONTROLS:

Revise the last sentence in paragraph to read as follows:

"On the ground, with full compressor output, maximum differential pressure will be less than .3 Hg with .2 Hg as a design objective".

Effect on Weight Empty: 0
Effect on Balance: 0
Effect on Performance: None

C O N V A I R A Division of General Dynamics Corporation San Diego, California

SPEC NO: ZD-22-003		DATE:		
CUSTOMER: Delta Air Lines Inc.		MCL 10.148 Dtd		
CHANGE NO: 88		MODEL: (880) 22- 2		
Revision of Auto Pilot, Installation of Rotary Rudder Servo in Lieu of Linear Actuator				
ORIGIN: Contractor initiated.				
REASON FOR CHANGE:	aileron and ele	erchangeable parts between rudder, evator Servo motors; and to improve for maintenance.		
	EFFECT ON WEIG			
Guar. Wt. Empty	Oper. Wt. Emp	ty		
+4.0 lbs	+4.0 lbs	+5228 Inch Lb.		
EFFECT ON GUARANTEI	ED PERFORMANCE:	* None		
* Negligible Change Totals Reflected Acceptance of the Prior Acceptance	in a Future Char is Change is Dep	nge Proposal endent Upon		
		Engineering Approval		
LATEST DATE OF ACCI	EPTANCE:	AIRPLANES AFFECTED:		
SPECIAL PROVISIONS:		EFFECT ON PRICE PER AIRPLANE: Recurring: Non-Recurring Total:		
ACCEPTED:		CONVAIR, A Div. of Gen. Dyn. Corp.		
BY: DATE:		BY: Chief of Contract Administration Commercial		

Delta Air Lines Inc. Change No. 88

CONVAIR: SD

Revision of Auto Pilot, Installation of Rotary Rudder Servo in Lieu of Linear Actuator Title:

Origin: Convair initiated.

Reason for Change: To provide interchangeable parts between rudder,

aileron and elevator Servo Motors; and to improve

accessibility for maintenance.

Description of Change:

Page A8. APPENDIX I-C. INSTRUMENTS AND RELATED EQUIPMENT:

Under "Auto-Pilot", change the below items as follows:

2 Servo Drive From:

To: 3 Servo Drive

From: 2 Servo Bracket

To: 3 Servo Braket

Delete "1 Rudder Actuator"

Enclosure: (A) Four (4) copies of sketch showing proposed change from a linear to a rotary actuator for rudder control system of autopilot.

Effect on Weight Empty: +4.0 pounds

Effect on Balance: +5228 inch-pounds

Effect on Performance: None Delta - Change no. 87

Cancelled

(Andrhed in CCP. No.]

Per. 10-23-57)

Dal. Charge no. 86

(Cancellel) Date 10-21-57

A Division of General Dynamics Corporation San Diego, California

SPMC NO: ZD-22-00	3	DATE:				
CUSTOMER: Delta Ai	r Lines Inc.	MCL	Dtd			
CHANGE NO: 85B		MODEL:_	(880) 22-1	2		
TITLE: National Ai	TITLE: National Aircraft Standard Fasteners, Use of					
ORIGIN: Contractor	initiated					
TEASON FOR CHANGE:	To include the highin the standard for use in the aircrait	astener cate	gory specii	ried for		
	EFFECT ON WEIGHT		LFFECT ON	BALANCE *		
Guar. Wt. Empty	Oper. Wt. Empty					
0	0		0	Inch Lb.		
EFFECT ON GUARANTEI	ED PERFORMANCE: *					
	None					
* Negligible Change Totals Reflected	es Will be Accumula in a Future Change					
Acceptance of the Prior Acceptance	is Change is Depend of the Following C	lent Upon Changes:				
			Engineer	ing Approval		
LATEST DATE OF ACC	SPTANCE: 4	AIRPLANES AF	FECTED:			
SPECIAL PROVISIONS	1	FFECT ON PR Recurring:_ Ion-Recurrin Total:	g			
ACCEPTED:	(CONVAIR, A D	iv. of Gen.	Dyn. Corp.		
BY: DATE:		Chief of	Contract Ad Commercia	lministration		

CONVAIR: S.D.

Delta Air Lines Inc. Change No. 85B

Page 1 of 1

Title: National Aircraft Standard Fasteners, Use of

Origin: Contractor initiated

Reason for Change: To include the high strength NAS bolts and screws

in the standard fastener category specified for use in the aircraft; and revision to CCP No. 85A

Description of Change:

Page 2, Paragraph 1.1 SCOPE

Revise second paragraph on page as follows:

"It shall be permissible to use Huck lock bolts, barrel nuts, taper pins, roll pins, shear type camlock fasteners, Hi-shear rivets, Jo-bolts, corrosion resisting steel rivets, internal wrenching bolts as well as AN, MS, NAS and Convair standard fasteners".

Effect on Weight Empty: 0
Effect on Balance: 0
Effect on Performance: None

Exhibit "A", not a part of Specification language.

- 1. NAS internal wrenching bolts are now part of MS Standards
- 2. Convair is installing NAS external wrenching bolts and screws in some applications.

A Division of General Dynamics Corporation San Diego, California

SPEC NO: ZD-22-00	3	DATE:		
CUSTOMER: Delta A	ir Lines Inc.	MOE 10,146 Pld 9 October 1957		
CHANGE NO: 84		10 DEL: (880) 22-2		
TITLE: Deletion of Rain Erosion		sions and Installation of a Radome		
	quest Ref: Conva	ir and Delta meeting Dated 26 Sept.		
1957 MASON FOR CHANGE:	To reduce weight			
	ERMICE OH WEIGH	HI * ' SEPREM OF BALANCE *		
Guar. Wt. Empty	Oper. Mt. Empty			
-15.0 lbs	-15.0 lbs	-6456 Inch i.b.		
IMPRICT ON GUALAITEED PERFORMANCE: *				
	None			
* Negligible Change Totals Reflected	es Will be Accumu in a Future Chan	ilated and ige Proposal		
Acceptance of the	is Change is Depe of the Following	endent. Upon 7 Changes:		
vent or a common of the common		Engineering Approval		
LATEST DATE OF ACC	PTANCE:	ATRPLANUS AFFECTED:		
SPICIAL PROVISIONS	:	DEFECT OF POICE PRE ATTPLANT:		
		Non-Necurring Total:		
	,			
ACCEPTAD:	2000	CONVAIR, A Div. of Gen. Dyn. Corp.		
BY:		DY: Chief of Contract administration Commercial		

CONVAIR: SD

Delta Air Lines Inc. Change No. 84

Page 1 of 1

Title: Deletion of Anti-icing Provisions and Installation of a Radome Rain Erosion Boot.

Origin: Customer request, Ref. Convair and Delta Meeting Dated 26 Sept. 1957

Reason for Change: To reduce weight.

Description of Change:

Page 27, Paragraph 3.7.1.2 CONSTRUCTION:

Add the following to end of paragraph:

"A rain erosion boot shall be installed on the nose radome".

Page 102, Paragraph 3.17.4.1 WEATHER PENETRATION AIRBORNE RADAR:

Change the seventh line starting with "An adequate anti-iced radome"

To: "The radome"

Page 121, Paragraph 3.20.2.1 ANTI-ICING OF NONTRANSPARENT AREAS:

Delete the third sentence as follows:

"Adequate anti-icing of the radome shall be provided".

Figure 3.20-1 AIR CONDITIONING SCHEMATIC:

Revise figure as required to reflect above change.

Effect on Weight Empty: -15.0 pounds

Effect on Balance: -64,561 inch-pounds

Effect on Performance: None

A Division of General Dynamics Corporation San Diego, California

SPEC NO: ZD-22-003		DATE:	
CUSTOMER: Delta Air Lines Inc.		MCL 10,141 Dtd	
CHANGE NO: 83A		MODEL: (880) 22-2	
	Brake System, Revision		
ORIGIN: for Delta;	equested by TWA and C and Delta Letter Fil	e 142, dated 6 November 1957.	
REASON FOR CHANGE: To change from dual cable to single cable system between brake metering valves and brake pedals; and revision to CCP No. 83.			
	EFFECT ON WEIGHT *	EFFECT ON ,BALANCE *	
Guar. Wt. Empty	Oper. Wt. Empty		
-5.0 lbs	-5.0 lbs	-4,236 Inch Lb.	
EFFECT ON GUARANTEED PERFORMANCE: * None			
* Negligible Change Totals Reflected	es Will be Accumulated in a Future Change Pr	and, coposal	
Acceptance of the Prior Acceptance	is Change is Dependent of the Following Char	Upon nges:	
		Engineering Approval	
LATEST DATE OF ACC	EPTANCE: AIR	PLANES AFFECTED:	
SPECIAL PROVISIONS	Reci Non-	ECT ON PRICE PER AIRPLANE: : arring: -Recurring al:	
ACCEPTED:	CON	VAIR, A Div. of Gen. Dyn. Corp.	
BY:		Chief of Contract Administration Commercial	
D 55 L x J 6 2 2	20-11-2		

CONVAIR: SD

Emergency Brake System, Revision to Title:

Verbally requested by TWA and Convair proposed, where applicable, for Delta; and Delta Letter File 142, dated 6 November Origin:

1957.

Reason for Change: To change from dual cable to single cable system

between brake metering valves and brake pedals; and

revision to CCP No. 83.

Description of Change:

Page 64, Paragraph 3.15.1.11 BRAKE VALVE:

Revise the first sentence to read as follows:

"The brake metering valves shall be controlled by a single cable system from the brake pedals."

Figure 3.15-1 HYDRAULIC SYSTEM:

Revise figure to reflect above changes.

Effect on Weight Empty: -5.0 pounds
Effect on Balance: -4,236 inch-pounds Effect on Balance:

Effect on Performance: None

A Division of General Dynamics Corporation San Diego, California

SPEC NO: ZD-22-00	3	DATE:		
CUSTOMER: Delta Air Lines Inc.		MCL Dtd		
CHANGE NO: 82		MODEL: (880) 22-2		
TITEE: "Basic T" I Panel and N	Instrument Arrange discellaneous Corr	ement For The Pilot and Co-Pilot's rections.		
ORIGIN: In accordan	nce with CAR Amend	dment 4B-7.		
REASON FOR CHANGE:				
	EFFECT ON WEIG	HT * EFFECT ON BALANCE *		
Guar. Wt. Empty	Oper. Wt. Empt	У		
Negligible	Negligible	None Inch Lb.		
EFFECT ON GUARANTE	EFFECT ON GUARANTEED PERFORMANCE: *			
	7	lone		
* Negligible Change Totals Reflected	es Will be Accumu in a Future Chan	lated and ge Proposal		
Acceptance of the Prior Acceptance				
		Engineering Approval		
LATEST DATE OF ACC	EPTANCE:	AIRPLANES AFFECTED:		
SPECIAL PROVISIONS		EFFECT ON PRICE PER AIRPLANE: Recurring: Non-Recurring Total:		
ACCEPTED:		CONVAIR, A Div. of Gen. Dyn. Corp.		
BY:		BY: Chief of Contract Administration Commercial		

CONVAIR: S.D.

Delta Air Lines Inc. Change No. 82

Page 1 of 2

Title: "Basic T" Instrument Arrangement For The Pilot and Co-Pilot's

Panel and Miscellaneous Corrections

Origin: In accordance with CAR Amendment 4B-7.

Reason for Change: To comply with CAR Amendment 4B-7.

Description of Change:

Page 58, Paragraph 3.14.1.1 PILOTS INSTRUMENT:

Change last item in Equipment List to read as follows:

"One Power Failure Indicator (essential bus)"

Delete present illustration Figure 3.14-1 and replace with revised attached illustration Figure 3.14-1.

Page A9, APPENDIX I-C, INSTRUMENTS AND RELATED EQUIPMENT:

Delete the eighth and ninth items in the Equipment List as follows:

"l Switch Computer Selector l Warning Light

Kollsman Convair^u

NOTE: (Not to be included in Specification language.)

- 1. The essential bus failure warning lights, as shown on the attached illustration, are as approved on the Mock-Up. The pilots instruments and other equipment are connected to the pilot's essential bus. The power to pilots instruments is taken off the pilots essential bus switch relays, therefore if a failure of the source of power that the pilot has selected occurs the pilot can then choose another source to supply the power.
- 2. (a) The airspeed electrical warning light has been replaced by Kollsman with an electrical fail indicating flag built into the airspeed instrument.
 - (b) The air data computer selector switch has been deleted from Appendix I-C since Convair shall supply switching "As Required" to provide satisfactory operation of the KIFIS system.
- 3. A compass slave switch has been relocated under the C-6 compass to be compatible with basic "T" instrument arrangement.
- 4. A guarded landing gear down lock override button has been added to the diagram for clarity as shown in the Mock-Up. The

CONVAIR: S.D.

Delta Air Lines Inc. Change No. 82

Page 2 of 2

landing gear cannot be inadvertently raised on the ground. If in flight should a malfunction of the ground protection system occur, the manual override will allow raising of the handle to retract the gear.

Effect on Weight Empty: Negligible

Effect on Balance: None Effect on Performance: None

C O N V A I R A Division of General Dynamics Corporation San Diego, California

GPEC NO: ZD-22-00	3	DATE:				
CUSTOMER: Delta Air Lines Inc.		MCL 10,191 Dtd 10 February 1958				
CHANGE NO: 81A		MODEL: (880) 22- 2				
TITLE: Vickers Hyd	raulic Pumps, Instal	lation of				
ORIGIN: TWA request	ORIGIN: TWA requested and Convair proposed for Delta.					
REASON FOR CHANGE:	As above.					
	EFFECT ON WEIGHT	* EFFECT ON BALANCE *				
Guar. Wt. Empty	Oper. Wt. Empty					
+29.0 lbs	+29.0 lbs	+21,750 Inch Lb.				
EFFECT ON GUARANTEED PERFORMANCE: * None						
* Negligible Changes Will be Accumulated and Totals Reflected in a Future Change Proposal. Acceptance of this Change is Dependent Upon Prior Acceptance of the Following Changes:						
		Engineering Approval				
LAFEST DATE OF ACC	EPTANCE: Al	IRPLANES AFFECTED:				
SPECIAL PROVISIONS	FFECT ON PRICE PER AIRPLANE: ecurring: on-Recurring otal:					
ACCEPTED:	Co	ONVAIR, A Div. of Gen. Dyn. Corp.				
BY: DATE:		Y: Chief of Contract Administration Commercial				

Delta Air Lines Inc. Change No. 81A

CONVAIR: SD

Vickers Hydraulic Pumps, Installation of Title:

Origin: TWA requested and Convair proposed for Delta.

Reason for Change: As above.

Description of Change:

Page AlO, APPENDIX I-C, HYDRAULIC EQUIPMENT:

Change fourth item in Description List as follows:

521415" Ham. Standard From "4 - Main System Pumps (variable displacement type)

"4 - Main System Pumps To: (variable displacement type) Vickers Model 3913"

Effect on Weight Empty: +29.0 pounds Effect on Balance: +21,750 inch-pounds

Effect on Performance: None Dal- Change No. 81

(Rejected)

A Division of General Dynamics Corporation San Diego, California

SPEC NO: ZD-22-00	3	DATE:	
CUSTOMER: Delta Ai	r Lines Inc.	MCL 10,135	Dtd 17 September 19
CHANGE NO: 80A			80) 22-2
TITLE: 15-Ampere	Electrical Recep	ptacle, Installati	en of
TWA requested, Reference: TWA Letter No. 8808-15, dated 13 September 1957; and Convair proposed for Delta To provide a receptacle, and wiring of greater electrical load capacity at the loading ramps; and revision to CCP No. 80.			
	EFFECT ON WE		FFECT ON BALANCE *
Guar. Wt. Empty	Oper. Wt. Emp	pty	
41.0 1b	+1.0 26		+700 Inch Lb.
EFFECT ON GUARANTEED PERFORMANCE: * None Rejected			
* Negligible Change Totals Reflected Acceptance of thi	in a Future Cha is Change is Dep	enge Proposal	
Prior Acceptance	of the Followin	ng Changes:	
		I	Engineering Approval
LATEST DATE OF ACCI	PTANCE:	AIRPLANUS AFFEC	TED:
SPECIAL PROVISIONS:		EFFECT ON PRICE Recurring: Non-Recurring Total:	
ACCEPTED:		CONVAIR, A Div.	of Gen. Dyn. Corp.
BY: DATE:			cract Administration ommercial

Delta Air Lines Inc. Change No. 80A

CONVAIR: SD

16

15-Ampere Electrical Receptacle, Installation of Title:

TWA Letter No. 880S-15, dated 13 Origin: TWA requested, Reference: September 1957; and Convair proposed

for Delta

Reason for Change: To provide a receptacle, and wiring of greater electrical load capacity at the loading ramps; and revision to CCP No. 80.

Description of Change:

Page 79, Paragraph 3.16.10.8 LCADING RAMP RECEPTACLES:

Revise the paragraph to read as follows:

"External direct-current power receptacles shall be installed, one each, at both passenger loading doors to furnish a maximum of 15 amperes to the loading ramp. The receptacles shall be accessible from the loading ramps. Voltage drop at rear entrance door shall not exceed 2.8 volts."

Effect on Weight Empty: +1.0 pounds

Effect on Balance: +700 Effect on Performance: None +700 inch-pounds

Dal-Charge 710. 80
(Rejected)

Dal. Change No. 79

(Rejected)

Dal- Change No. 78

(Cancellel)

C O N V A I R A Division of General Dynamics Corporation San Diego, California

SPEC NO: ZD-22-GO 3		DAT	C:		
CUSTOMER: Delta Air	Lines Inc.	MCL		ntd	
CHANGE NO: 77		MOD	EL: (880)	22-2	
TITLE: Deletion of	Customs Se	al Provisions	in Cargo	Doors	
ORIGIN: Contractor	Initiated				
REASON FOR CHANGE:	Admin1str	ative Specifi	cation Cha	nge	
	EFFECT ON	WEIGHT *	EFF	CT ON BALANCE	*
Guar. Wt. Empty	Oper. Wt.	Empty	0	Inch Li	D •
EFFECT ON GUARANTEE	PERFORMANC	CE: * None			
* Negligible Changes Totals Reflected Acceptance of this Prior Acceptance	in a Future Change is	Dependent Upo	en en	gineering Appr	o v al
LATEST DATE OF ACCE.	PTANCE:	AIRPLANI	S AFFECTE	D:	
SPECIAL PROVISIONS:		Recurring Non-Recu	ng:	ER AIRPLANE:	
ACCEPTED:		CONVAIR	, A Div. o	f Gen. Dyn. Co	rp.
BY:		BY:	P of Contr	act Administra	tion
DATE:				mercial	2.2.4.48

Title: Deletion of Customs Seal Provisions in Cargo Doors

Origin: Contractor Initiated

Reason for Change: Administrative Specification Change

Description of Change:

Page 30, Paragraph 3.7.1.5.4 CARGO DOORS:

Delete fourth sentence, starting on sixth line "(Provisions shall be made to permit cargo doors to be sealed for customs)"

Effect on Weight Empty: 0
Effect on Balance: 0
Effect on Performance: None

CONVAIR

A DIVISION OF GENERAL DYNAMICS COREGRATION SAN DIEGO, CALIFORNIA

SPEC NO.: ZD- 22-003			DATE:	
CUSTOMER: Delta Air Lines Inc.			MCL 10,117	Revised DTD 17 December 19
CHANGE NO: 76E			MODEL: 22-2	(Convair "880")
TITLE: VGH Rec	orders, Installat	ion o	£	
ORIGIN: NACA request to install subject equipment				
REASON FOR CHANGE: A	s above, and revi	sion (to CCP No. 76D	
EFFECT O	N WEIGHT "		EFFEC	T ON BALANCE *
0				O INCH LB.
EFFECT ON GUARANTEED P	ERFORMANCE: * Nor	ne		
* NEGLIGIBLE CHANGES WILL TOTALS REFLECTED IN A ACCEPTANCE OF THIS CHAPRIOR ACCEPTANCE OF TI	FUTURE CHANGE PROPOS ANGE IS DEPENDENT UPO	SAL N	Melon	GINEERING APPROVAL
LATEST DATE OF ACCEPTA	NCE:	AIRPL	ANES AFFECTED:	
		RECUR NON-RE	T ON PRICE PER AIR RING: ECURRING:	
ACCEPTED: BY:		CONVA	IR, A DIVISION OF GENI	ERAL DYNAMICS CORP.
DATE:				CONVALIGNA, GRANTA

Delta Air Lines Inc. Change No. 76E

CONVAIR: SD

Title: VGH Recorders, Installation of

Origin: NACA request to install subject equipment

Reason for Change: As above, and revision to CCP No. 76D

Description of Change:

Page 62 (Cont), Paragraph 3.14.3.9 VGH RECORDING PROVISIONS:

Revise the paragraph and paragraph title to read as follows:

"VGH RECORDER: One VGH recorder shall be installed on each of two airplanes* to record research data for gust studies. The recorder shall be installed on the autopilot rack and its acceleration transmitter on the floor beam in the rear spar area. The installation shall include mountings, aluminum tubing from the copilot's static line and the pitot line to the recorder, circuit breakers, nameplate and the necessary wiring."

Revise the single asterisk note on bottom of Page 62 (Cont) as follows:

From: "*The specific airplanes on which the VGH recorder provisions shall be installed will be Convair Production No. 16 and 17 (Delta Ship No. 4 and 5)."

To: "*The specific airplanes on which the VGH recorders shall be installed will be Convair Production Nos. 17 and 21 (Delta Ship Nos. 5 and 6)."

Not to be a part of the Specification language:

The following weight effect shall be subtracted from the as weighed figures when considering guaranteed weight of the affected airplanes and is not to be included in the accumulative specification weight figures.

Effect on Weight: +20.0 pounds

Effect on Balance: +8,334 inch-pounds

Effect on Performance: None

C (P V A T H A Division of General Dynamics Corporation San Diego, California

SPEC NO: ZD-22-003		DATE:	
CUSTOMER: Delta Air	Lines Inc.	MCJ, 10,131 Dtd	
CHANGE NO: 75A		MODEL: (880) 22- 2	
TITLE: Fuses, Incre	ease in Spares of		
ORIGIN: Contractor	initiated.		
REASON FOR CHANGE: To comply with CAR regulation on percentage of spare fuses to be provided, and revision to CCP No. 75			
	EFFECT ON WEIGH	HT * EFFECT ON BALANCE * '	
Guar. Wt. Empty	Oper. Wt. Empty		
Negligible	Negligible	Negligible Inch Lb.	
DFFECT ON GUARANTEED PERFORMANCE: * None			
* Negligible Change Totals Reflected	es Will be Accumu in a Future Chan	lated and ge Proposal.	
Acceptance of the Prior Acceptance	is Change is Depe of the Following	ndent Upon Changes:	
		Engineering Approval	
LATEST DATE OF ACC	EPTANCE:	AIRPLANES AFFECTED:	
SPECIAL PROVISIONS		EFFECT ON PRICE PER AIRPLANE: Recurring: Non-Recurring Total:	
ACCEPTED:		CONVAIR, A Div. of Gen. Dyn. Corp.	
BY: DATE:		BY: Chief of Contract Administration Commercial	

CONVAIR: SD Delta Air Lines Inc. Change No. 75A

Title: Fuses, Increase in Spares of

Origin: Contractor initiated

Reason for Change: To comply with CAR regulation on percentage of

spare fuses to be provided, and revision to CCP No. 75

Description of Change:

Page 72, Paragraph 3.16.7.1.2 - FUSES:

Revise first sentence on top of page to read as follows:

"Fuses of same rating exceeding 12 or more per airplane shall be provided with a minimum of 12 fuses or a minimum of 50 percent (whichever is greater) spares."

Effect on Weight Empty: Negligible
Effect on Balance: Negligible
Effect on Performance: None

A pivision of General Dynamics Corporation San Diego, California

SPEC NO: ZD-22-603			DATE:	
CUSTOMER: Delta Air Lines Inc.			MCL 10,129 Dtd	
CHANGE NO: 74			MODEL: (880) 22-2	
TITLE: Skydrol Hyd	raulic Fluid	l, Use of		
ORIGIN: TWA requested, Reference TWA Letter 880-232 dated 23 July 1957, and Contractor proposed for Delta. REASON FOR CHANGE: To utilize a hydraulic fluid of a less flammable characteristic.				
	EFFECT ON	WEIGHT *	EFFECT ON BALANCE *	
Guar. Wt. Empty	Oper. Wt.	Empty		
+204 lb	+204	1b	+180,140	
EFFECT ON GUARANTEED PERFORMANCE: * None				
* Negligible Changes Will be Accumulated and Totals Reflected in a Future Change Proposal Acceptance of this Change is Dependent Upon Prior Acceptance of the Following Changes:				
Engineering Approval				
LATEST DATE OF ACCEPTANCE: AIRPLANES AFFECTED:				
SPECIAL PROVISIONS: Recurring: Non-Pecurring Potal:				
ACCEPTED:		ALC: N	TAIR, A Div. of Gen. Dyn. Corp.	
DATE:		H.Y.	Thief of Contract Administration , Commercial	

CONVAIR: SD

Delta Air Lines Inc. Change No. 74

Page 1 of 2

Title: Skydrol Hydraulic Fluid, Use of

Origin: TWA requested, Reference: TWA Letter 880-232 dated 23 July

1957, and Contractor proposed for

Delta.

Reason for Change: To utilize a hydraulic fluid of a less flammable

characteristic.

Description of Change:

Page 16. Paragraph 3.2.4.1 - DETAIL STRUCTURAL FINISH:

Add the following subparagraph:

"h. Surfaces, equipment and components likely to be exposed to the hydraulic fluid specified in paragraph 3.15.1.2 shall be suitably protected against the action of this fluid."

Page 63, Paragraph 3.15.1.2 - FLUID:

Revise paragraph as follows:

"The hydraulic systems shall be designed to function with a hydraulic fluid conforming to "Skydrol 500"."

Paragraph 3.15.1.3 - PACKING AND SEALS:

Revise paragraph as follows:

"All packing, seals, gaskets and cups, in the hydraulic systems, shall be of materials suitable for use with the specified hydraulic fluid and shall, in general, be Teflon, AN Types or equivalent."

Paragraph 3.15.1.4 - LINES:

Add the following to the end of the paragraph:

"Drip pans or shrouds shall be installed in the nose wheel area, and in the aft fuselage area aft of the pressure bulkhead, as required, to contain the fluid during repair of the hydraulic system."

CONVAIR: SD

Delta Air Lines Inc. Change No. 74

Page 2 of 2

Page 68. Paragraph 3.16.5.5 - WIRE PROTECTION:

Add the following sentence to the end of the paragraph:

"Any wiring likely to be exposed to the hydraulic fluid specified in paragraph 3.15.1.2 shall have suitable resistance to such fluid."

Page 79, Paragraph 3.16.10.7 - PLUGS AND RECEPTACLES:

Add the following sentence to the end of paragraph:

"Plugs and receptacles likely to be exposed to the hydraulic fluid specified in paragraph 3.15.1.2 shall be fabricated of material resistant to the action of this fluid."

Effect on Weight Empty: + 204 pounds

+180,140 inch-pounds Effect on Balance:

Effect on Performance:

None

Dal- Change 74. A.

(Cancellel)

GONVAIR A Division of General Dynamics Corporation San Diego, California

SPEC NO: ZD-22-00:		DATE:		
CUSTOMER: Delta Air	Lines Inc.	MCI. 10,125 Dtd_		
CHANGE NO: 73		MODEL: (880) 22-2		
TITLE: Electroni	c Panel, Change of			
ORIGIN: Reference	: Delta Letter File 1	42, dated 12 July 1957		
REASON FOR CHANGE: Customer request for a panel which incorporates a Tacan facility switch and an odometer indicator.				
	EFFECT ON WEIGHT *	EFFECT ON BALANCE *		
Guar. Wt. Empty	Oper. Wt. Empty			
Negligible	Negligible	Negligible Inch Lb.		
EFFECT ON GUARANTEED PERFORMANCE: * None				
* Negligible Change Totals Reflected	es Will be Accumulated in a Future Change Pro	and oposal		
Acceptance of the Prior Acceptance	is Change is Dependent of the Following Chang	Upon ges:		
N. T. N.		Engineering Approval		
LATEST DATE OF ACC	EPTANCE: AIRP	LANES AFFECTED:		
SPECIAL PROVISIONS: EFFECT ON PRICE PER AIRPLANE: Recurring: Non-Recurring Total:				
ACCEPTED:	CONV	AIR, A Div. of Gen. Dyn. Corp.		
BY:		hief of Contract Administration Commercial		
DATE:		Commer Caul		

Delta Air Lines Inc. Change No. 73

CONVAIR: SD

Electronic Panel, Change of Title:

Reference: Delta Letter File 142, dated 12 July 1957 Origin:

Reason for Change: Customer request for a panel which incorporates a

Tacan facility switch and an odometer indicator.

Description of Change:

Page 91, Paragraph 3.17.1.1 - CONTROL PANELS:

Change the second item in Description list as follows:

From: Two VHF/VOR Control Panels

Two VHF Comm/Nav. Control Panels To:

Page A6, APPENDIX I-C, ELECTRONIC EQUIPMENT:

Change first item under CONTROL PANELS as follows:

P/N to be supplied Convair 2 VHF/VOR Control Panel From:

2 VHF/ Comm/Nav. Control Panel Gables G510V To:

Negligible Effect on Weight Empty: Effect on Balance: Effect on Performance: Negligible

None

A Division of General Dynamics Corporation San Diego, California

SPEC NO: ZD-22-003	DATE:			
CUSTOMER: Delta Air Lines In	MCL 10,130 Dtd			
CHANGE NO: 72	MODEL: (880) 22-2			
TITLE: Teleflex Controls	in Pods and Pylons, Use of			
ORIGIN: Contractor initiat	ed.			
REASON FOR CHANGE: Administ	crative specification change.			
4:				
EFFECT	ON WEIGHT * EFFECT ON BALANCE *			
Guar. Wt. Empty Oper. 1	Wt. Empty			
0 0	O Inch I.b.			
EFFECT ON GUARANTEED PERFORMANCE: * None				
* Negligible Changes Will b Totals Reflected in a Fut	* Negligible Changes Will be Accumulated and Totals Reflected in a Future Change Proposal			
Acceptance of this Change Prior Acceptance of the F	is Dependent Upon ollowing Changes:			
	Engineering Approval			
LATEST DATE OF ACCEPTANCE:	AIRPLANES AFFECTED:			
SPECIAL PROVISIONS:	EFFECT ON PRICE PER AIRPLANE: Recurring: Non-Recurring Total:			
ACCEPTED:	CONVAIR, A Div. of Gen. Dyn. Corp.			
BY: DATE:	Commercial			

CONVAIR: SD

Delta Air Lines Inc. Change No. 72

Title: Teleflex Controls in Pods and Pylons, Use of

Origin: Contractor initiated.

Reason for Change: Administrative specification change.

Description of Change:

Page 56, Paragraph 3.12.11.2 - GENERAL CONTROLS:

Delete the first sentence and add the following item to list of propulsion system controls:

"Fuel shut-off control"

Page 56, Paragraph 3.12.11.2.1 - ENGINE CONTROLS:

Change paragraph title as follows:

From: ENGINE CONTROLS

To: ENGINE POWER CONTROLS

Page 57, Paragraph 3.12.11.2.1 - Power control lever.

Delete the first two sentences from top of page and substitute the following:

"Push-pull rods and cranks from pedestal to compartment below cockpit floor, closed cable system to pylon and push-pull cable (Teleflex type) to engine control. Provisions shall be made to prevent the power control from creeping in flight."

Effect on Weight Empty: 0
Effect on Balance: 0
Effect on Performance: None

A Division of General Dynamics Corporation San Diego, California

SPEC NO: ZD-22-603		DATE:		
CUSTOMER: Delta Air Lines Inc.		MCL 10,110 Dtd 19 July 1957		
CHANGE NO: 71		MODEL: (880) 22-2		
TITLE: Landing Gear Pin Warning Lights, Installation of				
ORIGIN: Customer H	Request, Delta Letter	File 142, dated 15 July 1957		
REASON FOR CHANGE:	To install warning li gear safety pins are	ights, to indicate when landing		
	gedr sared brus are	III pracor		
	EFFECT ON WEIGHT *	EFFECT ON BALANCE *		
Guar. Wt. Empty	Oper. Wt. Empty			
+6.0 lb	+6.0 lb	+3535 Inch Lb.		
EFFECT ON GUARANTEED PERFORMANCE: *				
None				
* Negligible Changes Will be Accumulated and Totals Reflected in a Future Change Proposal				
Acceptance of this Change is Dependent Upon Prior Acceptance of the Following Changes:				
		Engineering Approval		
LATEST DATE OF ACCEPTANCE: AIRPLANES AFFECTED:				
SPECIAL PROVISIONS:		CT ON PRICE PER AIRPLANE:		
	Recu Non-	rring:Recurring		
	Tota	1:		
ACCEPTED:	CONV	AIR, A Div. of Gen. Dyn. Corp.		
BY:	BY:			
	C	hief of Contract Administration Commercial		
DATE:		Commercial		

Delta Air Lines Inc. Change No. 71

CONVAIR: SD

Title: Landin Gear Pin Warning Lights, Installation of

Origin: Customer Request, Delta Letter File 142, dated 15 July 1957

Reason for Change: To install warning lights which would indicate when

landing gear safety pins are in place.

Description of Change:

Page 33. Paragraph 3.8.1.4 - LANDING GEAR SAFETY PINS:

Add the following after the first sentence:

"Landing gear safety pin indicator lights shall be installed as specified in par. 3.16.11.1.1".

Page 80

Add the following new paragraph:

"3.16.11.1.1 LANDING GEAR PIN INDICATOR LIGHTS: An individual landing gear pin indicator light shall be provided in the flight engineers panel for each of the main and nose landing gear and shall indicate when the landing gear safety pin has not been removed."

Effect on Weight Empty: +6.0 pounds
Effect on Balance: +3535 inch-pounds
Effect on Performance: None

Dal. Change 70.70
(Rejected)

C O N V A I R A Division of General Dynamics Corporation San Diego, California

SPEC NO: ZD-22-003		DATE:		
CUSTOMER: Delta Air Lines Inc.		MCL_10_121 _Dtd		
CHANGE NO: 69		MODEL: (880) 22-		
TITLE: Main and Nose Landing Gear Wheel and Tire Size, Change of				
ORIGIN: Contractor Initiated.				
REASON FOR CHANGE: To make specification language compatible with the only main and nose landing gear wheel and tire sizes available which will meet airplane requirements.				
	EFFECT ON WEIGHT *	EFFECT ON BALANCE *		
Guar. Wt. Empty	Oper. Wt. Empty			
0	0	O Inch Lb.		
EFFECT ON GUARANTEED PERFORMANCE: * None				
* Negligible Changes Will be Accumulated and Totals Reflected in a Future Change Proposal				
Acceptance of this Change is Dependent Upon Prior Acceptance of the Following Changes:				
		Engineering Approval		
LATEST DATE OF ACCEPTANCE: AIRPLANES AFFECTED:				
SPECIAL PROVISIONS:	Recu Non-	CT ON PRICE PER AIRPLANE: rring: Recurring 1:		
ACCEPTED:	CONV	AIR, A Div. of Gen. Dyn. Corp.		
BY:	BY:_			
DATE:	C	hief of Contract Administration Commercial		

CONVAIR: SD

Delta Air Lines Inc. Change No. 69

Page 1 of 2

Title: Main and Nose Landing Gear Wheel and Tire Size, Change of

Origin: Contractor Initiated.

Reason for Change: To make specification language compatible with the only main and nose landing gear wheel and tire sizes

available which will meet airplane requirements.

Description of Change:

Page 34, Paragraph 3.8.2.2 - WHEELS, BRAKES, AND BRAKE CONTROL SYSTEMS:

Delete the first sentence and substitute the following:

"The wheels and brakes for the main landing wheels shall meet Type VII, 39 x 13 Tire and Rim Association requirements."

Page 35, Paragraph 3.8.2.3 - TIRES:

Delete the first sentence and substitute the following:

"The tubeless tires for the main landing wheels shall be Type VII, 39 x 13 tires."

Page 36, Paragraph 3.8.4.2 - WHEEL AND BRAKES:

Delete the first sentence and substitute the following:

"The wheels for the nose landing gear shall meet Type VII, 29 x 7.7 Tire and Rim Association requirements."

Page 37, Paragraph 3.8.4.3 - TIRES:

Delete the first sentence and substitute the following:

"The tubeless tires for the nose landing gear shall be Type VII, 29 x 7.7 tires."

CONVAIR: SD

Delta Air Lines Inc. Change No. 69

Page 2 of 2

Page All, APPENDIX I-C, LANDING GEAR EQUIPMENT:

Change fourth item in Description list as follows:

From: Main Wheel Tires (12.50 x 16) Type III

To: Main Wheel Tires (39 x 13) Type VII

Change seventh item in Description list as follows:

From: Nose Wheel Tires (7.50 x 14) Type III

To: Nose Wheel Tires (29 x 7.7) Type VII

Effect on Weight Empty: O Effect on Balance: None Effect on Performance: None

A Division of General Dynamics Corporation San Diego, Salifornia

SPEC NO: <u>ZD-22-60</u>	3	DA'EE:
CUSTOMER: Delta Ai	r Lines Inc.	MCL_ 10,120 Dtd_
CHANGE NO: 68		MODEL: (880) 22-
TITLE: Cockpit	Temperature Bulb and	Indicator, Removal of
REASON FOR CHANGE:	1957	Letter No. 880-160 dated 28 March and Contractor Proposed for Delta considered nonessential in the
cockpit		CONSIDER MODESSELCIAL IN the
	EFFECT ON WEIGHT *	EFFECT ON BATANCE *
Guar. Wt. Empty	Oper. Wt. Empty	
-1.8 lb	-1.8 lb	-472 Inch lib.
EFFECT ON GUARANTE	ED PERFORMANCE: *	
	None	
Totals Reflected	es Will be Accumulated in a Future Change P:	coposal.
Acceptance of the Prior Acceptance	is Change is Dependent of the Following Char	: Upon
		Engineering Approval
LATEST DATE OF ACCI	EPTANCE: AIR	PLANES AFFECTED:
SPECIAL PROVISIONS	Reci Non-	CCT ON PRICE PER ATRPLANE: Pring: Recurring
ACCEPTED:		MAIR, A Div. of Gen. Dyn. Corp.
BY:		Thief of Contract Administration

Delta Air Lines Inc. Change No. 68

Title: Cockpit Temperature Bulb and Indicator, Removal of

TWA Letter No. 880-160 dated 28 March Origin: TWA Request, Reference: 1957, and Contractor Proposed for Delta.

Reason for Change: To remove instrument which is considered nonessential in the cockpit area.

Description of Change:

Page 59. Paragraph 3.14.1.5 - INSTRUMENTS AND NAVIGATION EQUIPMENT:

Delete: The thirty-third line from instrument list as follows: "(One cockpit temperature indicator)"

Page A7. APPENDIX I-C - INSTRUMENTS AND RELATED EQUIPMENT

Delete: The tenth and eleventh lines from the equipment list as follows:

Cockpit Temperature Indicator

Cockpit Temperature Bulb

Effect on Weight Empty: -1.8 pounds

Effect on Balance: -472 Effect on Performance: None -472 inch-pounds

C O N V A I R A Division of General Dynamics Corporation San Diego, California

		ATE:
CUSTOMER: Delta Air	r Lines Inc.	CL 10.122 Dtd
CHANGE NO: 67	P	ODEL: (880) 22-2
TITLE: Nose Wheel	Well Signal Horn, Dele	tion of
ORIGIN: 1957 on Moreover of Proposed 1 REASON FOR CRANGE: The	ock-Up Review of 25 - 27 for Delta.	ter No. 880-106 dated 28 March February 1957, and Contractor didered to be a requirement in
	EFFECT ON WEIGHT *	EFFECT ON BALANCE *
Guar. Wt. Empty	Oper. Wt. Empty	
-1.2 lb	-1.2 1b	-285 Inch Lb.
EFFECT ON GUARANTEE	ED PERFORMANCE: *	
	None	
Totals Reflected Acceptance of thi	es Will be Accumulated a in a Future Change Prop is Change is Dependent U of the Following Change	pon
		Engineering Approval
LATEST DATE OF ACCE		
LATEST DATE OF ACCE	EPTANCE: AIRPLA EFFECT Recurr Non-Re	Engineering Approval
	EPTANCE: AIRPLA EFFECT Recurr Non-Re Total:	Engineering Approval NES AFFECTED: ON PRICE PER AIRPLANE: ing: curring
SPECIAL PROVISIONS:	EFFECT Recurr Non-Re Total:	Engineering Approval NES AFFECTED: ON PRICE PER AIRPLANE: ing: curring R, A Div. of Gen. Dyn. Corp.

Delta Air Lines Inc. Change No. 67

CONVAIR: SD

Nose Wheel Well Signal Horn, Deletion of Title:

TWA Requested, Reference: TWA Letter No. 880-106 dated 28 March 1957 on Mock-Up Review of 25 - 27 February 1957, and Origin:

Contractor proposed for Delta.

Reason for Change: The signal horn is not considered to be a requirement in the interphone system.

Description of Change:

Page 99, Paragraph 3.17.2.3.5 - SERVICE INTERPHONE:

Delete first sentence starting on top of page:

"(A horn, connected to a momentary call switch installed in the cockpit area, shall be provided in the nose wheel well area.)"

Effect on Weight Empty:

-1.2 pounds -285 inch-pounds Effect on Balance:

Effect on Performance: None Dal. Charge - 20. 66
(Rejicted)

C (N V A T A A Division of General Pynamics Corporation San Diego, California

GPEC NO: ZD-22-003	DATE: Revised 8 November 1957					
CUSTOMER: Delta Air Lines Inc.	MCL 10,123 Dtd 9 August 1957					
CHANGE NO: 65A	MODEL: (880) 22-2					
TITLE: Horizontal and Vertical S Assembly; Specification,	Stabilizer Leading Edges and Stabilizer and Splice Design, Change of					
ORIGIN: Contractor initiated						
horizontal and vertical stabilize stabilizer splice design from a linternal tension splices and extension	REASON FOR CHANGE: 1. To clarify intent of Specification as regards horizontal and vertical stabilizer leading edges. 2. To change the stabilizer splice design from a bolted side splice to a combination of internal tension splices and external shear splices 3. Rev. to CCP No. 65					
	HEIGHT * EFFECT ON BALANCE *					
Guar. Wt. Empty Oper. Wt. E	Impty					
-12.7 lbs -12.7 lb	bs -19,387 Inch lb.					
EFFECT ON GUARANTEED PERFORMANCE	*					
None						
* Hegligible Changes Will be Acc Totals Reflected in a Future C						
Acceptance of this Change is D Prior Acceptance of the Follow						
	Engineering Approval					
LATEST DATE OF ACCEPTANCE:	AIRPLANES AFFECTED:					
SPECIAL PROVISIONS:	EFFECT ON PRICE PER ATRPLANE: Recurring: Non-Recurring Total:					
ACCEPTED:	CONVAIR, A Div. of Gen. Dyn. Corp.					
BY: DATE:	BY: Chief of Contract Administration Commercial					

A Division of General Dynamics Corporation San Diego, California

SPEC NO: ZD-22-00:		DATE: 15 JULY 1957		
CUSTOMER: Delta Air	Lines, Inc.	MCL 10,102 Dtd		
CHANGE NO: 53		MODEL: (880) 22-2		
TITLE: Rear Lav	atories, Single Servic	e Connection, Installation of		
ORIGIN: TWA comments on airplane inspection mock-up of 25-27 February 1957 and Contractor proposed for Delta. REASON FOR CHANGE: To accomplish ground service flushing of aft lavatories through a single connection.				
	EFFECT ON WEIGHT *	EFFECT ON BALANCE *		
Guar. Wt. Empty	Oper. Wt. Empty			
+ 3.1 1b	+ 3.1 lb	+ 4145 Inch Lb.		
EFFECT ON GUARANTEE	D PERFORMANCE: * None			
Totals Reflected Acceptance of thi	s Will be Accumulated in a Future Change Pros s Change is Dependent of the Following Chang	upon		
LATEST DATE OF ACCE	PTANCE: AIRPI	ANES AFFECTED:		
SPECIAL PROVISIONS:	Recur Non-F	T ON PRICE PER AIRPLANE: ring: ecurring		
ACCEPTED:	CONVA	IR, A Div. of Gen. Dyn. Corp.		
BY:	Ch	ief of Contract Administration		
DATE:		Commercial		

Delta Air Lines Inc. Change No. 53 15 July 1957

Title: Rear Lavatories, Single Service Connection, Installation of

Origin: TWA comments on airplane inspection mock-up of 25-27 February 1957, and Contractor proposed for Delta

Reason for Change: To accomplish ground service flushing of aft lavatories through a single connection.

Description of Change:

Page 107. Paragraph 3.19.2.2 - LAVATORIES:

Add following after fourth sentence, ending on fourteenth line:

"A pressure box and access door shall be provided in the fuselage under the aft lavatories to the right of airplane centerline. Both aft lavatory drains shall be connected through a Y-fitting to a single connection to the pressure box for ground lavatory flushing. A flush line shall be provided to accomplish the ground flushing operation. Pressure caps shall be provided for the drain and flush lines."

Effect on Weight Empty: +3.1 pounds Effect on Balance: +41+5 inch-pounds

Effect on Performance: None

Dal-Change No. 52
(Concelled)

A Division of General Dynamics Corporation San Diego, California

PERC NO: ZD-55-00	3	DATE:			
CUSTOMER: Delta Ai	r Lines Inc.	MCL 10,077 Dtd 27 March 1958			
CHANGE NO: 51A		MODEL: (880) 22-2			
FITE: Performance	Data, Revision	to			
ORIGIN: Convair ini	tiated.				
REASON FOR CHANGE:	REASON FOR CHANGE: To furnish Customer with the latest available per- formance data, and revision to CCP No. 51.				
	EFFECT ON WEIG				
Guar. Wt. Empty	Oper. Wt. Empt	Ey			
0	0	0 Inch Lb.			
EFFECT ON GUARANTE	ED PERFORMANCE: *				
		As noted.			
* Negligible Change Totals Reflected	es Will be Accumu in a Future Char	alated and age Proposal			
Acceptance of the Prior Acceptance					
		Engineering Approval			
DATEST DATE OF ACC	EPTANCE:	AIRPLANES AFFECTED:			
SPECIAL PROVISIONS		EFFECT ON PRICE PER AIRPLANE: Recurring: Non-Recurring Total:			
ACCEPTED:		CONVAIR, A Div. of Gen. Dyn. Corp.			
BY:		BY: Chief of Contract Administration			
(CATTA)		Commercial			

CONVAIA: SD

Delta Air Lines Inc. Change No. 51A

.itle: Performance Data, Revision to

Grigin: Convair initiated.

Reason for Change: To furnish Customer with the latest available per-

formance data, and revision to CCP No. 51.

Description of Change:

Page 10, Paragraph 3.1.1.1, GUARANTEED PERFORMANCE:

nevise the next to last item on page as follows:

"Haximum allowable take-off weight at sea From: level in accordance with CAR 4b climb requirements (but this shall not preclude operation at 174,025 lb at start of the take-off run)

1b 173,500"

"Maximum allowable take-off weight at sea 0: level in accordance with SR-442 climb requirements (but this shall not preclude operation at 179,025 lb at the start of

Page 11, Paragraph 3.1.1.1, GUARANTEED PERFORMANCE:

Mevise the last sentence in the paragraph to read as follows:

"With an ambient temperature of 90 degrees.F. at sea level and a starting take-off weight of 179,025 lb, the airplane shall be able to take-off with an engine failure at V₁ and climb out, raising the gear and retracting the flaps, to an altitude of 1,000 feet and thereafter accelerate without loss of altitude to best angle of climb speed. climb speed, using maximum climb thrust, within a total of 5 minutes of take-off thrust."

Page 12, Paragraph 3.1.2.2 LOADING SUMMARY:

Under "Weight - Less Fuel and OIL", change the first item as follows:

From: "Fuel

66.594 1b"

To: "Fuel

70.000 lb"

Delete the following item from paragraph:

"Maximum Gross Weight - (Take-Off)

173,500 1b"

fiect on Weight Empty: 0 ffect on Balance:

ffect on Performance: As noted.

Dal-Change 710. 51
(Rejected)

C O N V A I R A Division of General Dynamics Corporation San Diego, California

SPEC NO: ZD-22-00		DATE: 24	June 19	57
CUSTOMER: Delta Air	MCI, 10033	Dtd	4-3-57	
CHANGE NO: 50		MODEL: (88	0) 22- 2	William I was
TITLE: CJ-805-3	Engine Installation	on (G.E.)		
ORIGIN: General E	lectric Proposed To improve take	off performance.		
	EFFECT ON WEIGH		FECT ON	BALANCE *
Guar. Wt. Empty None	Oper. Wt. Empty		None	Inch Lb.
EFFECT ON GUARANTE		tached sheet		
Acceptance of the	es Will be Accumul in a Future Chang is Change is Depen of the Following	e Proposal dent Upon		
		I I	Engineer	ing Approval
LATEST DATE OF ACC	EPTANCE:	AIRPLANES AFFECT	red:	
SPECIAL PROVISIONS		EFFECT ON PRICE Recurring: Non-Recurring Total:		
ACCEPTED:		CONVAIR, A Div.	of Gen.	Dyn. Corp.
BY: DATE:		BY: Chief of Con	tract Adı	

Title: CJ-805-3 Engine Installation

Origin: General Electric Proposed

Reason for Change: To improve take-off performance.

Description of Change:

Page 8, Paragraph 3.1.1 - PERFORMANCE:

Revise paragraph to read as follows:

The performance computations for the airplane are based on the Standard Configuration described herein, with doors and windows closed, with the General Electric CJ-805-3 engine, and in addition are based on the following:

- A. An NACA standard atmosphere except as noted.
- B. Except for take-off data, the engine data shown in General Electric curves A-4012162-502B (4-9-56), -503B (4-9-56), -504B (undated), -505B(3-3-56), -506B (3-3-56), -507B (3-3-56), -508B (3-3-56) and -510B (3-16-56) with the cruise specific-fuel-consumptions reduced by 4-1/2 percent as guaranteed by General Electric.
- C. The take-off data as shewn in General Electric Engine Specification No. E-723, dated 15 March 1957.
- D. A JP-4 fuel (MIL-F-5624C) having an average net heating value of 18,650 Btu/lb.
- E. With engine data corrected for operation of cabin pressurisation and air conditioning units and for installation losses excluding the effects of engine sound suppressors."

Page 8, Paragraph 3.1.1.1 - THE FOLLOWING PERFORMANCE OF THE AIRPLANE IS GUARANTEED:

Revise paragraph to read as follows:

with thrust, other than take-off, in excess of engine specification values existing at the date of revision one (1) of this specification or take-off thrust in excess of those shown in General Electric Engine Specification No. E-723 dated 15 March 1957, with all thrusts reduced for installation losses excluding the effects of engine sound suppressors. Demonstrations for all guaranteed performance shall be made under existing atmospheric conditions using NACA atmospheric tables plus humidity corrections

established by CAA. All field lengths given are for level, dry, hard surface runways and sero wind conditions. Convair need not demonstrate to Buyer those performance guarantees which are included in the CAA certified data, but copies of the CAA report showing attainment of such performances shall be furnished to the Buyer."

Revise the last three items on Page 9, and first item on Page 10 to read as follows:

Take-off distance at sea level over 50-ft obstacle in accordance with CAR 4b (1.2 V ₆₁ used for take-off speed) with a weight of 140,000 lb	ft.	±5%	4,630
Take-off distance at sea level over 50-ft obstacle in accordance with CAR 4b (1.2 Vg, used for take-off speed) with a weight of 173,500 lb at lift off in standard air	ft.	±800	7,610
Take-off distance at sea level on 90°F day over 31 ft obstacle in accordance with CAR 4b (1.2 Vs ₁ used for take-off speed) with weight of 173,500 lb at lift off	ft.	±850 ′	8,350
Take-off distance at sea level over 31-ft obstacle in accordance with CAR 4b (1.2 Vs1 used for take-off speed) on a 90 degree F day with weight of 160,000 lb	ft.	±5%	6,820

Page 7, Paragraph 2.1 - APPLICABLE SPECIFICATIONS:

Last line of page, replace "General Electric Engine Specification No. E-709" with "General Electric Engine Specification No. E-723 dated 15 March 1957".

Page	A-1	-	APPENDIX	I-G	*	POWER	PLANT	EQUIPMENT:
------	-----	---	----------	-----	---	-------	-------	------------

Part or Spec Number Manufacturer Change first item to read: (B-723 3/15/57 G.E.-CJ-805-3 4 Engines, complete

None Effect on Weight Empty: None Effect on Balances Four items as noted Effect on Performance:

CONVAIR: S. D.

Delta Air Lines Inc. Change No. 65A Revised 8 November 1957

Page 1 of 2

Horizontal and Vertical Stabilizer Leading Edges and Stabilizer Title: Assembly; Specification, and Splice Design, Change of

Origin: Contractor initiated

Reason for Change: 1. To clarify intent of Specification as regards horizontal and vertical stabilizer leading edges. 2. To change the stabilizer splice design from a bolted side splice to a combination of internal tension splices and external shear splices. 3. Revision to CCP No. 65

Description of Change:

Page 23, Paragraph 3.6.2 - STABILIZER:

Delete third sentence and substitute the following:

"The stabilizer shall be assembled by means of a centerline splice; consisting of a bolted tension type splice at internal members, and external shear type splices at upper and lower surfaces. The shear splices shall utilize Huck lock bolts".

Page 125, Paragraph 3.23.1 - EQUIPMENT INTERCHANGEABILITY:

In subparagraph "1. Interchangeable Parts", add the following items to list:

"Horizontal Stabilizer, Leading Edge Vertical Stabilizer, Leading Edge *Horizontal Stabilizer, Complete Assembly Sealing Blades, Stabilizer to Fuselage

Add the following foot note to page 125:

"* Complete stabilizer assembly interchangeable airplane to airplane by disassembly of halves at the airplane centerline for removal from the airplane. Reassemble on installation by installing internal tension bolts on an "interchangeability without alteration" basis and installing 1/64 - inch larger diameter Huck lock bolts in shear connections'

CONVAIR: S. D.

Delta Air Lines Inc. Change No. 65A Revised 8 November 1957

Page 2 of 2

Page 126, Paragraph 3.23.1 - EQUIPMENT INTERCHANGEABILITY:

In subparagraph "2. Interchangeability Without Alterations"

Delete second item on page "Horizontal Stabilizer, Complete Assembly".

In subparagraph "5. Replaceable Parts"

Delete the following fourth and fifth items from list:

"Horizontal Stabilizer Leading Edge Vertical Stabilizer, Leading Edge"

Effect on Weight Empty: -12.7 Lbs.

Effect on Balance: -19,387 Inch-Lbs.

Effect on Performance: None

CONVAIR A Division of General Dynamics Corporation San Diego, California

SPEC NO: ZD-22-00	3	_ DATE:_	
CUSTOMER: Delta Ai	r Lines Inc.	MCL	Dtd
CHANGE NO: 64A		_ MODEL:_	(880) 22- 2
TITIE: Warning S	ystem, Change to		
ORIGIN: Convair i	nitiated and Delt dated 15 May 195	a request for	revision by Letter
REASON FOR CHANGE:	To clarify the i	ntent of the No. 64.	Specification, and
	EFFECT ON WEIG		EFFECT ON BALANCE *
Guar. Wt. Empty	Oper. Wt. Empt	У	
0	0		o Inch Lb.
EFFECT ON GUARANTE		lone	
* Negligible Change Totals Reflected	es Will be Accumu in a Future Chan	lated and ige Proposal	
Acceptance of the Prior Acceptance			
			Engineering Approval
LATEST DATE OF ACCI	EPTANCE:	AIRPLANES AF	FECTED:
SPECIAL PROVISIONS		Recurring:	RICH PER AIRPLANE:
ACCEPTED:	**	CONVAIR, A	ity, of Gon. Dyn. Corp.
BY:			
DATE:			

Delta Air Lines Inc. Change No. 64A

Title: Warning System, Change to

Origin: Convair initiated and Delta request for revision by Letter

File 142, dated 15 May 1958.

Reason for Change: To clarify the intent of the Specification, and

revision to CCP No. 64.

Description of Change:

Page 41, Paragraph 3.10.2.1 LIFT AND DRAG INCREASING DEVICE SYSTEMS:

Add the following to the end of the paragraph:

"An electrical interconnect between flaps, landing gear scissors switch and throttles shall be provided. This interconnect will sound the warning horn when any two throttles are advanced to take-off position and the flaps and elevator trim are not in the take-off regime."

Page 80, Paragraph 3.16.11.1 LANDING GEAR WARNING HORN:

Add the following to the end of the paragraph:

"An electrical interconnect between flaps, landing gear scissors switch and throttles shall be provided. This interconnect will sound the warning horn when any two throttles are advanced to take-off position and the flaps and elevator trim are not in the take-off regime."

Effect on Weight Empty: 0
Effect on Balance: 0
Effect on Performance: None

C O N V A I R A Division of General Dynamics Corporation San Diego, California

SPEC NO: ZD-22-00	3	DATE:		
CUSTOMER: Delta Ai	r Lines Inc.	MCI_ 10,112 Dtd		
CHANGE NO: 63		MODEL: (880) 22-2		
TITLE: Engine Oi	l Pressure Gages, Ch	ange of		
TWA requested, Reference: Item 6a, page 3 of TWA Comments of ORIGIN: Mock-Up review dated 25, 27 February 1957, and Contractor proposed for Delta. REASON FOR CHANGE: To provide four single oil pressure indicators in lieu of two dual oil pressure indicators.				
	EFFECT ON WEIGHT	* EFFECT ON BALANCE *		
Guar. Wt. Empty	Oper. Wt. Empty			
Negligible	Neligible	Negligible Inch Lb.		
EFFECT ON GUARANTE	ED PERFORMANCE: * Nor	le la		
Totals Reflected Acceptance of thi	es Will be Accumulation a Future Change is Change is Dependent of the Following Ch	Proposal ent Upon		
LATEST DATE OF ACCI	EPTANCE: Al	RPLANES AFFECTED:		
SPECIAL PROVISIONS	Re No	FFECT ON PRICE PER AIRPLANE: ecurring: on-Recurring otal:		
ACCEPTED:	CC	ONVAIR, A Div. of Gen. Dyn. Corp.		
BY: DATE:		Chief of Contract Administration Commercial		

CONVAIR: SD Delta Air Lines Inc.
Change No. 63

Title: Engine Oil Pressure Gages, Change of

Origin: TWA requested, Reference: Item 6a, page 3 of TWA Comments of

Mock-Up review dated 25, 27 February 1957, and Contractor proposed

for Delta.

Reason for Change: To provide four single oil pressure indicators in

lieu of two dual oil pressure indicators.

Description of Change:

Page 59. Paragraph 3.14.1.4 - FLIGHT ENGINEER'S INSTRUMENTS:

Change first item in instrument list as follows:

From: Four oil pressure gages (2 dual)

To: Four indicators, engine oil pressure

Page Al, APPENDIX I-C, POWER PLANT EQUIPMENT:

Change first item under "OIL SYSTEM EQUIPMENT":

From: "2 011 Pressure Gages (Dual)

To: 4 Indicators, Engine Oil Pressure"

Effect on Weight Empty: Negligible Effect on Balance: Negligible Effect on Performance: None

The following not to appear in Specification language:

"Manufacturer's name and/or part number will be provided in APPENDIX I-C on Customer acceptance of this Change No. 63, as soon as available."

Dal. Changed 20.62
(Rejected)

C O N V A I it A Division of General Dynamics Corporation San Diego, California

SPEC NO: ZD-22-003		DATE:
CUSTOMER: Delta Air	Lines Inc.	MCL 10,104 Revised 25 Sept.1957 Dtd 19 July 1957
CHANGE NO: 61A		MODEL: (880) 22-2
TITLE: Door Open Wa	rning Indicator, Ins	tallation of
ORIGIN: Contractor 1	nitiated	
REASON FOR CHANGE:	To provide increase to show which speci:	indication of open doors and fic door is not fully closed.
	EFFECT ON WEIGHT *	EFFECT ON BALANCE *
Guar. Wt. Empty	Oper. Wt. Empty	
+4.0 lb	+4.0 lb	+2935 Inch Lb.
EFFECT ON GUARANTEI	ED PERFORMANCE: *	
	N	one
* Negligible Change Totals Reflected	es Will be Accumulate in a Future Change F	d and roposal
Acceptance of the Prior Acceptance	is Change is Dependent of the Following Cha	t Upon nges:
		Engineering Approval
LATEST DATE OF ACCI	EPTANCE: AIF	PLANES AFFECTED:
SPECIAL PROVISIONS	Rec Nor	ECT ON PRICE PER AIRPLANE: urring: -Recurring :al:
ACCEPTED:	CON	WAIR, A Div. of Gen. Dyn. Corp.
BY: DATE:		Chief of Contract Administration Commercial

Delta Air Lines Inc Change No. 61A

CONVAIR: SD

Title: Door Open Warning Indicator, Installation of

Origin: Contractor Initiated

Reason for Change: To provide increased indication of open doors and

to show which specific door is not fully closed.

Description of Change:

Page 80, Add the following new paragraph:

DOOR OPEN WARNING INDICATORS: An individual door open warning indicator light shall be provided at the flight engineer's station above the flight engineer's panel adjacent to the landing gear pin warning lights for each of the two main entrance doors, the two service doors, the two cargo doors, the electronics and hydraulics doors and the aft bulkhead pressure door. The warning system shall indicate each specific door which is not fully closed."

age 89. Paragraph 3.16.17.1 EMERGENCY POWER:

Add to bottom of "Warning List": "Door Open Warning Indicators"

Effect on Weight Empty: +4.0 pounds

Effect on Balance: +2935 inch-pounds

Effect on Performance: None

C O N V A I R A Division of General Dynamics Corporation San Diego, California

SPING NO: ZD-22-00		DATE:		
CUSTOMER: Delta Air	r Lines Inc.	MCL 10,144 Dtd		
CHANGE NO: 60A		MODEL: (880) 22-2		
TITLE: Cabin Compr	ressor Low Oil Pressu	re Warning Light, Deletion of		
ORIGIN: Contractor	initiated.			
REASON FOR CHANGE: Compressor was redesigned to delete oil pump, therefore a low oil pressure warning light is not required.				
	EFFECT ON WEIGHT	EFFECT ON BALANCE	*	
Guar. Wt. Empty	Oper. Wt. Empty			
-1.0 lb	-1.0 lb	-400 Inch Li	0.	
EFFECT ON GUARANTEI		one		
* Negligible Change Totals Reflected	es Will be Accumulate in a Future Change F	ed and Proposal		
	is Change is Depender of the Following Cha		oval	
LATEST DATE OF ACCI	EPTANCE: AIR	RPLANES AFFECTED:		
SPECIAL PROVISIONS	Rec Nor	TECT ON PRICE PER AIRPLANE: curring: -Recurring cal:		
ACCEPTED:	COI	WAIR, A Div. of Gen. Dyn. Co.	rp.	
BY:	BY:	Chief of Contract Administra	tion	
DATE:		Commercial		

Delta Air Lines Inc. Change No. 60A

CONVAIR: SD

Title: Cabin Compressor Low Oil Pressure Warning Light, Deletion of

Origin: Contractor intiated.

Reason for Change: Compressor was redesigned to delete oil pump,

therefore a low oil pressure warning light is not

required.

Description of Change:

Page 59. Paragraph 3.14.1.4 FLIGHT ENGINEER'S INSTRUMENTS:

Delete the following item from the instrument list:

"2 Warning light, cabin compressor low oil pressure."

Page A7. APPENDIX I-C. INSTRUMENTS AND RELATED EQUIPMENT:

Delete the following item from the Description list:

Warning light, cabin compressor low oil pressure."

Effect on Weight Empty: Effect on Balance:

-1.0 pound -400 inch-pound

Effect on Performance: None

Dal. Charge X 59
(Rejected)

A Division of General Dynamics Corporation San Diego, California

SPEC NO: ZD-22-003		DATE: 24 JULY 1937		
CUSTOMER: Delta Air Lines Inc.		MCL 10.105 Dtd		
CHANGE NO: 58		MODEL: (880) 22-2		
TITLE: C-10 Compass System, Changes to				
ORIGIN: Reference: Delta Letter, File 142, dated 17 April 1957 REASON FOR CHANGE: Customer requested.				
	EFFECT ON WEIGHT *	EFFECT ON BALANCE *		
Guar. Wt. Empty	Oper. Wt. Empty			
-3.9 lb	-3.9 lb	-1100 Inch Lb.		
EFFECT ON GUARANTEED PERFORMANCE: * None				
* Negligible Changes Will be Accumulated and Totals Reflected in a Future Change Proposal				
Acceptance of this Change is Dependent Upon Prior Acceptance of the Following Changes:				
Engineering Approval				
LATEST DATE OF ACCEPTANCE: AIRPLANES AFFECTED:				
SPECIAL PROVISIONS	Recu Non-	CT ON PRICE PER AIRPLANE: irring: Recurring al:		
ACCEPTED:	CONV	VAIR, A Div. of Gen. Dyn. Corp.		
BY:DATE:		Chief of Contract Administration Commercial		

CONVAIR: 8D

Delta Air Lines Inc. Change No. 58 24 July 1957

Title: C-10 Compass System, Changes to

Origin: Reference: Delta Letter, File 142, dated 17 April 1957

Reason for Change: Customer requested.

Description of Change:

Page A8, APPENDIX I-C, INSTRUMENTS AND RELATED EQUIPMENT:

Change "REMOTE COMPASS SYSTEM" Equipment List to read as follows:

Quan. Reqd.	Description	Manufacturer	Part or Spec. Number
	REMOTE COMPASS SYSTEM Sperry C-10 Compass System		
2222	Flux Valve Compass Indicator Directional Gyro Rack Assembly 1 Servo Amplifier 1 Slaving Amplifier	Sperry Sperry Sperry Sperry Sperry Sperry	620359 613260-2 614937-10 618379 621107

Note: (Not a part of specification language.)

* Part number called out in CCP No. 28A, revised 18 July 1957.

Effect on Weight Empty:

-3.9 pounds -1100 inch-pounds Effect on Balance:

Effect on Performance: None

C O N V A I R A Division of General Dynamics Corporation San Diego, California

SPEC NO: ZD-22-003	DATE: 19 July 1957			
CUSTOMER: Delta Air Lines Inc.	MCL_10,106			
CHANGE NO: 57	MODEL: (880) 22-2			
TITLE: Exterior Lighting, Changes to				
ORIGIN: 1957, and Contractor propo	ock-up inspection of 25-27 February sed for Delta.			
REASON FOR CHANGE: To make exterior lighting common between DAL and TWA configurations.				
EFFECT ON WEI	GHT * EFFECT ON BALANCE *			
Guar. Wt. Empty Oper. Wt. Emp				
Negligible Negligible	Negligible Inch lb.			
EFFECT ON GUARANTEED PERFORMANCE: *				
	None			
* Negligible Changes Will be Accumulated and Totals Reflected in a Future Change Proposal				
Acceptance of this Change is Dependent Upon Prior Acceptance of the Following Changes:				
Engineering Approval				
LATEST DATE OF ACCEPTANCE:	AIRPLANES AFFECTED:			
SPECIAL PROVISIONS:	EFFECT ON PRICE PER AIRPLANE: Recurring:			
	Non-Recurring			
ACCEPTED:	CONVAIR, A Div. of Gen. Dyn. Corp.			
BY:	BY:			
DATE:	Chief of Contract Administration Commercial			

CONVAIR: SD

Delta Air Lines Inc. Change No. 57 19 July 1957 Page 1 of 2

Title: Exterior Lighting, Changes to

Origin: TWA comments on airplane mock-up inspection of 25-27 February

1957, and Contractor proposed for Delta.

Reason for Change: To make exterior lighting common between DAL and TWA

configurations.

Description of Change:

Page 74, Paragraph 3.16.8.1.1 - FUSELAGE AND POSITION:

Change paragraph title to "POSITION LIGHTS", and delete second and third sentences.

Paragraph 3.16.8.1.1.1 - CONTROL:

Delete paragraph and substitute following:

"Switches shall be installed in the system as required to control the forward and rearward position lights."

Paragraph 3.16.8.1.3 - AUXILIARY LANDING LIGHT:

Delete paragraph and substitute following:

"Two 600-watt white auxiliary landing lights shall be installed; one on each side of the wing leading edge stub section. The lights shall be provided with a positioning adjustment not controllable in flight. The lights shall also be usable as taxi lights."

Paragraph 3.16.8.1.3.1 - CONTROL:

Revise paragraph to read as follows:

"A switch shall be installed on the forward center overhead switch panel to control the auxiliary landing lights."

Page 75, Paragraph 3.16.8.1.6 - SIGNAL LIGHT:

Delete paragraph and substitute following:

"The two 600-watt auxiliary landing lights, described in Paragraph 3.16.8.1.3, shall be combination lights so arranged as to also serve as signal lights.

Paragraph 3.16.8.1.6.1 - CONTROL:

Delate entire paragraph.

CONVAIR: SD

Delta Air Lines Inc. Change No. 57 19 July 1957 Page 2 of 2

Page 85, Paragraph 3.16.17 - ESSENTIAL POWER:

Under "Lighting", delete following items:

" 9 Fuselage Lights
10 Position Light Flasher".

Page A2, APPENDIX I-C, ELECTRICAL EQUIPMENT:

Under "EXTERIOR LIGHTS", change following item:

From: 1 Signal Light

To: 2 Auxiliary Landing Lights (Signal Lights)

Delete eighth item: "1 Taxi Light".

Effect on Weight Empty: Negligible Effect on Balance: Negligible Effect on Performance: None

Dat. Change Xv. 56
(Rejected)

Dol. Change 20.55

(Cancelled)

C O N V A I R A Division of General Dynamics Corporation San Diego, California

COMMERCIAL CHANGE PROPOSAL Reports.					
SPEC NO: ZD-22-003		DA'TE:			
CUSTOMER: Delta Air Lines Inc.		MCL 10,091 Dtd 19 June 1957			
CHANGE NO: 54A		MODEL: (880) 22-2			
TITLE: Selective Calling System, Relocation of					
ORIGIN: Reference: TWA Letter 880-155 dated 20 May 1957, and Contractor proposed for Delta					
REASON FOR CHANGE: To facilitate inspection and maintenance of unit by relocation to a more accessible area.					
	EFFECT ON WEIGHT *	EFFECT ON BALANCE *			
Guar. Wt. Empty	Oper. Wt. Empty				
+3.5 lb	+3.5 lb	+1,050 Inch I.b.			
EFFECT ON GUARANTE	ED PERFORMANCE: *				
Elited on deline	None				
* Negligible Changes Will be Accumulated and Totals Reflected in a Future Change Proposal					
a this Change is Dependent Upon					
Prior Acceptance of the Following Changes: Engineering Approval					
LATEST DATE OF ACCEPTANCE: AIRPLANES AFFECTED:					
EFFECT ON PRICE PER AIRPLANE:					
SPECIAL PROVISIONS:		Recurring:			
	Tota	1:			
ACCEPTED:	ACCEPTED: CONVAIR, A Div. of Gen. Dyn.				
	BY:				
BY:		Chief of Contract Administration Commercial			
DATE:		Confiner orax			

Delta Air Lines Inc. Change No. 54A

Title: Selective Calling System, Relocation of

Origin: Reference: TWA Letter 880-155 dated 20 May 1957, and

Contractor proposed for Delta

Reason for Change: To facilitate inspection and maintenance of unit by

relocation to a more accessible area.

Description of Change:

Page 100, Paragraph 3.17.2.4 - AIRBORNE SELECTIVE CALLING:

Add the following to the end of the paragraph:

"The provisions shall be made in the forward left hand passenger coat compartment and arranged to provide accessibility to equipment from the flight deck."

Effect on Weight Empty: +3.5 pounds

Effect on Balance: +1050 inch-pounds

Effect on Performance: None

SPEC NO: 40-22-003		DATE: 1 JULY 1937	
CUSTOMER: Delta Air	Lines Inc.	MCL 10,093 Dtd 21 June 1957	
CHANGE NO: 49		MODEL: (880) 22-2	
TITLE: ATC Tran	sponder, 51R4 Receiver tion and Type Changes	and Remler P.A. Amplifier; of	
ORIGIN: Customer between	requested, Reference: Convair and Delta repr	Meeting of 20 June 1957 esentatives.	
REASON FOR CHANGE: Customer request to change ATC Transponder from installation to provisions, and changes in type of VHF Navigation Receivers and P.A. Amplifier.			
	EFFECT ON WEIGHT *	EFFECT ON BALANCE *	
Guar. Wt. Empty	Oper. Wt. Empty		
- 37.9 lb	- 37.9 lb	-9148 Inch Lb.	
EFFECT ON GUARANTEED PERFORMANCE: * None			
* Negligible Changes Will be Accumulated and Totals Reflected in a Future Change Proposal Acceptance of this Change is Dependent Upon Prior Acceptance of the Following Changes:			
Engineering Approval			
LATEST DATE OF ACCEPTANCE: AIRPLANES AFFECTED:			
SPECIAL PROVISIONS:	Recur Non-l	CT ON PRICE PER AIRPLANE: rring: Recurring	
ACCEPTED:	CONV	AIR, A Div. of Gen. Dyn. Corp.	
BY: DATE:	Cl	nief of Contract Administration Commercial	

Delta Air Lines Inc. Change No. 49 1 July 1957 Page 1 of 2

ATC Transponder, 51R+ Receiver and Remler P.A. Amplifier; Installation and Type Changes of Title:

Origin: Customer requested, Reference: Meeting of 20 June 1957 between Convair and Delta

representatives.

Reason for Change: Customer request to change ATC Transponder from

installation to provisions for, and changes in type of VHF Navigation Receivers and P.A. Amplifier.

Description of Change:

Page 90, Paragraph 3.17.1 - EQUIPMENT:

Delete fifth item in Description List, "One ATC Beacon Transponder System".

Under "Complete provisions for the following systems shall be made",

"Second ATC Transponder Beacon System" to "Dual ATC Change: Transponder Beacon System".

Page 98, Paragraph 3.17.2.3.5 - SERVICE INTERPHONE:

To end of first sentence add "and H.F. tuner location".

Page A4. APPENDIX I-C. ELECTRONIC EQUIPMENT:

Under "HF NAVIGATION SYSTEM"

Change: 2 Receivers Collins 51R4

To: 2 Receivers Collins 51X2

Add: VOR/LOC, Instrumen- Collins tation Unit 2 344B-1

Page A5, APPENDIX I-C, ELECTRONIC EQUIPMENT:

Delete following item:

MATC TRANSPONDER BEACON

1 ATC Transponder Beacon ARINC SPEC 532A

Delta Air Lines Inc. Change No. 49 1 July 1957 Page 2 of 2

Page A5, APPENDIX I-C, ELECTRONIC EQUIPMENT (Continued)

Under PASSENGER ENTERTAINMENT (PA) SYSTEM

Remler A550 Change: 1 Amplifier

Collins 346D-1 To: 1 Amplifier

Effect on Weight Empty: -37.9 pounds Effect on Balance: -9148 inch-pounds Effect on Performance: None

SPEC NO: ZD-22-00		DATE: 29 May 1957	
CUSTOMER: Delta Air Lines, Inc.		MCL 10045 Dtd	
CHANGE NO: 48		MODEL: (880) 22-2	
TITLE: Selection	of Electronic Equi	pment	
ORIGIN: Minutes of Meeting between Convair and Delta, dated 16 January 1957 REASON FOR CHANGE: Customer requested.			
	EFFECT ON WEIGHT	* EFFECT ON BALANCE *	
Guar. Wt. Empty	Oper. Wt. Empty		
+ 0.2 lb	+ 0.2 lb	+ 987 Inch Lb.	
EFFECT ON GUARANTE	EFFECT ON GUARANTEED PERFORMANCE: *		
	Non	18	
* Negligible Changes Will be Accumulated and Totals Reflected in a Future Change Proposal Acceptance of this Change is Dependent Upon Prior Acceptance of the Following Changes:			
Engineering Approval			
LATEST DATE OF ACCEPTANCE: AIRPLANES AFFECTED:			
SPECIAL PROVISIONS	Re No	FFECT ON PRICE PER AIRPLANE: ecurring: on-Recurring otal:	
ACCEPTED:	CO	ONVAIR, A Div. of Gen. Dyn. Corp.	
BY:	B	Chief of Contract Administration	
DATE:		Commercial Commercial	

Delta Air Lines, Inc. Change No. 48 29 May 1957 Page 1 of 5

american

Title: Selection of Electronic Equipment.

Origin: Minutes of Meeting between Convair and Delta, dated 16

January 1957.

Reason for Change: Customer requested.

Description of Change:

Page 88, Paragraph 3.16.17.1 - EMERGENCY POWER:

Under "Power Packs", in item "2", add "Phase" before "Instrument", in item "3" add "Phase" before "Instrument", and in item "4" add "Phase" before "Lighting".

Page 90, Paragraph 3.17.1 - EQUIPMENT:

Under "Space provisions for the following systems shall be made", delete: "Proximity Warning System"
"Terrain Warning System"
"Dual Tacan System"

Add to list: "Tacan Azimuth Accessory Units (2-1/4 ATR Spaces)"

Page 91, Paragraph 3.17.1.1 - CONTROL PANELS:

In Description list, change second item to read: "Two VHF/VHF NAV (ILS-DMET) Control Panels"

Change seventh item to read: "One Dual Selective Call System Control Panel"

Delete from Description list: "One Marker Beacon Hi-Low Control Switch"

Change the sixth item to read: "One Dual ATC Transpender Control Panel with Marker Beacon Hi-Low Switch"

Add: "Four Audio Selector Control Panels (one each side console, one flight engineer and one electronic compartment)"

Delete following from paragraph: "Provisions for the following panels shall be made:
Radar Identification Control Second ATC Beacon Transponder Control"

Delta Air Lines, Inc. Change No. 48 29 May 1957 Page 2 of 5

Page 93, Paragraph 3.17.1.3.4 - SPARE TERMINALS AND SPARE WIRES:

In second line, change "space" to "spare".

Page 95, Paragraph 3.17.1.6.3 - CABLE:

Change paragraph title to "CABLES", and in third line delete "overhead", and in last line on page change "panel" to "panels".

Page 96, Paragraph 3.17.1.7.1 - D-C POWER CONTROLS:
In fourth line, delete "terrain warning".

Page 97, Paragraph 3.17.2.1.1 - ANTENNA:

Delete last sentence and substitute following:

"A low drag external antenna shall also be installed on top of the airplane with co-axial cable routed to permit future connection to either receiver."

Paragraph 3.17.2.1.2 - CONTROLS:

Delete second sentence and substitute following:

"Wiring for SCS and DCS operation shall be provided in accordance with ARINC Specification 520A, Attachment II."

Page 98, Paragraph 3.17.2.3.5 - SERVICE INTERPHONE:

Revise paragraph to read as follows:

"A service interphone system shall be installed with jack boxes at the following stations: Nose Wheel Well

Each Engine Nacelle

Main Gear Well

External Ground Power Plug Fuselage Tail Cone Hydraulic Compartment Air Conditioning Compartment

Delta Air Lines, Inc. Change No. 48 29 May 1957 Page 3 of 5

Page 98, Paragraph 3.17.2.3.5 - SERVICE INTERPHONE: (Continued)
Handsets shall be installed at the following stations:

Both Buffet Areas Flight Deck, at aft end of pedestal

These handsets shall also be connected and used with the Public Address System (par. 3.17.2.3.7). A single stroke chime and call light shall be installed at the flight deck and each buffet area for use with these handsets, and shall be activated by momentary contact call switches labeled "Stewardess" and "Cockpit". A horn connected to a momentary call switch in the cockpit area shall be installed in the nose wheel well area. An additional momentary contact call switch and signal light shall be installed at each buffet area for inter-buffet signals: The chime and light installed at the flight deck also shall be activated from the nose wheel well, ground power plug, tail cone and main gear area. The interphone amplifier shall be installed in the radio rack. The service interphone system is on. As a guide, Convair Report No. 22-03400 shall be used to define the design and operating characteristics of the service interphone system."

Page 99, Paragraph 3.17.2.3.6 - SMOKE MASK MICROPHONE:
In fifth line, change "inboard" to "outboard".

Paragraph 3.17.2.3.7 - PUBLIC ADDRESS SYSTEM:

In sixth line, delete "neon type".

Page 100, add following new paragraph:

"Par. 3.17.2.4.1 - AIRBORNE SELECTIVE CALLING CONTROL: A SEL-CAL panel shall be installed in the radio control panel. Audio to the SEL-CAL unit shall be selected by the selector switches on the panel. An indicator light for each channel shall be installed on the panel. Audio from #1 and #2 H.F. and #1 and #2 VHF communications may be selected by either SEL-CAL Channel. A single chime shall be installed and connected to each SEL-CAL intermittant channel. Provisions for "Reset" shall be accomplished on the SEL-CAL panel."

Page 100, Paragraph 3.17.3.2 - MARKER BEACON RECEIVER:

Revise third sentence to read: "Control for the marker beacon shall be located in the ATC control panel."

Page 101, Paragraph 3.17.3.5 - DISTANCE MEASURING EQUIPMENT:

Change paragraph title to "DISTANCE MEASURING EQUIPMENT TACAN", and in second line change "DME" to "DMET".

Page 101, Paragraph 3.17.3.5.1 - INDICATORS:

Revise first sentence to read: "Space shall be provided on the pilot's and on the co-pilot's instrument panels for a 3-inch dual counter DMET indicator."

Paragraph 3.17.3.5.2 - ANTENNAS:

Delete paragraph and substitute following:

"Two DMET antennas shall be installed, one on top of fuselage and one on bottom of fuselage."

Page 102, Paragraph 3.17.4.1 - WEATHER PENETRATION AIRBORNE RADAR:

Fifth line, change "34" to "30".

Seventh line, change "anti-iced" to "deiced".

Paragraph 3.17.4.2 - TERRAIN WARNING TRANSCEIVER:

Delete paragraph.

Paragraph 3.17.4.3 - IDENTIFICATION RADAR:

Delete paragraph.

Paragraph 3.17.4.4.1 - CONTROL:

Delete paragraph and substitute following:

"One Dual ATC Transponder Beacon Control shall be installed in the radio control panel."

Delta Air Lines. Inc. Change No. 48 29 May 1957 Page 5 of 5

Figure 3.14.-1 - PILOT'S & CO-PILOT'S INSTRUMENT PANEL: Revise figure to reflect change in paragraph 3.17.3.5.1.

Figure 3.17-1 - PILOT'S & CO-PILOT'S PEDESTAL: Revise figure to reflect change in paragraph 3.17.3.2.

Figure 3.17-2 - PITOT STATIC SYSTEM SCHEMATIC: Renumber this figure and change location to Instrument Section of Specification.

Page A5 - APPENDIX I-C - ELECTRONIC EQUIPMENT:

Add following new item:

"DISTANCE MEASURING EQUIPMENT TACAN"

2 Antenna

Convair P/N to be supplied.

Page A5 - APPENDIX I-C - WEATHER RADAR: Fourth item, "Antenna", change "34" to "30", and change part number to "537F-3".

Page A6 - APPENDIX I-C - CONTROL PANELS:

Change "ATC Transponder Beacon Panel" to "Dual ATC Transponder Beacon/Marker. Mfr.: GABLES. P/N G-565."

Effect on Weight Empty: -0.2 lb Effect on Balance: +987 inch-lb Effect on Performance: None

A Division of General Lynamics Corporation San Dieso, California

SPEC III: ZD-22-00	3	_ DAVE:			
CUSTOMER: Delta Air Lines Inc.		MCI, 10,04	O Dtd	Revised	5-26-58
CHANGE NO: 47A		HODEL:((880) 22	-2	
TITLE: Deletion	of Access Door in	Aft Pressure I	Bulkhead		
ORIGIN: Delta req	uested at DELTA-C	CONVAIR Meeting	of 19 M	ay 1958.	
REASON FOR CHANGE:	To eliminate a p leakage.	ossible source	of cabin	n pressu	re
	EFFECT ON WEIG		EFFECT C	N BALANC	E *
Guar. Wt. Empty	Oper. Wt. Empt	У			
-6.0 lbs	-6.0 lbs		-8,184	Inch	I.b.
EFFECT ON GUARANTE	EFFECT ON GUARANTEED PERFORMANCE: * None				
* Negligible Changes Will be Accumulated and Totals Reflected in a Future Change Proposal					
Acceptance of this Change is Dependent Upon Prior Acceptance of the Following Changes:					
			Enginec	ring App	reval
LATEST DATE OF ACC	PTANCH:	AIRPLANES AFFE	CIND:	SAA-SAA-CARA-AAAAAAAAAAAAAAAAAAAAAAAAAAA	on the same of the
SPECIAL P. VITTORS:		DEFECT OF PRICE Tecurring Hon-Recurring Total:		MPLAMM:	
ACCLATED:		CONVER, A DIV	. of non	. Sym. C	· ? · .
BY:					
DAMA:					

Delta Air Lines Inc. Change No. 47A

CONVAIR: SD

Title: Deletion of Access Door in Aft Pressure Bulkhead.

Origin: Delta requested at DELTA-CONVAIR Meeting of 19 May 1958.

Reason for Change: To eliminate a possible source of cabin pressure

leakage.

Description of Change:

Page 80, Paragraph 3.16.11.2.1 DOOR OPEN WARNING INDICATORS:

Delete the last six words of the first sentence, and repunctuate sentence: "(and the aft bulkhead pressure door)".

Effect on Weight Empty: Effect on Balance: Effect on Performance: -6.0 pounds -8,184 inch-pounds

None

SPEC NO: ZD-22-003		DATE: 30 April 1957	
CUSTOMER: Delta Air	Lines, Inc.	MCL 10040 Dtd 19 April 1957	
CHANGE NO: 46		MODEL: (880) 22-2	
TITLE: Installe	tion of External Acces	ss Door in Tail Cone	
ORIGIN: TWA requirements of the contract	ested, Ref.: TWA Letter proposed for Delta	ter 880-98 of 11 March 1957, and	
REASON FOR CHANGE:	To improve access to	the tail cone area.	
	EFFECT ON WEIGHT *	EFFECT ON BALANCE *	
Guar. Wt. Empty	Oper. Wt. Empty		
+ 19.7 lb	+ 19.7 lb	+27,601 Inch Lb.	
EFFECT ON GUARANTE	ED PERFORMANCE: *	M =	
	None		
* Negligible Changes Will be Accumulated and Totals Reflected in a Future Change Proposal			
Acceptance of this Change is Dependent Upon Prior Acceptance of the Following Changes:			
		Engineering Approval	
LATEST DATE OF ACCEPTANCE: AIRPLANES AFFECTED:			
SPECIAL PROVISIONS	Recu Non-	CCT ON PRICE PER AIRPLANE: arring: Recurring	
ACCEPTED:	CON	VAIR, A Div. of Gen. Dyn. Corp.	
BY: DATE:		Chief of Contract Administration Commercial	

Installation of External Access Door in Tail Cone Title:

TWA requested, Ref.: TWA Letter 880-98 of 11 March 1957, and Origin: Contractor proposed for Delta

Reason for Change: To improve access to the tail cone area.

Description of Change:

Page 30 - Add new paragraph as follows:

TAIL CONE ACCESS DOOR: An access door, approximately 17.0" wide by 19.0", shall be installed on the bottom fuselage centerline aft of the rear pressure bulkhead for access into the unpressurised tail cone area for ground maintenance and inspection. 3.7.1.5.5

Effect on Weight Empty: +19.7 pounds Effect on Balance: +27,601 inch-pounds Effect on Performance:

None

Dal. Change Xo. 45

Concelled - retained for record Only.

see Other Julder for Current.

Chg. Xv. 45

10-1-56

SPEC NO: ZD-22-003		DATE: 18 April 1957		
CUSTOMER: Delta Air Lines, Inc.		MCL 10,014 Dtd 4 April 1957		
CHANGE NO: 44		MODEL: (880) 22-2		
TITLE: Convert fr C-10 Compa	om basic Sperry Chiss system.	b Compass to the Sperry complete		
Customer Initiated: Ref.: (1) Convair-Delta Minutes, dated 28 ORIGIN: December 1956, Page 4. (2) Convair-Delta Minutes, dated 16.17 January 1957. (3) Convair-Delta Telecon, 4 March 1957. (4) Ltr. REASON FOR CHANGE: J. Nycum-A.Savard, dated 3 April 1957. To comply with customer request.				
	EFFECT ON WEIGHT *	* EFFECT ON BALANCE *		
Guar. Wt. Empty + 1.5	Oper. Wt. Empty + 1.5	+ 324 Inch Lb.		
EFFECT ON GUARANTEED PERFORMANCE: * None				
* Negligible Changes Will be Accumulated and Totals Reflected in a Future Change Proposal Acceptance of this Change is Dependent Upon Prior Acceptance of the Following Changes: Engineering Approval				
LATEST DATE OF ACCEPT	ANCE: AIR	RPLANES AFFECTED:		
SPECIAL PROVISIONS:	Rec Non	FECT ON PRICE PER AIRPLANE: curring: n-Recurring tal:		
ACCEPTED:	CON	NVAIR, A Div. of Gen. Dyn. Corp.		
BY: DATE:		Chief of Contract Administration Commercial		

18 April 1957 Change No. 44

Convert from Basic Sperry C4b Compass to the Sperry Complete Title:

C-10 Compass System

Customer Initiated: Ref .: Origin:

> Convair-Delta Minutes, dated 28 December 1956, Page 4 Convair-Delta Minutes, dated 16, 17 January 1957 Convair-Delta Telecon of 4 March 1957 Letter J. Nycum-A. Savard, dated 3 April 1957 $\binom{1}{2}$

Reason for Change: To comply with Customer request.

Description of Change:

Page A8, Appendix 1-C

Change: "REMOTE COMPASS SYSTEM" Equipment List to read as follows:

Part or Quan. Spec. Number Manufacturer Read Description

REMOTE COMPASS SYSTEM

Sperry C-10 Compass System

Flux Valve

2 Compass Indicator

Compass Control

22 Directional Gyro

Rack Assembly

1 Power Supply 1 Servo Amplifier

1 Slaving Amplifier

Sperry C-6

Effect on Weight: Effect on Balance: Effect on Performance:

+1.5 +324 inch-1b

None

SPEC NO: ZD-22-003		DATE: 17 April 1957		
CUSTOMER: Delta Air Lines		MCL 10,031 Dtd 26 March 1957		
CHANGE NO: 43		MODEL: (880) 22-2		
TITLE: Passenger Oxygen Outlets - Change to Six Abreast				
ORIGIN: Customer requested - Ref.: TWA Ltr. 880-102, dated 20 March 1957 REASON FOR CHANGE: To provide oxygen outlet facilities for children in arms (tourist and mixed version seating).				
	FFECT ON WEIGHT *	EFFECT ON BALANCE *		
Guar. Wt. Empty On	+7.0	+5838 Inch Lb.		
EFFECT ON GUARANTEED PERFORMANCE: * None				
* Negligible Changes Will be Accumulated and Totals Reflected in a Future Change Proposal Acceptance of this Change is Dependent Upon Prior Acceptance of the Following Changes:				
		Engineering Approval		
LATEST DATE OF ACCEPTANCE: AIRPLANES AFFECTED:				
SPECIAL PROVISIONS:	Recu Non-	CCT ON PRICE PER AIRPLANE: Crring: Recurring al:		
ACCEPTED:	CON	VAIR, A Div. of Gen. Dyn. Corp.		
BY: DATE:		Chief of Contract Administration Commercial		

Passenger Oxygen Outlets - Change to Six Abreast Title:

Origin: Customer requested - Ref.: TWA Letter 880-102, dated 20

March 1957

Reason for Change: To provide oxygen outlet facilities for children in

arms (tourist and mixed version seating).

Description of Change:

Page 114, Paragraph 3.19.5.4 - INDIVIDUAL OUTLETS
Add to end of paragraph:

Provisions for one additional mask shall be made for each seat row (3 masks for each seat row on both sides of the airplane) to provide for emergency oxygen for children in arms.

Figure 3.19-14 - Revise to show additional oxygen outlets.

Effect on Weight: +5838 inch-1b Effect on Balance: Effect on Performance: None

SPEC NO: ZD-22-003		DATE: 15 April 1957
CUSTOMER: Delta Air	Lines. Inc.	MCL 10034 Dtd
CHANGE NO: 42		MODEL: (880) 22-2
TITLE: Main Lan	ding Gear, Heat Tre	at; Revision of
ORIGIN: Contract	or Initiated	
REASON FOR CHANGE:	For purpose of we	ight control.
	EFFECT ON WEIGHT	* EFFECT ON BALANCE *
Guar. Wt. Empty	Oper. Wt. Empty	
0	0	0 Inch Lb.
EFFECT ON GUARANTEE	D PERFORMANCE: *	
	None	
* Negligible Changes Will be Accumulated and Totals Reflected in a Future Change Proposal		
Acceptance of thi Prior Acceptance	s Change is Depende of the Following Ch	ent Upon nanges:
		Engineering Approval
LATEST DATE OF ACCE	PTANCE: A	IRPLANES AFFECTED:
SPECIAL PROVISIONS:	Re No	FFECT ON PRICE PER AIRPLANE: ecurring: on-Recurring otal:
ACCEPTED:	Co	ONVAIR, A Div. of Gen. Dyn. Corp.
BY: DATE:		Chief of Contract Administration Commercial

Title: Main Landing Gear, Heat Treat; Revision of

Origin: Contractor Initiated

Reason for Change: For purpose of weight control.

Description of Change:

Page 38, Paragraph 3.8.4.8 - MATERIAL PROPERTIES
Delete paragraph and substitute following:

The main landing gear shock strut outer cylinder and piston, and the wheel truck beam may be made from SAE 4340 steel, heat treated to 260,000 - 280,000 psi. The tensile properties of the steels used in all other gear components shall not exceed 240,000 psi (max) unless approved by Buyer.

Effect on Weight Empty: None Effect on Balance: None Effect on Performance: None

SPEC NO: ZD-22-003		DATE: 16 April 1957	
CUSTOMER: Delta Air Lines, Inc.		MCI, 10037 Dtd_	
CHANGE NO: 41		MODEL: (880) 22-2	
TITLE: Cargo Doors	s; Increase in Size	of	
ORIGIN: and Contrac	by Hughes Tool Compactor proposed for De	any in their Mock-up Comments,	
REASON FOR CHANGE:	To provide access	for entry of larger articles.	
	EFFECT ON WEIGHT	* EFFECT ON BALANCE *	
Guar. Wt. Empty	Oper. Wt. Empty		
-16.0	-16.0	-12,848 Inch Lb.	
EFFECT ON GUARANTEED PERFORMANCE: * None			
* Negligible Changes Will be Accumulated and Totals Reflected in a Future Change Proposal			
Acceptance of the Prior Acceptance	is Change is Depend of the Following C	ent Upon hanges:	
Change No. 40, dated 15 April 1957 Engineering Approval			
LATEST DATE OF ACC	EPTANCE: A	IRPLANES AFFECTED:	
Re No		FFECT ON PRICE PER AIRPLANE: con-Recurring otal:	
ACCEPTED:	C	ONVAIR, A Div. of Gen. Dyn. Corp.	
BY: BY		Chief of Contract Administration Commercial	

Title: Cargo Doors; Increase in Size of

Requested by Hughes Tool Company in their Mock-up comments Origin: and Contractor proposed for Delta.

Reason for Change: To provide access for entry of larger articles.

Description of Change:

Page 30, Paragraph 3.7.1.5.4 - Cargo Doors Change, in third sentence: 30 inches by 34 inches, to 39 inches by 34 inches.

Enclosure (A) Five (5) copies Contractor Proposal 1 - Increase Opening to Receive 27 x 32 x 89 Container.

Figure 1-2 - Inboard Profile and Plan View: Revise to show correct cargo area.

> Effect on Weight Empty: +16.0

Effect on Balance: +12,848 inch-1b

Effect on Performance: None Title: Cargo Doors; Increase in Size of

Origin: Requested by Hughes Tool Company in their Mock-up comments and Contractor proposed for Delta.

Reason for Change: To provide access for entry of larger articles.

Description of Change:

Page 30, Paragraph 3.7.1.5.4 - Cargo Doors
Change, in third sentence: 30 inches by 34 inches, to 39 inches
by 34 inches.

Enclosure (A) Five (5) copies Contractor Proposal 1 - Increase Opening to Receive 27 x 32 % 89 Container.

Figure 1-2 - Inboard Profile and Plan Views Revise to show correct cargo area.

> Effect on Weight Empty: +16.0 Effect on Balance: +12,848 inch-1b Effect on Performance: None

SPEC NO: ZD-22-003		DATE: 12 April 1957		
CUSTOMER: Delta Air	Lines Inc.	MCL 10,036 Dtd		
CHANGE NO: 40		MODEL: (880) 22-2		
TITLE: Delete one a	ft baggage compart	ment door, relocate remaining door.		
ORIGIN: Contractor Initiated REASON FOR CHANGE: To increase usable cargo volume and decrease weight.				
	EFFECT ON WEIGHT	T * _ EFFECT ON BALANCE *		
Guar. Wt. Empty	Oper. Wt. Empty			
-59.6	-59.6	-64,400 Inch Lb.		
EFFECT ON GUARANTE	ED PERFORMANCE: * Non-	16		
* Negligible Changes Will be Accumulated and Totals Reflected in a Future Change Proposal				
Acceptance of thi Prior Acceptance	is Change is Depend of the Following C	dent Upon Changes:		
		Engineering Approval		
LATEST DATE OF ACCE	PTANCE: A	AIRPLANES AFFECTED:		
SPECIAL PROVISIONS	N	EFFECT ON PRICE PER AIRPLANE: Recurring: Non-Recurring Total:		
ACCEPTED:	C	CONVAIR, A Div. of Gen. Dyn. Corp.		
BY: DATE:		BY: Chief of Contract Administration Commercial		

Title:

Delete One Aft Baggage Compartment Door, and Relocate

Remaining Door.

Origin:

Contractor Initiated.

Reason for Change: To increase usable cargo volume and decrease weight.

Description of Change:

Page 30. paragraph 3.7.1.5.4 - CARGO DOORS
Revise first two sentences to read as follows:

"Two inward opening doors shall be provided for access to the cargo areas below the floor. One door shall be provided for each cargo area. The doors shall be approximately centrally located, fore and aft with respect to the end bulkheads."

Figure 1-1 - General Arrangement Drawing:
Revise to show one centrally located compartment cargo door.

Figure 1-2 - Inboard Profile and Plan View Drawing: Revise to show correct cargo storage area.

Effect Weight Empty: Effect on Balance: Effect on Performance: -59.6 lb -64,400 inch-lb None

SPEC NO: ZD-22-00		DATE: 15 April 195	7
CUSTOMER: DELTA AIF	R LINES .	MCL 10,029 Dtd 28	Mar. 1957
CHANGE NO: 39		MODEL: (880) 22-2	
	ISION LIGHT - UPPER F		
ORIGIN: Requested and Contr	by TWA: Ref. TWA Lt.	r. 880-79, dated 12 F	ebruary 1957
REASON FOR CHANGE:	To relocate the upper tion on the fuselage tenance. Ref. R.F.C	that will permit acc	t to a posi- ess for main-
	EFFECT ON WEIGHT *	EFFECT ON 1	BALANCE *
Guar. Wt. Empty + 4.0	Oper. Wt. Empty	+3103	Inch Lb.
EFFECT ON GUARANTEED PERFORMANCE: * None			
* Negligible Changes Will be Accumulated and Totals Reflected in a Future Change Proposal Acceptance of this Change is Dependent Upon Prior Acceptance of the Following Changes: Engineering Approval			
LATEST DATE OF ACCEPTANCE: AIRPLANES AFFECTED:			
SPECIAL PROVISIONS:		EFFECT ON PRICE PER AIRPLANE: Recurring: Non-Recurring Total:	
ACCEPTED:	CON	VAIR, A Div. of Gen.	Dyn. Corp.
BY: DATE:		Chief of Contract Adm Commercial	inistration

Anti-Collision Lights - Upper Fuselage Installation Title:

Requested by TWA: Ref.: TWA Ltr. 880-79 dated 12 February Origin:

1957 and Contractor proposed for Delta.

To relocate the upper anti-collision light to a pesi-Reason for Change:

tion on the fuselage that will permit access for maintenance. Ref. R.F.C. 3.16.D4.

Description of Change:

Page 74, Paragraph 3.16.8.1.4 - ANTI-COLLISION LIGHTS Change paragraph to read as follows:

The airplane shall be equipped with two anti-collision lights; one providing light for the upper hemisphere and the other for the lower hemisphere. The upper light shall be accessible from within the passenger compartment. Drainage provisions shall be made to assure fluid drainage as a result of accumulation of condensed moisture or other fluids which may become trapped. The lower light location shall not be adjacent to any fuel or hydraulic fuel vent or drain line.

Exhibit to Change: (Not to appear in specification language)

The upper light shall be removed from the fin tip and installed at the CL of the fuselage at a point approximately opposite the lower light. The light shall be accessible from within the passenger cabin area through a door in a pressure tight housing. A removable panel in the interior trim will be provided. Wiring shall be changed as required.

Effect on Weight: Effect on Balance: Effect on Performance: Weight Empty: +4.0 + 3103 inch-1b. None

SPEC NO: ZD-22-003	DATE:
CUSTOMER: Delta Air Lines Inc.	MCL 10,069 Dtd 23 May 1957
CHANGE NO: 38A	MODEL: (880) 22-2
TITLE: Cabin Interior, Modification	of
ORIGIN: Purchase Agreement, dated 13 142 dated 11 March 1957, and REASON FOR CHANGE:	Exerter of Agreement No. 21 to September 1956, Delta Letter File Inderior Mock-Up of 11 June 1957. Ted cabin interior, and revision
EFTECT ON WARDS	
Guar. Wt. Empty per. Wt. Empty +173.3 lbs +173.3 lbs	+155,413 Inch I.b.
EFFECT ON GUARANTEED PERFORMANCE: * Non	le la
* Negligible Changes Will be Accumul Totals Reflected in a Future Change Acceptance of this Change is Deper Prior Acceptance of the Following	ge Proposal edent Upon
LATEST DATE OF ACCEPTANCE:	AIRPLANUS AFFECTED:
SPECIAL PROVISIONS:	EFFECT ON PRICE PER AIRPLANE: Recurring: Non-Recurring Total:
ACCEPTED:	CONVAIR, A Div. of Gen. Dyn. Corp.
BY: DATE:	BY: Chief of Contract Administration Commercial

Delta Air Lines Inc. Change No. 38A

Page 1 of 2

Title: Cabin Interior, Modification of

Origin: Customer Initiated, References: Letter of Agreement No. 21 to Purchase Agreement dated 13 September 1956, Delta Letter File 142 dated 11 March 1957 and Interior Mock-Up of 11 June 1957.

Reason for Change: To furnish Customer with desired cabin interior, and revision to CCP No. 38.

Description of Change:

Page 78, Paragraph 3.16 - ELECTRICAL SYSTEM:

Add following new paragraph under paragraph 3.16.8.6:

"3.16.8.7 SIDE WINDOW LIGHTING: Provisions shall be made at the cabin side windows for valance type fluroescent lighting, which shall include dimming features."

Page 107, Paragraph 3.19.2.3 - MISCELLANEOUS LAVATORY EQUIPMENT:

Change first item in equipment list to read:

"Three shatterproof mirrors (one mirror in forward lavatory and one each in aft lavatories).

Page 111, Paragraph 3.19.3.3 - TRIM:

Add following new sentence to end of paragraph:

"Carpeting shall be provided on side walls of cabin interior extending approximately 10 inches up the walls."

Page 111, Paragraph 3.19.3.5 - CURTAINS:

Change the first sentence to read as follows:

"All passenger compartment windows shall be provided with glare control."

Delete the last sentence which reads as follows:

"Window curtains, wherever practicable, shall be interchangeable."

Delta Air Lines Inc. Change No. 38A

Page 2 of 2

Page 111, Paragraph 3.19.3.6 - HAT RACKS:

Revise the paragraph to read as follows:

"Overhead hat racks shall be installed extending the full length of the passenger compartment except in the area of the stowage bins.
They shall be sufficiently rigid to support passengers walking in
the aisle in rough weather. The racks shall be designed for a stowage load of one pound per lineal inch and an additional load of 170 pounds applied at each third row of seats. Stowage bins, to break the continuity of the hat racks, shall be installed in four locations on each side of the aisle. A door, or doors, shall be provided for each bin."

Page Al2, APPENDIX I-C, FURNISHINGS:

Change 21st and 22nd items in Description List to read:

"AR Lavatory Water Tanks" From:

" 3 Lavatory Drain Tanks" To:

"3 Wash Basin Mirrors" From:

"3 Lavatory Mirrors (Shatterproof)" To:

Figure 3.19-2 - AFT WATER SYSTEM SCHEMATIC Figure 3.19-3 - LAVATORY TOILET WATER SCHEMATIC

Revise figures to show separate drain tank for each lavatory.

Effect on Weight Empty:

+173.3 pounds +155,413 inch-pounds Effect on Balance:

Effect on Performance: None

SPEC NO: ZD-22-003	DATE: 18 April 1957		
CUSTOMER: Delta Air Lines, Inc.	MCL 10,032 Dtd 22 March 1957		
CHANGE NO: 37	MODEL: (880) 22-2		
TITLE: Air Conditioning - Description	of Ground Connection Location		
ORIGIN: Customer Requested (TWA) Ref.:	Review of Mock-up, Page 20, Item 7, dated 12 March 1957		
REASON FOR CHANGE: Relocate to reduce and reduce weight			
2			
EFFACT ON WEIGHT	* EFFECT ON BALANCE *		
Guar. Wt. Empty Open Wt. Empty			
-26.0	-10,400 Inch Lb.		
EFFECT ON GUARANTEED PRIFORMANCE: * None			
* Negligible Changes Will be Accumulated and Totals Reflected in a Future Change Proposal Acceptance of this Change is Dependent Upon Prior Acceptance of the Following Changes:			
	Engineering Approval		
LATEST DATE OF ACCEPTANCE: A	IRPLANES AFFECTED:		
Re	FFECT ON PRICE PER AIRPLANE: ecurring: on-Recurring otal:		
ACCEPTED: C	ONVAIR, A Div. of Gen. Dyn. Corp.		
BY:	Y:		
DATE:	Chief of Contract Administration Commercial		

Title: Air Conditioning - Description of Ground Connection Relocation

Origin: Customer Requested (TWA) Ref.: Review of Mock-up, Page 20, Item 7, dated 12 March 1957

Reason for Change: Relocate to reduce time required during engine starts and reduce weight of system.

Description of Change:

Page 120. Paragraph 3.20.1.12

Change sentence starting on 6th line of paragraph to read:

A ground test connection shall be located on the R.H. side of fuselage near the front wing spar to permit ground pressure testing of the high pressure duct system

Figure 3.20-1 Air Conditioning schematic to be revised to reflect relocation of connection.

Effect on Weight: Effect on Balance: Effect on Performance: -26 -10,400 inch-1b

SPEC NO: ZD-22-003		DATE: 28 March 1957	
CUSTOMER: Delta Airlines		MCL 10,008 Dtd 11 Mar. 1957	
CHANGE NO: 36(A)		MODEL: (880) 22-2	
TITLE: Oxygen System - Gaseous, 1800 PSI - Change to:			
ORIGIN: Contractor	Initiated		
proposal for the in	Contractor wishes to estallation of a high the presently designat	pressure gaseous oxys	en supply
	EFFECT ON WEIGHT *	EFFECT ON	BALANCE *
Guar. Wt. Empty	Oper. Wt. Empty		× , z + l
+104.0	+104.0	+37,065	Inch Lb.
EFFECT ON GUARANTE	ED PERFORMANCE: *		
* Negligible Change Totals Reflected	es Will be Accumulated in a Future Change Pr	l and coposal	
Acceptance of the Prior Acceptance	is Change is Dependent of the Following Char	Upon nges:	
	4	Engineeri	ng Approval
LATEST DATE OF ACC	EPTANCE: AIRE	PLANES AFFECTED:	
SPECIAL PROVISIONS:		FECT ON PRICE PER AIRPLANE: curring: n-Recurring tal:	
ACCEPTED:		CONVAIR, A Div. of Gen. Dyn. Corp.	
BY:	BY:		
DATE:		Chief of Contract Administration Commercial	

28 March 1957 Change No.36(A)

TITLE: Oxygen System - Gaseous, 1800 PSI - Change to:

ORIGIN: Contractor Initiated:

REASON FOR CHANGE: COD

Contractor wishes to advise customer of an alternate proposal for the installation of a high pressure gaseous exygen supply system in lieu of the presently designated liquid exygen system.

DESCRIPTION OF CHANGE:

Page 113 Paragraph 3.1x9.5.1 General: Pirst sentence Change: "Liquid Oxygen Converter" Eo: "High Pressure Gas"

Paragraph 3.1.9.5.2 Components: Change to read as follows: "System components shall be comprised of regulators, valves, pressure gages, metering orifice valve, tubing, mask assemblies and three (3) oxygen cylinders. Complete previsions for the fourth cylinder shall be made.

Page A-18 Appendix I-C Oxygen Equipment

1 Build-up and vent valve

1 Oxygen Converter

1 Quantity Gage 1 Filler Valve

Add:

3 High Pressure Oxygen Cylinder (107 cu.ft each)

2 Pressure Gage 2 Pressure Reducer

2 Check Valve

1 Line Valve

Figure 3.1944 dtd 7-26-56
Revised 3-14-57 showing high pressure gaseous
Oxygen Supply System with a 3 bottle configuration and provisions for the fourth
bottle.


Effect on weight: +104.0 1b Effect on Balance: +37065 in.1b Effect on Performance: None A DIVISION OF GENERAL DYNAMICS CORPORATION SAN DIEGO

PAGE REPORT NO. MODEL DATE

SAECA" ZD-22-063 1.100 End in Com F16 3.194 PENSED

FILE OPPOSITE FIG 319-4 DATE 3-14-57

HP. DXYGEN CY211581 - (3)



C O M V A T R A Division of General Dynamics Corporation San Diego, California

SPEC NO: ZD-22-003	DATE:
CUSTOMER: Delta Air Lines Inc.	MCL 10070-B Dtd *4 October 1957
CHANGE NO: 35B	MODEL: (880) 22-2
TITLE: Buffets, Changes to	
ORIGIN: *Delta - Convair Buffet Meeting	gs of 1 August and 6 August 1957 of 1 October 1957
REASON FOR CHANGE: Customer requested.	
EFFECT ON WEIGHT	* EFFECT ON BALANCE *
Guar. Wt. Empty Oper. Wt. Empty	
Proposal 2 +256 lbs Proposal 2 +256 lbs	Proposal 2 +238,895Inch Lb.
EFFECT ON GUARANTEED PERFORMANCE: *	None
* Negligible Changes Will be Accumulate Totals Reflected in a Future Change	ed and Proposal
Acceptance of this Change is Dependent Prior Acceptance of the Following Change	ent Upon anges:
	Engineering Approval
LATEST DATE OF ACCEPTANCE: Al	RPLANES AFFECTED:
Re No	FFECT ON PRICE PER AIRPLANE: ecurring: on-Recurring otal:
ACCEPTED: CO	ONVAIR, A Div. of Gen. Dyn. Corp.
BY:	Chief of Contract Administration
DATE:	Commercial

Delta Air Lines Inc. Change No. 35B

Page 1 of 4

PROPOSAL No. 2

Page 105, Paragraph 3.19.2.1 - BUFFETS:

Revise second and third sentences to read as follows:

"Each of the buffets shall consist of two units as shown on Figures 3.19-5, 3.19-6 and 3.19-7. The units shall be identified as No. 1, No. 2, No. 3 and No. 4; units 2 and 3 shall be alike for interchangeability. No. 1 unit shall accommodate nine tray carriers. No. 4 unit shall be located forward of No. 3 unit on R.H. side forward of rear service door facing aft, and shall accommodate ten tray carriers.

Delete last sentence from paragraph "(The buffet insert sizes shall)", and substitute the following:

"Solid overhead type doors shall be installed over ovens and tray carriers of units 1, 2 and 3. Hinged side stowing doors shall be provided in No. 4 unit as follows: (a) one pair for each lower two levels on aft side. (b) a single door for each of the three inboard tray carriers and (c) a single door for the upper aft tray carrier. All doors shall be designed to utilize easily replaceable commercial material and to sustain a 3g ultimate load from loaded ovens or tray carriers. The overhead doors over the ovens and tray carriers shall be designed to serve as auxiliary serving counters. All loaded ovens and tray carriers shall be retained in position by 12g ultimate load self-locking latches. Counter tops, side and back splash to be one piece replaceable "Formica" or equivalent."

Page 106, Paragraph 3.19.2.1.2 - BUFFET EQUIPMENT:

Add to end of first sentence "as required".

Revise second sentence to read as follows:

"The equipment and arrangement shall be as shown on Figures 3.19-5, 3.19-6, 3.19-6A and 3.19-7."

Delta Air Lines Inc. Change No. 35B

Page 2 of 4

Delete equipment list and substitute the following:

		NO.	OF	ITEMS IN	BUFFET	UNIT
		No.	1	No. 2	No. 3	No. 4
	Tray Carrier (6-meal capacity)		9	0	0	10
	Food Warming Oven (12-meal capacity)		0	5	5	0
*	Non-Inflatable Escape Chute Stowage		0	1	1	0
	Coffee Maker		0	1	1	0
	Counter Top (Including Liquid Drain)		0	1	1	0
神	2-Gallon Liquid Container		1	2	2	2
	Filters(In addition to coffee maker	filter	0	1.	1.	0
*	Waste Container (Wet and Dry)		U	1	1	0
	Cold Water Outlet		0	1	1	0
	Water Cooler (1-qt capacity)		0	1	1	0
	Switch Panel		0	1	1	0
	Integral Counter Light		0	1	1	0
	Hot Cups		0	1	1	0
*	Drawers (4)		0	1	1	0
	Hinged Serving Counters		0	2	prov	0
	Miscellaneous Stowage	As	ava	llable		

* Incorporates 12g Load Carrying Doors

** Incorporates 3g Load Carrying Doors

Add to bottom of Paragraph 3.19.2.1.2, under above equipment list:

"Refer to APPENDIX I-B for description of equipment to be furnished and installed by Customer after delivery of aircraft. All other items to be Contractor furnished Contractor installed equipment."

Add the following new page to specification:

APPENDIX I-B

FURNISHINGS

Equipment to be Furnished and Installed by Customer after Delivery of Aircraft.

Description

Tray Carriers (R.E.F. Model 815) 2-Gallon Liquid Containers Food Warming Ovens Hot Cups

Mansfield Prod. Co. Mansfield Prod. Co. Helmco-Lacy

#180-115 #206-115 #STD-N-VT-115

Delta Air Lines Inc. Change No. 35B

Page 3 of 4

Page Al2, APPENDIX I-C, FURNISHINGS:

Change 24th item in Equipment List as follows:

From: 1 Buffet (4 units)

To: 2 Buffets (2 units each)

50450 Add: 2 Coffee Makers (115V AC) Nordskog Co.

Figure: 3.19-8 FWD BUFFET, View Looking Fwd.

Delete above figure from specification.

Figures: 1-2 INBOARD PROFILE AND PLAN VIEW (See Exhibit "A") 1-3 ALTERNATE SEATING ARRANGEMENT

Revise figures as required to reflect above changes.

Enclosures:

(A) Four (4) copies Figure 3.19-5 Revision C
(B) Four (4) copies Figure 3.19-6 Revision C
(C) Four (4) copies Figure 3.19-6A Revision A
(D) Four (4) copies Figure 3.19-7 Revision A, Alt. B

Replace present figures with Enclosures: (A), (B), (C) and (D).

Effect on Weight Empty: +256 pounds Effect on Balance: +238,895 inch-pounds

Effect on Ferformance: None

Page 4 of 4

The following not to appear in Specification language:

EXHIBIT "A"

I. Alternate "B" (Proposal No. 2)

Figure 1-2 - Inboard Profile and Plan View and Figure 1-3 - Alternate Seating Arrangement, will be revised in accordance with this Change No. 35B as follows:

- (a) Aft left hand buffet replaced with coat rack.
- (b) Aft right hand double seat, partition and stewardess seat replaced with 37-1/2" deep buffet.
- (c) Aft left hand double seat replaced with movable coat divider.
- (d) Center cabin movable coat rack divider replaced with standard seats.
- (e) Aft right hand stewardess seat relocated to inboard face of aft left hand coat rack in item (a) above.
- (f) Width of forward right hand buffet increased to Buttock Line 4.0.
- (g) Width of pilot's door reduced to 21" to accommodate item (f).
- (h) The R.H. passenger windows, everhead baggage rack including all passenger conveniences such as air, call button, oxygen outlets, etc., and seat attach points will be retained for the future reinstallation of the two standard passenger seats and/or removable coat room divider in the area between sta. 1224 and sta. 1261.5.
- II. light hand movable cost rack will be provided as loose equipment.
- III. Convair will use a total of 614 pounds for Customer food service in Convair useful load calculations.


CONVAIR

A DIVISION OF STREAM DYNAMICS COMPORATION SAN DIEGO

PAGE REPORT NO. MODEL -

DESTA






A STONATE COTTO AT AND OF TIME - 10

TARING FOR THIS SWITCH TIED BACK F STOWED IN #1 BUFFET

NOTE: ALL SWITCHES TO BE CROSS NUMBERED TO THEIR RESPECTIVE INSERT POSITIONS

SWITCH PANEL BUFFET #2\$3



ANALYSIS PREPARED BY CHECKED BY REVISED BY

C O'N V A I R
A DIVISION OF GENERAL DEVISION CORPORATION
SAN O COO

PAGE REPORT NO. MODEL D. A . L.

DATE TO S

39 TI--FWD TWO 2 GAL LIQUID STOWAGE TRATE MAN DIFFE (10) 1261.5 B.L. 13.0 STA. 1224.0 STA. 1261.5 PLAN VIEW EUFFET #4. FIG 3.19-7 FEV. A

ANALYSIS
PREPARED SY
CHECKED BY


CONVAIR

A DIVISION OF SENERAL DIVING & CORPORATION SAN DIEGO

REPORT NO.

MODEL DAL.

DATE 10 - 4-57



ANALYSIS
PREPARED SY
CHECKED SY
REVISED SY

CONVAIR

A STYIST OF GENERAL DYNAMICS CORPORATION

PAGE
REPORT NO.
MODEL DAL.

B.L.4.0 STOWAGE 2 GAL LIQUID TRAY CARRIERS (9) STOWAGE W.L. 59 BUFFET #1 VIEW LOOKING FWD. FIG. 3.19 - 5 REV.C

A Division of General Dynamics Corporation San Diego, California

SPEC NO: ZD-22-003		DATE:	9 May 1957
CUSTOMER: Delta Air	Lines, Inc.	MCL	Dtd
CHANGE NO: 34		MODEL:	(880) 22-2
TITLE: Flux Valve,	Wing Inspection Pl	ate - Relocat	ion of
ORIGIN: Contractor	Initiated		
REASON FOR CHANGE:	Inspection and ad practical from un access from upper	justment afte derside of wi wing surface	r installation is not ng, thus requiring
Con-	EFFECT ON WEIGHT		EFFECT ON BALANCE *
Guar. Wt. Empty	Oper. Wt. Empty		
None	None		None Inch Lb.
EFFECT ON GUARANTEE	D PERFORMANCE: *		
	No	ne	
* Negligible Change Totals Reflected	s Will be Accumula in a Future Change	ted and Proposal	
	s Change is Depend of the Following C		
			Engineering Approval
LATEST DATE OF ACCE	PTANCE: A	IRPLANES AFFE	CTED:
SPECIAL PROVISIONS:	R	lecurring: lon-Recurring_	E PER AIRPLANE:
ACCEPTED:	0	ONVAIR, A Div	of Gen. Dyn. Corp.
BY:	B	Y	
			ntract Administration

Title: Flux Valve, Wing Inspection Plate - Relocation of

Origin: Contractor Initiated

Inspection adjustment after installation is not practical from underside of wing, thus requiring Reason for Change;

access from upper wing surface.

Description of Change:

Page 61, Paragraph 3.14.3.4.1 - FLUX VALVE:

Change first sentence to read:

"Two flux valve units shall be installed in one wing tip area with an access door in the upper wing surface."

Effect on Weight Empty: Effect on Balance: None None Effect on Performance: None

A Division of General Dynamics Corporation San Diego, California

(1

SPEC NO: ZD-22-003	DATE:			
CUSTOMER: Delta Air Lines, Inc.	MCI, 10,068 Dtd 22 May 1957			
CHANGE NO: 33C	Model: (880) 22-2			
TITLE: Club Area, In lieu of Loung	e and Two Rose of Standard Seats			
(:IGIN: Contractor Initiated				
TO provide a 1 CCP No. 33.	2-place club area and revision to			
EFFECT ON WE				
Guar. Wt. Empty Oper. Wt. Emp				
+178.5 lbs +178.5 lbs	+81,418 Inch Lb.			
FFECT ON GUARANTEED PERFORMANCE: * None				
* Negligible Changes Will be Accum Totals Reflected in a Future Cha	nulated and nge Proposal			
Acceptance of this Charge is Dep Prior Acceptance of the Followin	ndent Upon g Changes:			
1 1 1 9	Engineering Approval			
LATEST DATE OF ACCEPTANCE.	AIRPLANES AFFECTED:			
SPECIAL PROXISIONS:	EFFECT ON PRICE PER AIRPLANE: Recurring: Non-Recurring			
	Total:			
ACCEPTED:	CONVAIR, A Div. of Gen. Dyn. Corp.			
BY:	BY:			
DATE:	Chief of Contract Administration Commercial			

* * *

Delta Air Lines Inc. Change No. 33C

Page 1 of 3

Title: Club Area, In Lieu of Lounge and Two Rows of Standard Seats

Origin: Contractor Initiated

Reason for Change: To provide a 12-place club area, and revision to CCP No. 33.

Description of Change:

Page v - INTRODUCTION:

In eighth line of first paragraph, change "80 to 108" to "84 to 107".

Page 1, Paragraph 1.1 - BASIC TYPE:

In fifth line of first paragraph, change "80" to "84", and in seventh line, change "108" to "107".

Page 12, Paragraph 3.1.2.2 - LOADING SUMMARY:

Under "Payload", change "(80 passengers plus 4 lounge)" to "(84 passengers including 12-place club area)".

Page 81, Paragraph 3.16.11. 4 - CALL SYSTEM:

Revise third sentence to read as follows:

"Call lights to indicate calls as follows: One from the club area (or forward passenger area) and one from the after passenter area, one from each lavatory, and one from the flight deck shall be installed and shall be visible from the passenger compartment and the cabin attendants' stations."

Page 83. Paragraph 3.16.11.4.1 - PASSENGER CALL SWITCHES:

Revise first sentence to read as follows:

"Call switches shall be installed; two for each row of seats within reach of passengers, one in each lavatory and six in the club area."

Page 103, Paragraph 3.19.1.1 - INTERIOR:

Revise first sentence to read:

"The interior shall include furnishings and equipment for 84 passengers, including 12 club area passengers, plus crew accommodations."

Page 104, Paragraph 3.19.1.1.5 - LOUNGE SEATS:

Delete paragraph title and first sentence and substitute following:

Delta Air Lines Inc. Change No. 33C

Page 2 of 3

"CLUB AREA SEATS: A 12-place club area shall be provided aft of the forward main entrance door, with seat assemblies arranged as follows:

(1)Left hand double seat facing aft (2)Right hand double seat facing aft

(3) Right hand double seat facing forward

Left hand quadruple seat assembly (5) Right hand double seat facing inboard

Page 104, Paragraph 3.19.1.1.6 - PASSENGER SEATS:

Change the words "lounge type", appearing in the third line, and "lounge" appearing in the ninth and eleventh lines, to "club area".

Page 105, Paragraph 3.19.1.1.8 - CONVERTIBILITY:

Revise paragraph to read as follows:

"The standard 84-passenger configuration (including 12-club area passengers) shall include full provisions to permit quick conversion to a full range of mixed class interiors utilizing the two coat compartments shown in Figure 1-3 as dividers. These coat compartments shall be designed to utilize the standard floor seat attach points and thus may be placed in any of the rows between rows six and fifteen inclusive, excluding emergency hatch areas, in the main cabin section. Each of the twenty-two seat rows shall incorporate standard cabin windows, and each row aft of the club area shall have reading lights and individual air outlets for five abreast seating as shown in the coach configuration in Figure 1-3. All rows shall permit the installation of standard seats or coach seats. Provisions shall be made for installation of a left and right hand hat rack in the club area for use with four and five abreast seating arrangements."

Page 109, Paragraph 3.19.2.8.8 - MAGAZINE RACKS:

Revise paragraph to read:

"Four magazine racks of the self cleaning type shall be installed; one in aft part of the forward entrance area, two in aft part of aft entrance area and one in the club area."

Page 110, Paragraph 3.19.3.1.1 - PASSENGER COMPARTMENT:

Revise first sentence to read:

"The passenger compartments provide seating accommodations for 84 passengers, including 12-club area passengers."

Add to last sentence: " except in the areas of lowered ceiling."

Delta Air Lines Inc. Change No. 33C

Page 3 of 3

Page A2, APPENDIX I-C - ELECTRICAL SYSTEM:

Under "Interior Lights", tenth item, "Fasten Seat Belts - No Smoking Sign"

Change: "2 Fasten Seat Belts - No Smoking Sign" to "4 Fasten Seat Bekts - No Smoking Sign"

Page Al2. APPENDIX I-C - FURNISHINGS:

Revise Description List as follows:

Fifth item, "Passenger Seats (Double) change: "40 Passenger Seats (Double)" to "36 Passenger Seats (Double)".

Sixth item, "Lounge Seats (Double)" change: "2 Lounge Seats (Double)" to "4 Club Area Seats (Double)"

Figure 1-2 - INBOARD PROFILE AND PLAN VIEW
Figure 1-3 - ALTERNATE SEATING ARRANGEMENT
Figure 3.7-1 - EMERGENCY EXIT FLOW
Figure 3.19-4 - HIGH PRESSURE OXYGEN GAS SYSTEM SCHEMATIC

Revise above figures as required to reflect change.

Enclosure: (A) One (1) copy of sketch of proposed Club Area Arrangement.


Effect on Weight Empty: Effect on Balance:

+178.5 pounds +81,418 inch-pounds

Effect on Performance: None

The following not to appear in Specification language:

"The effects of CCP No. 35B, Proposal No. 2, have been incorporated in this change."



12-PLACE CLUB AREA

A Division of General Dynamics Corporation San Diego, California

SPEC NO: ZD-22-003	DATE:
CUSTOMER: Delta Air Lines Inc.	MCL 10.030 Dtd 18 March 1957 MODEL: (880) 22-2
CHANGE NO: 32B	
TITLE: Engine Air Starter System,	Modification of
ORIGIN: Reference: Delta Letters 1977 and Telecon of 16 May Letter, File 142 dated 23 Ja	119 112 dated 1 February and 3 May 1997 (Mellinger to Dycum); Delta 1997 and Telecon of 17 August 1997 (Delta to Convair).
Customer request to incorp a ground line combustor for	orate provisions for utilization of starting engines No. 3 and No. 4.
EFFECT ON WEIGH	T * EFFECT ON BALANCE *
Guar. Wt. Empty Oper. Wt. Empty	
+52.0 16 +52.0 16	#37,915 Inch I.b.
EFFECT ON GUARANTEED PERFORMANCE: *	
* Negligible Changes Will be Accumul Totals Reflected in a Future Chang	
Acceptance of this Change is Deper Prior Acceptance of the Following	ndent Upon Changes:
	Engineering Approval
LATEST DATE OF ACCEPTANCE:	AIRPLANES AFFECTED:
SPECIAL PROVISIONS:	EFFECT ON PRICE PER AIRPHANE:
SPECIAL PROVIDENCE	Recurring: Non-Recurring Total:
ACCEPTED:	CONVAIR, A Div. of Gen. Dyn. Corp.
BY:	BY: Chief of Contract Administration Commercial
DATE:	

Delta Air Lines Inc. Change No. 32B

Page 1 of 2

Title: Engine Air Starter System, Modification of

Origin: Reference: Delta Letters, File 142 dated 1 February and 3 May 1957, and Telecon of 16 May 1957 (Mellinger to Nycum) Delta Letter, File 142 dated 23 July 1957 and Telecon of 17 August 1957 (Delta to Comvair).

Reason for Change: Customer request to incorporate provisions for utilization of a ground line combustor for starting engines No. 3 and No. 4.

Description of Change:

Page 44, add following new paragraph to bottom of the page:

"3.11.9 GROUND COMBUSTOR STARTER ACCESS: One access door each shall be installed in the No. 3 and No. 4 namelles with an electrical receptacle and duct connector installed inside each door for utilization of a ground line combustor for engine starting. The airplane nipple shall be capable of accepting a "Wiggins" 2-inch ground starter hose connector No. GSS155-32H."

Page 47, Paragraph 3.12.4.4 - STARTERS;

After third sentence, ending in fifth line, invert the following:

"In addition, provisions shall be made on No. 3 and No. 4 engines for utilisation of a ground line combustor for engine starting."

Page 57, Paragraph 3.12.12 - STARTING SYSTEM:

After first sentence, insert the following:

"Two additional control switches, to be emergised from an outside source, shall be provided to permit ground line combustor starting from the cockpit."

Delta Air Lines Inc. Change No. 32B

Page 2 of 2

Page A3, APPENDIC I-C - ELECTRICAL SYSTEM:

Add the following new items:

Quan.	Description	Mr.	Part or Spec. Number
2	Control Switches (I ground starter ed ment)	for juip-	
1	(For ground star equipment)	ter (7-pin conne	etor)

Figure 3.12-1 - ENGINE STARTING SYSTEM
Figure 3.20-1 - AIR CONDITIONING, ANTI-ICE SYSTEM SCHEMATIC

Revise figures as required to reflect above changes.

Effect on Weight Empty: +52.0 pounds Effect on Balance: +37,914 inch-pounds Effect on Performance: None

A Division of General Dynamics Corporation San Diego, California

SPEC NO: ZD-22-003	DATE: 7 June 1957				
CUSTOMER: Delta Air Lines Inc.	MCL 10046 Dtd 3 May 1957				
CHANGE NO: 31	MODEL: (880) 22-2				
TITLE: External Engine Carrying Pod, Provisions for Rejected					
ORIGIN: TWA Requested, Ref: TWA Letter and Contractor proposed for De REASON FOR CHANGE: To provide means for carrying	elta				
EFFECT ON WEIGHT	* EFFECT ON BALANCE *				
Guar. Wt. Empty Oper. Wt. Empty					
+75.0 lb +75.0 lb	+62,525 Inch Lb.				
EFFECT ON GUARANTEED PERFORMANCE: * i	None. For effects on performance tached page.				
* Negligible Changes Will be Accumula Totals Reflected in a Future Change	ted and Proposal				
Acceptance of this Change is Depend Prior Acceptance of the Following C					
	Engineering Approval				
LATEST DATE OF ACCEPTANCE: A	IRPLANES AFFECTED:				
R N	FFECT ON PRICE PER AIRPLANE: ecurring: on-Recurring otal:				
ACCEPTED: C	ONVAIR, A Div. of Gen. Dyn. Corp.				
BY:	Y:Chief of Contract Administration				

External Engine Carrying Pod, Provisions for Title:

TWA Requested and Contractor Proposed for Delta Origina

To provide means for carrying a spare engine Reason for Change: pod.

Description of Changes

Page 45, add the following new paragraph:

"3.12.2.1 EXTERNAL ENGINE CARRYING POD: Provisions shall be made for carrying a spare engine externally under the right wing between the inboard nacelle and fuselage, by means of a pod supported by a pylon bolted to the under surface of the wing. Support fittings, fasteners and reinforcement provisions shall be installed as required. The pod assembly, when installed, shall be included in the Alternate Useful Load: See Appendix III.

Enclosures (A) Three (3) copies Convair Dwg. SD-57-03037 - Spare Engine Transportation Pod CJ-805(GE) & (P & W) JT-3C-4 & JT-4A3, Model 22 Aircraft

Effect on Weight Empty: +75.0 lb Effect on Balance: Effect on Performances

462,525 inch-1b See attached page

APPENDIX III, EXTERNAL ENGINE CARRYING POD

Reference: Convair Drawing No. SD-57-03037 - Spare Engine Transportation Pod - CJ-805(GE) & (P& W) JT-3C-4 & JT-4A-3, Model 22 Airplane

- 1. POD AND PYLON:
- POD: An external spare engine carrying pod shall be provided and installed: The pod shall be fabricated of Fibreglas and be reinforced with Fibreglas rope and metal, and shall incorporate stowing provisions for all engine mount fittings required for engine models called out in Paragraph 1:2 of this Appendix. The center and tail come of pod shall be detachable by means of quick-acting latches. Fod shall be provided with forward and aft handles on each side to facilitate ground handling or stowage.
- PYLON: A pylon of box type beam structure with provisions for main engine mount pickup for engine Models CJ-805, JT-3C and JT-4A shall be furnished. The pylon shall be equipped with fittings and other attachments for securing pylon to the wing, and for assembly with the pod. Access doors as required shall be provided to permit attachment or detachment of the pylon.
- 2. ENGINE HOISTING:
- 2.1 ENGINE HOISTING PROVISIONS: Engine hoisting provisions shall be contained within the pylon, and shall consist of support brackets as required, hand-crank sheave with pawl and rachet, cables, fittings and tie down provisions.
- 3. PERFORMANCE CHARACTERISTICS: Will be submitted at a later date when data becomes available.
- 4. ARRODYNAMICS CHARACTERISTICS: Will be submitted at a later date when data becomes available.

A Division of General Dynamics Corporation San Diego, California

SPEC NO: ZD-22-00	3	DATE:		
CUSTOMER: Delta Ai	r Lines Inc.	10,222 9 April 1958 MCL10,078 Dtd 2 May 1958		
CHANGE NO: 30B		MODEL: (880) 22-2		
	Oxygen System, Revisi			
ORIGIN: Delta re represen	quested during meeting tatives on 23, 24 and	between Delta and Convair 25 April 1958.		
REASON FOR CHANGE:	Customer requested, a CCP No. 30A.	nd revision to CCP No. 30 and		
	EFFECT ON WEIGHT *	- EFFECT ON BALANCE *		
Guar. Wt. Empty	Oper. Wt. Empty			
0	-32.0 lbs	-29,310 Inch Lb.		
EFFECT ON GUARANTEE	ED PERFORMANCE: *			
	None			
* Negligible Changes Will be Accumulated and Totals Reflected in a Future Change Proposal				
Totals Reliected	in a rubate onange Fi	7,000.		
Acceptance of thi	s Change is Dependent of the Following Chang	Upon		
Acceptance of thi	s Change is Dependent	Upon		
Acceptance of thi	s Change is Dependent of the Following Chang	Upon es:		
Acceptance of thi Prior Acceptance LATEST DATE OF ACCE SPECIAL PROVISIONS: This CCP cancels an	s Change is Dependent of the Following Change PTANCE: AIRPI EFFECT Becur	Upon es: Engineering Approval ANES AFFECTED:		
Acceptance of thi Prior Acceptance LATEST DATE OF ACCE SPECIAL PROVISIONS:	s Change is Dependent of the Following Change Prance: AIRPI AIR	Upon es: Engineering Approval ANES AFFECTED:		
Acceptance of thi Prior Acceptance LATEST DATE OF ACCE SPECIAL PROVISIONS: This CCP cancels an supersedes CCP No. and CCP No. 30A. ACCEPTED:	s Change is Dependent of the Following Change Colly/	Upon es: Engineering Approval ANES AFFECTED: T ON PRICE PER AIRPLAIR: Pring: Becurring		
Acceptance of thi Prior Acceptance LATEST DATE OF ACCE SPECIAL PROVISIONS: This CCP cancels an supersedes CCP No. and CCP No. 30A.	s Change is Dependent of the Following Change Colly/	Upon es: Engineering Approval ANES AFFECTED: T ON PRICE PER AIRPLAIR: Ting: Securing		

Delta Air Lines Inc. Change No. 30B

Page 1 of 2

Title: Portable Oxygen System, Revision to

Delta requested during meeting between Delta and Convair representatives on 23, 24 and 25 April 1958. Origin:

Reason for Change: Customer requested, and revision to CCP No. 30 and

CCP No. 30A.

Description of Change:

Page 114, Paragraph 3.19.5.5 MASK:

Revise the last sentence to read as follows:

"Passenger masks shall be of the disposable type."

Page 114, Paragraph 3.19.5.6 PORTABLE BOTTLES:

Revise the paragraph to read as follows:

"One portable ll-cubic foot capacity, high pressure protective oxygen unit, including cylinder, full face mask and one pair of asbestos gloves, shall be provided in the flight station. Three 7-cubic foot capacity portable oxygen bottles, each with continuous flow regulators and two Scott "KS" continuous flow mask assemblies shall be provided in the passenger compartment. The bottles shall be located as follows: one in the forward left hand hatrack stowage bin, one in the left hand mid-cabin stowage bin and one in the aft left hand stowage bin."

Page A-15, APPENDIX I-C, OXYGEN SYSTEM:

Change the fifth item in the Description List as follows:

"2 Air-Pac - Portable (Crew Compartment)" From:

"1 Portable O2 Cylinder Assembly (11-cubic foot) (Crew Compartment) To: Scott 6080-3L"

Change the sixth item in the Description List as follows:

"3 Portable Op (310 liter)" From:

"3 Portable 02 Cylinder Assemblies, To 5500-1 AB" Scott (7-cubic foot) (Passenger Compartment) with Scott "KS" masks, Scott 8611 60-inch

hose and ARO 0674-Alo nipple.

Delta Air Lines Inc. Change No. 30B

Page 2 of 2

Page A-15, APPENDIX I-C, OXYGEN SYSTEM (Cont)

Delete the eighth item in the Description List as follows: "2 pr. Asbestos Gloves"

Effect on Weight Empty:

Effect on Fixed Useful Load:

Effect on Operating Weight Empty:

Effect on Performance:

Weight (lb)

O

-32.0

-29,310

-29,310

None

Val. Change no. 29-A

(Cancelled)

A Division of General Dynamics Corporation San Diego, California

SPEC NO: ZD-22-003		DATE: 26	June 19	1957
CUSTOMER: Delta Air	Lines Inc.	MCL_10.07	4 Dtd	7 June 1957
CHANGE NO: 28A		MODEL:((880) 22-	
TITLE: Integrally Provisions of	ighted Instruments	; Installat	ion or W	iring
ORIGIN: Reference:	C.C.P. No. 28 date TWK, Nycum to East	d 24 April	1957, and	i Delta
	Customer request f			
	EFFECT ON WEIGHT *		EFFECT OF	N BATANCE *
	Oper. Wt. Empty		Vince Vince	
Proposal 1, +12.5 b	oposal 1, +12.5 ib	Proposal	1, +3158	Inch Lb.
EFFECT ON GUARANTEED	PERFORMANCE: *			45
	Propose	11 1 - None		
* Negligible Changes Totals Reflected in	Will be Accumulate a Future Change P	d and roposal		
Acceptance of this Prior Acceptance of	Change is Dependent the Following Char	t Upon nges:	All March	
			Engineer	ing Approval
LATEST DATE OF ACCEPTA	ANCE: AIRI	PLANES AFFE	QTED:	
SPECIAL PROVISIONS:	Recu Non:	CCT ON PRICE Pring: Recurring		PLANE:
ACCEPTED:	CON	AIR, A Div.	of Gen.	Dyn. Corp.
BY:	BY:			
DATE:		hief of Oar	itract Ad Commercia	ministration 1
	A STATE OF THE STA		"大型"	

Delta Air Lines Inc. Change No. 28A 20 June 1957 Rev. 2 August 1957

Title: Integrally Lighted Instruments: Installation or Wiring Pro-

Origin: Reference: C.C.P. No. 28 dated 24 April 1957 and Delta TWX, Nyoum to Eastland, dated 22 May 1957

Reason for Change: Customer request for revision of C.C.P. No. 28
Description of Change:

- See attached: Enclosure: (A) Proposal No. 1 Installation of clamp mounted and integrally lighted instruments at all locations except Flight Engineer's Panel.
 - *(B) Proposal No. 2 Installation of clamp mounted Non-Lit instruments at all locations.
 - **(C) Proposal No. 3 Installation of wiring provisions only at all locations to permit Customer installation of integrally lighted instruments.
 - * Requirements for Proposal No. 2 cancelled after Convair investigations.
 - ** Deleted.

Weight Data:

Proposal No. 1 - Effect on Weight Empty: +12.5 pounds
Effect on Balance: +3158 inch-pounds
Effect on Performance: None

Proposal No. 2 -

Proposal No. 3 - Effect on Weight Empty: +8.0 pounds Effect on Balance: +2240 inch-pounds Effect on Performance: None

Delta Air Lines Inc. Change No. 28A 20 June 1957 Page 1 of 4 Rev. 2 Aug. 1957

Enclosure: (A) Proposal No. 1 - Installation of clamp mounted and integrally lighted instruments at all locations except Flight Engineer's Panel.

NOTE: *Item integrally lighted and clamp mounted.

Description of Change:

Page 58. Paragraph 3.14.1.1 - PILOT'S INSTRUMENTS:

Change paragraph title to "PILOT'S INSTRUMENT PANEL" and revise instrument list as follows:

* One indicator, airspeed, angle of attack * One indicator, compass (remote) Sperry C-6

* One clock

* One indicator, Mach. No. (Syn. Trans. Type)

* One altimeter (3-pointer type)

* One deviation indicator, Sperry R-1

* One indicator, rate of climb

One indicator, R.M.I.

One indicator, turn and slip

One tester, Autopilot Yaw Damper

* One gyro horizon (Sperry HZ-4)

One set marker beacon lights One essential buss failure indicator light

One airspeed system electrical fail warning light

One compass slaving switch

One KIFIS test switch

One master caution light

Delta Air Lines Inc. Change No. 28A 20 June 1957 Page 2 of 4 Rev. 2 Aug. 1957

Enclosure: (A) Proposal No. 1 (Continued)

NOTE: *Item integrally lighted and clamp mounted.

Page 58, Paragraph 3.14.1.2 - COPILOT!S INSTRUMENTS:

Change paragraph title to "COPILOT'S INSTRUMENT PANEL" and revise instrument list as follows:

* One indicator, airspeed, true

* One indicator, airspeed angle of attack

* One indicator, compass (remote) Sperry C-6

* One clock

* One indicator, Mach. No. (Syn. Trans. Type)

* One altimeter (3-pointer type)

* One deviation indicator, Sperry R-1

* One indicator, rate of climb

* One indicator, R.M.I.

* One indicator, turn and slip

* Two indicator, hydraulie pressure

* One gyro horizon (Sperry HZ-4)

One instrument power failure indicator light

One set marker beacon lights

One KIFIS test switch

One compass slaving switch

Delta Air Lines Inc. Change No. 28A 20 June 1957 Page 3 of 4 Rev. 2 June 1957

Enclosure: (A) Proposal No. 1 (Continued)

NOTE: *Item integrally lighted and clamp mounted.

Page 58. Paragraph 3.14.1.3 - ENGINE INSTRUMENTS:

Change paragraph title to: "ENGINE INSTRUMENT PANEL" and revise instrument list as follows:

* One indicator, master static air temperature

* Four indicator, exhaust temperature, Null Balancing Type

Four indicator, emains temperature, multiFour indicator, engine pressure ratio
Four indicator, fuel flow
One indicator, fuel quantity totalizer
One indicator, ram air temperature
One indicator, Autopilot, 3-Axis Trim
One indicator, flap position, dual
Four oil pressure low warning light
Four landing gear position indicator light One landing gear control handle One landing gear door indicator light Four in transit light - thrust reverse Four reverse thrust indicator light Four engine overheat light

CONVAIR:

Delta Air Lines Inc. Change No. 28A 20 June 1957 Page 4 of 4 Rev. 2 Aug. 1957

Enclosure: (A) Proposal No. 1 (Continued)

NOTE: *Item integrally lighted and clamp mounted.

Page 59. Paragraph 3.14.1.5 - MISCELLANEOUS INSTRUMENTS:

Delete: Eighth item in instrument list: "Required hydraulic pressure indicators"

"Two flap position Delete: Fourteenth item in instrument list: indicators".

Add: "One indicator, emergency air brake (in auxiliary side panel)".

Figure 3.14-1 - PILOT AND COPILOT INSTRUMENT PANEL
Figure 3.14-2 - PILOT AND COPILOT CONSOLE
Figure 3.14-4 - PILOT'S AND COPILOT'S OVERHEAD PANEL

Revise figures to reflect changes proposed by Enclosure (A) of this Change No. 28A.

Following not to appear in Specification language:

"APPENDIX I-C of Specification will be revised to be compatible with changes on Customer's acceptance of Proposal No. 1 of this Change No. 28A. Mammfacturer's name and/or part number, where not presently provided, will be furnished when available, with revisions to existing part numbers as applicable."

Delta Air Lines Inc. Change No. 28A 20 June 1957 Rev. 2 Aug. 1957

Exhibit to Change No. 28A

Manufacturers, and Part Numbers of Integrally Lighted Instruments:

QUAN. REQD	DESCRIPTION	MANUFACTURER	PART OR SPEC. NUMBER
71754413	Discourt Troy		CT COMPANY OF THE STATE OF THE
1	Indicator, Autopilot, 3-Axis	Sperry	1776004-1
2	Indicator, airspeed, angle of attack	Kollsman	A29297-10, plus
2	Indicator, compass (remote) Sperry C-6L	Sperry	range marks 1777213-620
2	Clock	Wakmann	W33-7530-10
2	Indicator, Mach. No. (Syn. Trans. Type)	Kollsman	A29247-10-001
** 2	Altimeter (3-pointer type)	Kollsman	A36410-00-001
	Deviation indicator Sperry R-1	Sperry	R-1L #1777211-621
5	Indicator, rate of climb	Pioneer	1653-6AB-A6-1
2	Indicator, R.M.I.	Pioneer	36126-1AF-25-A1
2	Indicator, turn and slip	Pioneer	3920-1AD-A1-1
1	Compage magnetic	U. S. Gauge	C-4B
1	Compass, magnetic Tester, Autopilot Yaw Damper	Sperry	1777967
1	Indicator sireneed, true	Kollsman	A29277-10-001
1	Indicator, airspeed, true Indicator, flap position, dual	G. E.	8DJ91LAB-1
222211112	Indicator, hydraulic pressure	U. S. Gange	SRL-07, plus
1	Indicator, master static air temperature	Kellsman	A29257-10-001
4	Indicator, exhaust temperature Null Balancing Type	Honeywell	*JG116A
4	Indicator, engine pressure ratio	Kollsman	29187-10-001
4	Indicator, tachometer	G. E.	8D-J81-LAB
4	Indicator, fuel flow	G. E.	8DJ971.AA1
\mathbf{I}	Indicator, fuel quantity	Part number to b	e supplied.
	totalizer		161BCL2
1	Indicator, ram air temperature	Levis	1776365-622
*** 2	Horizon, Remote Indicator	Sperry	TITOTON-OFF

^{*} Similar to part number shown except shall be integrally lighted. ** Includes A30397-10-001 indicator and B2604-00-001 for scale error

corrector. *** Added from CCP #24 (8.0. 880-2-25)

A Division of General Dynamics Corporation San Diego, California

SPEC NO: ZD-22-003	DATE: 4 April 1957			
CUSTOMER: Delta Air Lines	MCL 10,023 Dtd 31 Jan. 1957			
CHANGE NO:27	MODEL: (880) 22-2			
TITLE: Sperry Auto-Pilot - Install	ation of:			
ORIGIN: Customer Request: Reference REASON FOR CHANGE: Customer request Auto-Pilot, in lieu of the Bendix P.	e: DAL Ltr. 142, dtd. 25 Jan. 1957 ts a proposal for the Sperry SP-30 B-30 Auto-Pilot.			
EFFECT ON WEIG				
Guar. Wt. Empty Oper. Wt. Empt				
-7.0 -7.0	+1837 Inch Lb.			
EFFECT ON GUARANTEED PERFORMANCE: *				
* Negligible Changes Will be Accumu Totals Reflected in a Future Chan				
Acceptance of this Change is Depe Prior Acceptance of the Following				
	Engineering Approval			
LATEST DATE OF ACCEPTANCE:	AIRPLANES AFFECTED:			
SPECIAL PROVISIONS:	EFFECT ON PRICE PER AIRPLANE: Recurring: Non-Recurring Total:			
ACCEPTED:	CONVAIR, A Div. of Gen. Dyn. Corp.			
BY:DATE:	BY: Chief of Contract Administration Commercial			

Titles

Sperry Auto-Pilot - Installation of:

origin:

Customer Request - Reference: Delta Ltr. 142 dated 25 January 1957

Reason for Change:

Customer requests a proposal for the Sperry SP-30 Auto-Pilot, in lieu of the Bendix PB-20 Auto-Pilot.

Description of Changet

Page 42, paragraph 3.10.4, AUTOMATIC FLIGHT CONTROL:

Delete second sentence. In third sentences Change: "effect" to: "provide"

Page A-8, Appendix I-C, INSTRUMENTS & RELATED EQUIPMENT

Auto-Pilot Delete and Add the following:

1 Stabiliser Computer Consisting of:	1776002
3 Serve Amplifier 1 Safety Monitor 1 Trim Coupler 1 Stabilizer Computer Rack	619298-1 1775389 1775390 1776258
1 Flight Control Computer Consisting of:	1776003-03
1 Yaw Command Computer 1 Roll Command Computer 1 Pitch Command Computer 1 Radio Coupler 1 Pressure Computer 1 Interlock Rack	620134 1777339 17775381 17775388 17775882-4 1775392-03
1 Vertical Cyro 1 Gain Calibrator 4 Linear Accelerometer 2 Linear Accelerometer 2 Servo Drive 2 Servo Bracket	617926_1 1776710_01 615704_1 615764_2 615764_03 615144_01

4 April 1957 Change No. 27

Title:

Sperry Auto-Pilot - Installation of:

1	Rudder Actuator		
1	Yaw Damper		1777967
1	Auto Pilot	Controller	1777967 1776001
1		Indicator	177600
1	Trim Servo	Motor & Drive	1776004 669388
1	Trim Servo	Drum & Bracket	675011

Effect on Weights Effect on Balances Effect on Performances

Weight Empty -7.0 +1637

NONE

C O N V A I R A Division of General Dynamics Corporation San Diego, California

SPEC NO: ZD-22-003	DATE:
CUSTOMER: Delta Air Lines In	MCL 10.027 Dtd
CHANGE NO: 26A	MODEL: (880) 22-2
TITLE: Provisions for Ove	erwater Operation.
ORIGIN: Customer requested between Delta and REASON FOR CHANGE:	Reference: Meeting of 2 August 1957 Convair representatives.
To comply with CAL	R requirements for overwater operation.
the section because the section of t	ON WEIGHT * EFFECT ON BALANCE *
Guar. Wt. Empty Oper.	See attached sheet Inch Lb.
EFFECT ON GUARANTEED PERFOR	RMANCE: *
* Negligible Changes Will Notals Reflected in a Fu	oe Accumulated and ture Change Proposal
Acceptance of this Change Prior Acceptance of the I	e is Dependent Upon Following Changes:
	Engineering Approval
LATEST DATE OF ACCEPTANCE:	AIRPLANES AFFECTED:
SPECIAL PROVISIONS:	EFFECT ON PRICE PER AIRPLANE: Recurring: Non-Recurring Total:
ACCEPTED:	CONVAIR, A Div. of Gen. Dyn. Corp.
BY: DATE:	BY: Chief of Contract Administration Commercial

Delta Air Lines Inc. Change No. 26A

WEIGHT DATA

EFFECT ON WEIGHT	STANDARD VERSION	COACH VERSION
*Effect on Weight Empty: *Operating Weight Empty: Alternate Useful Load:	+111.0 lbs +111.0 lbs +814.0 lbs	+117.0 lbs +117.0 lbs +957.0 lbs
EFFECT ON BALANCE:	STANDARD VERSION	COACH VERSION
Weight Empty: Operating Weight Empty: Alternate Useful Load:	+ 82,891 in-lbs + 82,891 in-lbs +471,493 in-lbs	+ 87,966 in-lbs + 87,966 in-lbs +589,277 in-lbs

EFFECT ON PERFORMANCE: None

^{*} Alternate Useful Load not included in Operating Weight Empty.

Delta Air Lines Inc. Change No. 26A

Page 1 of 2

Title: Provisions for Overwater Operation

Origin: Customer requested, Reference: Meeting of 2 August 1957 between Delta and Convair representatives.

Reason for Change: To comply with CAR requirements for overwater operation.

Description of Change:

Page 78, Paragraph 3.16.8.5.1 - CONTROLS:

Delete paragraph and substitute the following:

13.16.8.5.1 INDEPENDENT LIGHT ASSEMBLIES: Seven independent light assemblies incorporating self-contained batteries shall be installed. Six shall be installed at the emergency exits and one on the flight dock. Lights shall be automatically energised during a crash landing or when airplane power is cut off. Lights may be switched off during normal shut down of airplane power, or switched on for manual operation or for test.

Page 90, Paragraph 3.17.1 - EQUIPMENT:

Add the following item to list under "Complete provisions for the following systems shall be made":

"Emergency Radio Transmitter"

Page 101, add the following new paragraph:

"3.17.3.5.3 EMERGENCY RADIO TRANSMITTER: Provisions shall be made for the stowage of one AN/CRT-3 umergency radio transmitter in the forward L.H. coat compartment. The emergency transmitter and stowage assembly, when installed shall be included in the Alternate Useful Load."

Page 104, Paragraph 3.19.1.1.6 - PASSENGER SEATS:

Delete the fourth sentence, starting in sixth line, and substitute the following:

"Stowage provisions for life preservers shall be made on underside of passenger seats. When life preserver provisions are not installed, a minimum space of 10 x 15 x 24 inches shall be provided under the seats, exclusive of lounge seats, for passenger package stowage. Life preservers, when installed shall be included in the Alternate Useful Load."

Delta Air Lines Inc. Change No. 26A

Page 2 of 2

Page 115, add the following new paragraph:

- "3.19.7 PROVISIONS FOR OVERWATER FLIGHT OPERATION:
 - 3.19.7.1 LIFE RAFTS: Provisions shall be made for stowage of four 25-man life rafts and one 20-man raft in the standard version; and four 25-man life rafts and two 20-man rafts in the coach version. The stowage provisions shall be located as follows:

One 25-man in forward L.H. coat compartment (Standard and Coach)

Two 25-man in forward R.H. Coat compartment

One 25-man in aft class divider, L.H. (Standard and Coach)

One 20-man in aft class divider, L.H. (Standard)
Two 20-man in aft class divider, L.H. (Coach)

Life raft lanyard fittings shall be installed, one each at the two forward exits and the two overwing exits. Life rafts and stowage strap assemblies, when installed, shall be included in the Alternate Useful Load."

Page A2, APPENDIX I-C, INTERIOR LIGHTS

Add the following new item to Description list:

"7 Independent Light Assemblies"

C O N V A I R A Division of General Dynamics Corporation San Diego, California

SPEC NO: ZD-22-003	DATE:
CUSTOMER: Delta Air Lines Inc.	MCL Dtd
CHANGE NO: 25	MODEL: (880) 22-2
TITLE: A-C Generators, Clarification	of
ORIGIN: Contractor initiated. REASON FOR CHANGE: Specification Admi	nistrative Change.
EFFECT ON WEIGHT	EFFECT ON BALANCE *
Guar. Wt. Empty Oper. Wt. Empty	
None None	None Inch Lb.
EFFECT ON GUARANTEED PERFORMANCE: * None	
* Negligible Changes Will be Accumulate Totals Reflected in a Future Change F Acceptance of this Change is Depender Prior Acceptance of the Following Cha	roposal nt Upon
LATEST DATE OF ACCEPTANCE: AIR	RPLANES AFFECTED:
Rec	PECT ON PRICE PER AIRPLANE: curring:Recurring tal:
ACCEPTED: COI	WVAIR, A Div. of Gen. Dyn. Corp.
BY:	Chief of Contract Administration

Delta Air Lines Inc. Change No. 25

Title: A-C Generators, Clarification of

Origin: Contractor initiated.

Reason for Change: Specification Administrative Change

Description of Change:

Page A3, APPENDIX I-C, ELECTRICAL EQUIPMENT:

Delete 11th item from Description Rist:

"4 Alternators - 30 KVA Approx. 115/200 v 3 Ø"

Change last item in Description List as follows:

From: * Generator - 30 KVA @ 76.0 lb 304.0 lb

To: 4 Generator, 40 KVA 6000 RPM @ 76.0 lb General Electric 304.0 lb

Effect on Weight Empty: None Effect on Balance: None Effect on Performance: None

A Division of General Dynamics Corporation San Diego, California

SPEC NO: ZD-22-003	DATE: 28 May 1957				
CUSTOMER: Delta Air Lines, Inc.	MCL 10,049 Dtd 3 May 1957				
CHANGE NO: 24	MODEL: (880) 22-2				
TITLE: Attitude Indicator System, C	hange of				
ORIGIN: Customer Requested, Ref.: Delta Letter 142, dated 25 January 1957 REASON FOR CHANGE: To specify instruments which are compatible with modified Compass System.					
EFFECT ON WEIGH	T * EFFECT ON BALANCE *				
Guar. Wt. Empty Oper. Wt. Empty					
+ 24.6 lb + 24.6 lb	+8,099 Inch Lb.				
EFFECT ON GUARANTEED PERFORMANCE: *	None				
* Negligible Changes Will be Accumul Totals Reflected in a Future Chang	ated and e Proposal				
Acceptance of this Change is Depen Prior Acceptance of the Following	dent Upon Changes:				
	Engineering Approval				
LATEST DATE OF ACCEPTANCE:	AIRPLANES AFFECTED:				
	EFFECT ON PRICE PER AIRPLANE: Recurring: Non-Recurring Total:				
ACCEPTED:	CONVAIR, A Div. of Gen. Dyn. Corp.				
BY:	BY:				
DATE: Chief of Contract Administration Commercial					

Title: Attitude Indicator System, Change of

Origin: Customer Requested, Ref: Delta Letter 142 dated 25 Jenuary 1957

Reason for Change: To specify instruments which are compatible with modified Compass System.

Description of Change:

Page 58, Paragraph 3.14.1.1 - PILOT'S INSTRUMENTS:

In instrument list, change "One gyro horisons (Sparry 4")" to read "One gyro horison remote indicator (Sperry HZ-4)"

Paragraph 3.14.1.2 - COPILOT'S INSTRUMENTS:

In instrument list, change "One gyro herizon (Sperry 4")" to read "One gyro herizon" remote indicator (Sperry HZ-4)"

Page A8, APPENDIX I-C - INSTRUMENTS AND RELATED EQUIPMENT:

Add following to bottom of page i

ATTITUDE INDICATOR SYSTEM:

1 Vertical Gyro Sperry #617926-1 4 Servo Amplifier Modules Sperry #618379 2 Gyro Horizon Remote Indicator Sperry HZ-4 #1776265

Effect on Weight Empty: +24.6 lb
Effect on Balance: +8099 inch-1b
Effect on Performance: None

C O N V A I R A Division of General Dynamics Corporation San Diego, California

SPEC NO: ZD-22-003		DATE: 8 May 1957		
CUSTOMER: Delta Air	Lines, Inc.	MCLDtd		
CHANGE NO: 23		MODEL: (880) 22-2		
TITLE: Shaver Outl	et, Change from 115	volts ac to 115 volts de		
ORIGIN: Contractor	Initiated			
REASON FOR CHANGE:	Administrative Type intent of specifics	e Change to correct and clarify		
	EFFECT ON WEIGHT	* EFFECT ON BALANCE *		
Guar. Wt. Empty	Oper. Wt. Empty			
None	None	None Inch Lb.		
EFFECT ON GUARANTEI	ED PERFORMANCE: * None			
Totals Reflected	es Will be Accumulation a Future Change Is Change is Dependent of the Following Change Chang	Proposal ent Upon		
		Fuglueering whilevar		
LATEST DATE OF ACCI	EPTANCE: Al	IRPLANES AFFECTED:		
SPECIAL PROVISIONS: EFFECT ON PRICE PER AIRPLANE: Recurring: Non-Recurring Total:				
ACCEPTED:	Co	ONVAIR, A Div. of Gen. Dyn. Corp.		
BY: Chief of Contract Administration Commercial				

Title: Shaver Outlet, Change from 115 volt ac to 115 volt de

Origin: Contractor Initiated

Reason for Change: Administrative Type Change to correct and clarify intent of specification.

Description of Change:

Page 79, Paragraph 3.16.10.3 - SHAVER OUTLETS:

Third line, after volts, change ac to dc.

Effect on Weight Empty: None Effect on Balance: None Effect on Performance: None

A Division of General Dynamics Corporation San Diego, California

SPEC NO: ZD-22-003	DATE			
CUSTOMER: Delta Air Lines Inc.	MCL 10.094 Dtd 21 June 1957			
CHANGE NO: 22A MODEL: (880) 22-2				
TITLE: Water System, Pressur	ized, Single 50-gallon Tank, Change to			
ORIGIN: Contractor initiated. REASON FOR CHANGE: To improve system efficiency; and revision to CCP No. 22.				
EFFECT ON	WEIGHT * EFFECT ON BALANCE *			
Guar. Wt. Empty Oper. Wt17.0 lb -17.0 lb	-28 691 Inch lib.			
EFFECT ON GUARANTEED PERFORMANC	CE: * None			
Totals Reflected in a ruture	* Negligible Changes Will be Accumulated and Totals Reflected in a Future Change Proposal Acceptance of this Change is Dependent Upon Prior Acceptance of the Following Changes: Engineering Approval			
LATEST DATE OF ACCEPTANCE: AIRPLANES AFFECTED:				
SPECIAL PROVISIONS: EFFECT ON PRICE PER AIRPLANE: Recurring: Non-Recurring Total:				
ACCEPTED:	CONVAIR, A Div. of Gen. Dyn. Corp.			
BY:BY:Chief of Contract Administration Commercial				

Delta Air Lines Inc. Change No. 22A

Page 1 of 2

Title: Water System, Pressurized, Single 50-gallon Tank, Change to

Origin: Contractor initiated.

Reason for Change: To improve system efficiency; and revision to CCP

No. 22.

Description of Change:

Page 59, Paragraph 3.14.1.4 - FLIGHT ENGINEER'S INSTRUMENTS:

Add the following to the instrument list:

"One Low water pressure warning light

One Water pump switch"

Page 106, Paragraph 3.19.2.1.2 - BUFFET EQUIPMENT:

Add to the bottom of the equipment list:

"Water filters"

Page 106, Paragraph 3.19.2.1.4 - WATER SYSTEM:

Delete paragraph and substitute the following:

"A pressurized potable water system shall be provided to supply the lavatory wash basins and buffets. Filters will be provided in buffets which have coffee makers or drinking water outlets. The system shall provide for draining on the ground. The tank capacity shall be 50 gallons of water with an adequate air space to act as a pressure reservoir. Means for filling on the ground at a rate of at least 10 gpm shall be provided. An overflow pipe from the tank shall visually indicate at the ground service connection when the tank is full. The system shall be located and designed to prevent freezing in flight. An air pump shall be provided. The pump assembly shall be rated for continuous duty operation.

The supply tank shall be designed to ensure that the last remaining 10 gallons in the tank will supply only the buffets.

Suitable controls shall be located on the flight engineer's panel for operation of the water system. These controls shall consist of the following:

1. Low pressure warning light

2. Pump switch"

Delta Air Lines Inc. Change No. 22A

Page 2 of 2

Page Al2, APPENDIX I-C, FURNISHINGS:

Change 21st item in Description List as follows:

From: AR Lavatory Water Tanks

To: 1 Potable Water Tank (50-gallon capacity, pressurized)

Add the following to bottom of the Description List:

" 1 Water System Pump AR Buffet Water Filters"

3.14-3 - FLIGHT ENGINEER'S PANEL 3.19-2 - WATER SYSTEM SCHEMATIC Figures:

Revise figures as required to reflect above changes.

Effect on Weight Empty: -17.0 pounds Effect on Balance: -28,631 inch-pounds

Effect on Performance: None

C O N V A I R A Division of General Dynamics Corporation San Diego, California

SPEC NO: ZD-22-003		DATE: 1 July 1957
CUSTOMER: Delta Air		MCI 10.087 Dtd 5 July 1957
CHANGE NO: 21A*		MODEL: (880) 22-2
TO BE THE WAY OF THE PARTY OF T	em, Change from Pre	ssure System to Electric Pump
REASON FOR CHANGE:		and reliability of the fuel system. natates "and tank filler openings".
	EFFECT ON WEIGHT	* EFFECT ON BALANCE *
Guar. Wt. Empty	Oper. Wt. Empty	o Inch Lb.
Asserbance of the		ent Üpon
LATEST DATE OF ACCI	eptance:	AIRPLANES AFFECTED:
SPECIAL PROVISIONS		EFFECT ON PRICE PER AIRPLANE: Recurring: Yon-Recurring Total:
ACCEPTED:		CONVAIR, A Div. of Gen. Dyn. Corp.
BY:		BY: Chief of Contract Administration Commercial

Revised 29 August 1957 Delta Air Lines Inc. Change No. 21A 1 July 1957 Page 1 of 6

Fuel System Change from Pressure System to Electric Pump Title:

System

Contractor Initiated Origin:

To improve safety and reliability of the fuel Reason for Change:

system.

Description of Change:

Page 48, Paragraph 3.12.9.1 - DESCRIPTION:

Insert the following between first and second sentences;

"The wing shall incorporate four fuel tank systems of integral construction; each tank system being divided into two parts consisting of a main and a replenishing system."

Page 49, Paragraph 3.12.9.1.1 - OPERATING LIMITS:

Delete fourth, fifth and sixth sentences starting in the minth line.

In sixth line, insert "initial" between "with" and "guel".

In seventh line, add "+" before "130°F".

Page 49, Paragraph 3.12.9.2 - PUMPSt

Change paragraph title to "BOOST PUMPS".

Revise first sentence to read: "Each main fuel tank shall be equipped with two ac electrically powered boost pumps."

Change second sentence to read:

"Each fuel supply system to the engine shall be so arranged that failure of either boost pump shall not result in an interruption of thrust throughout all normal flight altitudes."

Delete For transfer in eighth line.

Change sixth sentence starting in thirteenth line, to read:

"Each pump and its control relay shall receive power from the same source."

Delete eighth sentence, starting on the fifteenth line.

Page 49, Paragraph 3.12.9.2.1 - ENGINE-DRIVEN FUEL PUMPS:
Change paragraph number to "3.12.9.2.2".

Add new paragraph as follows:

"3.12.9.2.1 - TRANSFER PUMPS: Transfer pumps shall be located, as shown in Figure 3.12-2, in each main tank to supply the boost pump baffle areas, and in each inboard replenishing compartment to supply the corresponding main compartments. Check valves shall also be provided to hypass all transfer pumps to permit flow by gravity from the replenishing area into the main tank area and also from the main tank into the baffle areas. Separate circuit breakers shall be provided for each pump. Each pump and its control relay shall receive power from the same source."

Paragraph 3.12.9.3 - TANKS:

In first line, insert "compartmented" between "integral" and "fuel".

In third line, change "3 percent" to "2 percent".

Page 50, Paragraph 3.12.9.3.1 - CROSS-FRED SYSTEM:

Change last sentence to read: "The indicator lights shall be off when the valves are fully open or fully closed."

Paragraph 3.12.9.5.1 - VENT SYSTEM OPERATING LIMITS?

In first sentence, change limits to read "+3.6 psi maximum and -2.0 psi minimum."

In third sentence, add the word "initial" after "+1300F."

Page 51, Paragraph 3.12.9.7.2 - LINE SHUTOFF VALVES:

Revise first sentence to read: "A shutoff valve shall be installed for each of the four tanks."

Add following to paragraph:

"The valves shall incorporate provisions to electrically indicate in-transit positions. The indicator lights shall be off when the valves are fully open or fully closed."

Revised 29 August 1957 Delta Air Lines Inc. Change No. 21A 1 July 1957 Page 3 of 6

Page 51. Paragraph 3.12.9.7.3 - EMERGENCY SHUTOFF VALVES:

Revise first sentence to read:

"An emergency fuel shutoff valve for each engine supply system shall be mounted above and adjacent to the horizontal firewall."

Add following to paragraph:

"The valves shall incorporate provisions to electrically indicate when the valves are closed. The indicator lights shall be on when the valves are fully closed."

Page 52, Paragraph 3.12.9.8 - STRAINERS:

Delete last sentence and substitute following:

"An 8-10 mesh screen shall be installed at each fuel pump inlet."

Paragraph 3.12.9.9.1 - QUANTITY GAGES:

Revise fourth sentence, starting in eighth line, to read:

"One measurement system shall be provided for each fuel tank system with provisions to gage either main or total quantities."

Page 53. Paragraph 3.12.9.9.5 - FUEL SYSTEM WARNING DEVICES:

Delete third, fourth and fifth sentences:

Paragraph 3.12.9.10 - DRAINAGE PROVISIONS:

Change title to "FUEL JETTISON PROVISIONS".

Page 53, Paragraph 3.12.9.10.1 - TANK DRAIN:

Change title to "DESCRIPTION" and add the following:

the pilot's comparament. Each main tank shall be equipped with a hydraulic motor driven jettisen pump. Stand pipes shall be installed in each main tank to allow jettisening fuel down to maximum landing weight. Provisions shall be provided in each inboard main tank to jettisen all inboard fuel by means of a separate control.

Paragraph 3.12.9.10.2 - FUEL DUMP VALVES:

Delete paragraph number and title.

Revised 29 August 1957 Delta Air Lines Inc. Change No. 21A 1 July 1957 Page 4 of 6

Page 53; Paragraph 3.12.9.12 - FUEL EVAPORATION CONTROL:

Delete paragraph (35 lines).

Change paragraph 3.12.9.9.6 to read "3.12.9.12 - FUEL TEMPERATURE INDICATION".

Page 55, Paragraph 3:12.9.13.1 - UNDER-WING REFUELING:

Add the word "system" to end of first sentence and repunctuate.

Change seventh sentence, starting on eleventh line, to read:

The adapters shall be in accordance with MIL-A-7898, Type A-5 or an adaptation of this type."

Paragraph 3.12.9.13.2 - EMERGENCY REFUELING:

In first line, change "3-1/2 inches" to "3 inches".

Add the word "system" to end of first sentence, and repunctuate.

In fourth line, change "200 gpm" to "150 gpm".

Add the following sentence to end of paragraph;

"Suitable means shall be provided for connecting a ground wire from the refueling truck."

Paragraph 3.12.9.13.3 - REFUELING CONTROLS:

Revise first and second sentences to read as follows:

"A refueling panel shall be located in the aft section on the outboard side of each imboard pylem. The panels shall contain fuel quantity gages, pre-set quantity selectors, pre-check shutoff controls and jacks for microphone, headset and bandset."

Page 56, Paragraph 3.12.11.2 - GENERAL CONTROLS:

Change last item in controls list from "Fuel dump controls" to

Page 59, Paragraph 3:14.1.4 - FLIGHT ENGINEER'S INSTRUMENTS:

Change quantity of third item in instrument list from "Four" to

Change fourth item to read: "Eight fuel transfer pump pressure warning lights".

Revised 29 August 1957 Delta Air Lines Inc. Change No. 21A 1 July 1957 Page 5 of 6

Page 59, Paragraph 3.14.1.4 (Continued) "Four engine fuel pressure loss indi-Change fifth item to read: eater lights".

Page 64, Paragraph 3.15.3.1 - DESCRIPTION AND COMPONENTS:

Revise second sentence to read:

"The low pressure pneumatic system shall provide wing antiicing."

Delete last part of second sentence "and fuel system pressurisation". Delete third sentence starting on fourth line.

Page 84. Paragraph 3.16.17 - ESSENTIAL POWER. AC POWER:

Under heading "Fuel and Oil" add following new item:

"2. Fuel Transfer Pumps (6 of 8)9.

Page 86; Paragraph 3.16.17 - ESSENTIAL POWER, DC POWER:

Under heading "Fuel and Oil", revise list to read as follows:

ni. Fuel Shutoff

2. Engine Pump Warning Lights
3. Boost Pump Pressure Warning Lights
4. Transfer Pump Warning Lights

Bransfer Pump Warning Lights Oil Level Warning Lights

Page B-3, Appendix I-D, COMPONENT REMOVAL AND REPLACEMENT TIME:

Delete following items from list:

Fourteenth Stem: "Feul Pressurizing Valve"
Nineteenth Stem: "Fuel Tank Pressure Regulator" Thirty-four item: "Bleed Air heat Exchanger".

Revise following Figures to reflect above changes:

Figures: 3.12-1 Engine Starting System
3.12-2 Schematic, Engine Fuel Supply Subsystem
3.12-4 Schematic, Fuel Jettison, Subsystem.

3.12-5 Schematic, Refuel-Defuel Subsystem 3.12-3 Schematic, Fuel Tank Vent Subsystem

-3.12-7 Fuel Jettison Subsystem. Delete:

Revised 29 August 1957 Delta Air Lines Inc. Change No. 21A 1 July 1957 Page 6 of 6

Enclosure: (A) Four (4) copies Figure 3.12-1
(B) Four (4) copies Figure 3.12-2
(C) Four (4) copies Figure 3.12-3
(D) Four (4) copies Figure 3.12-4
(E) Four (4) copies Figure 3.12-5

Effect on Weight Empty: O Effect on Balance: O Effect on Performance: O

CONVAIR

A DIVISION OF GENERAL DYNAMICS CORPORATION SAN DIEGD, CALIFORNIA

SPEC NO.: ZD- 22-003	The second secon	DATE			
CUSTOMER: Delta Air	lines, Inc.	MCL		DTD	
CHANGE NO: 19J		MODEL	22-2	(Convair	"880")
TITLE: Manufac	turer's Name and/	or Part Num	per		
ORIGIN: Custome Convair	r approved specifior Buyer furnish	ic designat ed equipmen	ions for	r items of	
REASON FOR CHANGE:	To identify equiple I-A or Appendix		listed	in Append	iix
	A Bridge of the second				
EFFECT (ON WEIGHT *		EFFE	CT ON BALAN	CE *
GUAR, WT. EMPTY	OPER. WT. EMPTY				
0	0			0	INCH LB.
EFFECT ON GUARANTEED F	PERFORMANCE: * Non	е			
* NEGLIGIBLE CHANGES WILL TOTALS REFLECTED IN, A ACCEPTANCE OF THIS CH PRIOR ACCEPTANCE OF T	FUTURE CHANGE PROPO IANGE IS DEPENDENT UPO	SAL		NGINEERING	APPROVAL
				NGINEERING	APPROVAL
LATEST DATE OF ACCEPTA	ANCE:	AIRPLANES AF	FECTED:		
SPECIAL PROVISIONS:		EFFECT ON PERECURRING: NON-RECURRING TOTAL:	IG:		
ACCEPTED: BY:		CONVAIR, A DIV	ISION OF GE	ENERAL DYNAM	ICS CORP.

Page 1 of 6

Title: Manufacturer's Name and/or Part Number

Origin: Customer approved specific designations for items of Convair or Buyer furnished equipment.

Reason for Change: To identify equipment items listed in Appendix I-A or Appendix I-C.

Appendix I-A and Appendix I-C: Change or add manufacturer's name and/ or part number to item so as to read as follows:

Page No.	Quan Reqd	Description	Manufacturer	Part or Sp Number	
A-0	E	LECTRONIC EQUIPMENT			
From:	2	ATC Transponder Beacon	Wilcox	714B	47.6
To:	##2 ##2	ATC Transponder Beacon ATC Transponder Beacon	Wilcox Wilcox	714B 714C	47.6 47.6

Add the following to bottom of page:

#Effective Ships 1 through 13. ##Effective Ships 14 and on.

A-1	Ī	FUEL SYSTEM EQUIPMENT		
From:	8	Booster Pump Housing • Assembly	Thompson Prod.	TB-141100-4 TB-139900-2 TB-139100
To:	16	Booster Pump Housing Assembly	Thompson Prod.	TB-141100-4 TB-139900-2 TB-139100
A-2	Ī	EXTERIOR LIGHTS		
From:	1	Light, Tail Position Light, Anti-Collision,	Grimes	B7890-5
		Upper	Grimes	d9775-21-7079
To:	*1 **1 *1	Light, Tail Position Light, Tail Position Light, Anti-Collision,	Grimes Grimes	B7890-5 B7890-7
	**1	Upper Light, Anti-Collision,	Grimes	d9775-21-7079
	-	Upper	Grimes	09775-3-7079

GENERAL DYNAMICS/CONVAIR

Delta Airlines, Inc. Change No. 19J

Page 2 of 6

				A STATE OF THE STA
Page No.	Quan Reqd	Description	Manufacturer	Part or Spec. Number
A-4	<u>v</u>	HF NAVIGATION SYSTEM		
Add th	he fol	lowing item:		
	2	VOR/LOC Instrument Unit	Collins	T344B-1 522-0887-025
A-5	1	NTERPHONE SYSTEM (SERVICE)		
From:	3	Handsets	Remler	A-255/W75675-2
To:	ø3 øø3	Handsets Handsets	Remler Remler	A-255/W75675-2 A-255AD
A-7A	_	NSTRUMENTS AND RELATED EQU	JIPMENT	
From:	1	Indicator, Air Flow Cabin Compressor-Dual	Ham. Standard	537325
To:	ø1 øø1	Indicator, Airflow Cabin Compressor-Dual Indicator, Airflow Cabin Compressor-Dual	Ham. Standard Ham. Standard Weston	537325 537325 or 185249
A-9	E	LIGHT INSTRUMENTS		
From:	2	Indicator, Mach No. Synchrotel Transmit-		
	1	ter-Type Transmitter, Angle-of-	Kollsman	A-29274-10-006
		Attack	Kollsman	68-40800-0402
To:	2	Indicator, Mach No. Synchrotel Transmit-		
	1	ter Type Transmitter, Angle- of-	Kollsman	A-29247-10-006
	1	Attack	Kollsman	68-40800-0505
A-10	<u>F</u>	IYDRAULIC EQUIPMENT		
From:	2	Hydraulic Fluid Level Trans.	Simmonds	391035-01406
	2	Hydraulic Fluid Level Trans.	Simmonds	391035-02580
	**1	Nose Gear Steering Cyl- inder and Valve	Cleveland	J910J7-02J00
		Assembly	Pneumatic	9818B

Delta Airlines, Inc. Change No. 19J

Page 3 of 6

Page Quan No. Reqd	Description	Manufacturer	Part or Spec. Number
A-10 <u>H</u>	YDRAULIC EQUIPMENT (Cont)	
To: 1	Hydraulic Fluid Level Trans.	Simmonds	391035-01406
1 **1	Hydraulic Fluid Level Frans.	Simmonds	391035-02580
**1	Nose Gear Steering Cyl- inder and Valve Assembly	Cleveland Pneumatic	9818c
A-10A H	YDRAULIC EQUIPMENT		
From: 4	Main Landing Gear Door Cyl (Aft)	Thompson	к-51894
To: #4	Main Landing Gear Door Cyl. (Aft)	Thompson	к-51894
**4	Main Landing Gear Door Cyl. (Aft)	Thompson	к-51894-1
Add the fol	lowing to bottom of page:		
	Sective Ships 1 through 13. Sective Ships 14 and on.		
A-11 <u>I</u>	ANDING GEAR EQUIPMENT		
From: 2	Main Oleo Shock Strut	Cleveland Pneu.	9729A-L/R or 9729C-L/R
2	Nose Landing Gear Wheels and Brakes	Goodyear	9541334 or 9541334F, 956-479
To: #2	Main Oleo Shock Strut	Cleveland Pneu.	9729A-L/R or
**2	Main Oleo Shock Strut	Cleveland Pneu.	9729C-L/R 9729D
2	Nose Landing Gear Wheels and Brakes	Goodyear	9541334 or 9541334F, 9560479
A-12A	FURNISHINGS		
From: 1	Tank Assembly, Water	Convair	22-95400

Page 4 of 6

Page No.	Quan	Description	Manufacture	Part or Spec.
ALL LAND			Manufacturer	Number
A-12A		FURNISHINGS (Cont)		
	#1 ##1	Tank Assembly, Water Tank Assembly, Water	Convair Convair	22-95400 22-95400-1
A-13	I	FURNISHINGS		
From:		Toilet Tank and Hardware Toilet Tank and Hardware Buffet	Convair Convair	22-93802 (Fwd Lav) 22-94802 (Aft Lav)
	2	No. 1 No. 2 No. 3 No. 4 Coffee Makers (200-Volt,	Nordskog Co. Nordskog Co. Nordskog Co. Nordskog Co.	
		3-Phase, 400-Cycle, A/C 28v dec	Nordskog Co.	5045E
To:	ø1 ø2 øø1	Toilet Tank and Hardware Toilet Tank and Hardware Toilet Tank and Hardware	Convair Convair Convair	22-93802 (Fwd Lav) 22-94802 (Aft Lav) 22-09576-805
	p\$1	Toilet Tank and Hardware	Convair	(Fwd Lav) 30-09407-1 (Aft L/H Lav)
	øø1	Toilet Tank and Hardware	Convair	30-09407-2 (Aft R/H Lav)
	2 884	Buffet No. 1 No. 2 No. 3 No. 4 Coffee Makers (200-	Nordskog Co. Nordskog Co. Nordskog Co. Nordskog Co.	94-14800-004 94-14800-005 94-14800-007 94-14800-006
		Volt, 3-Phase, 400- Cycle, A/C 28v d-c	Nordskog	5045ED
Delete	the .	following item:		
	*1	Water System Pump	Cornelius Co.	3730100
A-13A	F	URNISHINGS		
From:	1 **1	Strap, Assist Rope, Forward Main Entrance Water System Pump	Convair Calco	92238 C-7010A

Delta Airlines, Inc. Change No. 19J

Page 5 of 6

Page Quan No. Reqd	Description	Manufacturer	Part or Spec.
A-13A <u>F</u>	URNISHINGS (Cont)		
1 #1 ##1 ###1	Strap Assist Rope Forward Water System Pump Water System Pump Water System Pump	Convair Cornelius Co. Calco	22-92238 3730100 C-7010A C-7010B
Add the fol	lowing to bottom of page:		
##Eff	ective Ships 1 through 10. ective Ships 11 through 13 ective Ships 14 and on.		
A-13A-1 <u>F</u>	<u>URNISHINGS</u>		
From: 1	Cabinet Dispenser, Aft Lav. L/H Cabinet Dispenser,	Convair	22-94805-3
	Aft Lav. R/H	Convair	22-94805-4
To: 1	Cabinet Dispenser, Aft Lav. L/H Cabinet Dispenser, Aft Lav. R/H	Convair	22-94803-1 22-94803-2
A-14 PRESS	URIZATION, ANTI-ICING AND	AIR CONDITIONING	EQUIPMENT
From: 2 2 1	Freon Compressors Freon Condensors Controller, Cabin	Ham. Standard Ham. Standard	561254 550281
	Pressure	AiResearch	102290-3
To: \$2 \$\$2 \$\$2 \$\$2 \$1	Freon Compressors Freon Compressors Freon Condensors Freon Condensors Controller, Cabin	Ham. Standard Ham. Standard Ham. Standard Ham. Standard	561254 573960 550281 574028
ø\$1	Pressure Controller, Cabin	AiResearch	102290-3
	Pressure	AiResearch	102290-4
A-18 F	IRE EXTINGUISHING EQUIPMEN	T	
From: 4	Containers	Walter Kidde	891154-03

GENERAL DYNAMICS/CONVAIR

Delta Airlines, Inc. Change No. 19J

Page 6 of 6

Page No.	Quan Reqd	Description	Manufacturer	Part or Spec. Number
A-18	F	IRE EXTINGUISHING	EQUIPMENT (Cont)	
To:	**†	Containers Containers	Walter Kidde Walter Kidde	891154-03 891154-04

Add the following to bottom of page:

*Effective Ships 1 through 13. **Effective Ships 14 and on.

Effect on Weight Empty: 0
Effect on Balance: 0
Effect on Performance: None

CONVAIR

A DIVISION OF GENERAL DYNAMICS CORPORATION

26FC UD: 55-003	DATE:
CUSTOMER: Delta Air Lines	MCLDTD
CHANGE NO: 19H	MODEL: 22-2 (Convair "830")
THE Manufacturer's Name and/or	Part Number
ORIGIN: Customer approved specific furnished equipment REASON FOR CHANGE: To identify equipme	designations for items of Convair ent items listed in Appendix I-C
EFFECT ON WEIGHT *	EFFECT ON BALANCE *
GUAR, WT. EMPTY OPER, WT. EMPTY	INCH LB.
EFFECT ON GUARANTEED PERFORMANCE: * None	
* NEGLIGIBLE CHANGES WILL BE ACCUMULATED AND TOTALS REFLECTED IN A FUTURE CHANGE PROPOSED ACCEPTANCE OF THIS CHANGE IS DEPENDENT UPOPRIOR ACCEPTANCE OF THE FOLLOWING CHANGES	DN DN
	ENGINEERING APPROVAL
LATEST DATE OF ACCEPTANCE:	AIRPLANES AFFECTED:
SPECIAL PROVISIONS:	EFFECT ON PRICE PER AIRPLANE: RECURRING: NON-RECURRING: TOTAL:
ACCEPTED: BY: DATE:	CONVAIR, A DIVISION OF GENERAL DYNAMICS CORP.

Delta Air Line Change No. 19H Page 1 of 4

Itle: Manufacturer's Name and/or Part Number

rigin: Customer approved specific designations for items of Convair furnished equipment.

eason for Change: To identify equipment items listed in Appendix I-C.

ppendix I-C: Change or add Manufacturer's name and or part numbers to items so as to read as follows:

age No.		Reqd.	Description	Manufacturer	Part or Spec. Number
A-1	POWER P	LANT EQU	I PAISNY		
	wit		Pressure Ratio Trans- mitter	Kollsman	A33041-50-025
	**17		Pressure Ratio Trans- mitter	Kollsman	c33041-50-433
A-7	INSTRUM	ENTS AND	RELATED EQUIPMENT		
	4		Tachometer indicator	Gen Electric	8DJ81-LAW-1
A-8	1		Stabilizer Computer, Consisting of:	Sperry	1776002-5
	1		l Servo Amplifier 2 Servo Amplifier 1 Safety Monitor 1 Trim Coupler 1 Stabilizer Computer Rack	Sperry Sperry Sperry Sperry	619298-5 619298-4 1775389-1 1775390-7
	1		Flight Control Compute Consisting of:		1776003-21
			1 Yaw Command Compute	er Sperry	620134-3
			1 Roll Command Com- puter	Sperry	1775339-3
			1 Pitch Command Com- puter 1 Radio Coupler	Sperry Sperry	1775391-4 1775388-4 or 1782104-4
			1 Pressure Computer	Sperry	1775882-10 or 1784027
			1 Interlock Rack	Sperry	1775392-3

*Effective ships 1 thru 7
**Effective ships 8 thru 13

Convair

Convair

22-93803

(Fwd Lav) 22-94804-3 (Aft Lav L/I 22-94804-4

(Aft Lav R/I

and the same of th		14.0	
A-8	/ /		4
0		nn	TI
A-U	ıv	UI1	L 1
			- /

A-8 (0	Cont)				
	1 1	Vertical Gyro Rudder Servo Drive Elevator Servo Drive Aileron Servo Drive Auto-Pilot Indicator Trim Servo Motor and Drive	Sperry Sperry Sperry Sperry Sperry Sperry		2585297 615743-09 615743-03 615743-10 1776004-5 1778879-21
Λ-9	1	Indicator, Master True Airspeed	Kollsman		A29277-10-00
A-10	HYDRA	ULIC EQUIPMENT		or	B29277-10-00
	2	Flap Actuating Motors	Vickers		MF-016B007A
	1	Main System Pumps, (Variable Displacement Type) Auxiliary Electric Pump	Vickers N.Y. Air Br	ake	AS61695-L-2 165W01008-2
A-11	LANDI	NG GEAR EQUIPMENT			
	2 2 8	Main Oleo Shock Strut Nose Gear Wheel MLG Wheels	Cleveland Pneumatic Goodyear Goodyear	or or	9729A-L & R 9729C-L & R 9541334 9541334F 9541333 9541333F
A-12	FURNI	SHINGS			,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,
	3	Stewardess Seats	Convair		22-93513-1 22-93529-1 22-93503-801
	7 8	Passenger Seats L/H Double Passenger Seats L/H Double	Convair Convair		22-92501-80 22-92501-80
	78	Passenger Seats R/H Double Passenger Seats R/H Double	Convair Convair		22-92501-806 22-92501-816
	1	Passenger Seats (Special Double L/H Passenger Seat (Special Double R/H	Convair Convair		22-92501-81: 22-92501-81

1 Toilet Tissue Dispenser

1 Toilet Tissue Dispenser

1 Toilet Tissue Dispenser Convair

Page 3 of 4

	2 Soap Dispensers Cake 1 Soap Dispenser Cake	Convair Convair	22-94806-3 22-94806-4
Delete	3 Towel Dispenser Units (each consisting of three dispensers; two universal for either linen or paper and one for paper only	r	
A-12A	Passenger Seat (Double) with Food Tray Receptacle - L/H Passenger Seat (Double) with Food Tray Receptacle - L/H Passenger Seat (Double with Food	Convair Convair	22-92501-807 22-92501-813
	1 Passenger Seat (Double with Food Tray Receptacle - R/H 1 Passenger Seat (Double with Food Tray Receptacle - R/H	Convair	22-92501-808
Delete	3 Cleansing Tissue Dispensers	Convair Convair	22-92501-814 22-93803(Fwd Lav) 22-94803(Aft Lav)
A-13	l Airplane Check-off List	Convair	22-91909-809
A-13A	Add the following:		
	Consisting of: Cleansing Tissue Dispenser Universal Dispenser (Linen or Paper) Dispenser - Paper Towels Soap Dispenser	Convair	22- 93803-1
	Cabinet Dispenser - Fwd Lav Consisting of: 1 Sanitary Napkin Dispenser 1 Air Sickness Bags Dispenser 1 Toilet Tissue Dispenser	Convair	22-92839
	Cabinet Dispenser - Aft Lav Consisting of: Air Sickness Bags Dispenser Universal Dispenser (Linen or Paper) Dispenser - Paper Towels Cleansing Tissue Dispenser Sanitary Napkin Dispenser	Convair	22-94803-1

. . CONVAIR: SD

Delta Air Lines Change No. 19H

Page 4 of 4

Cabinet Dispenser - Aft Lav. 1

Consisting of: 1 Air Sickness Bags Dispenser

2 Universal Dispenser (Linen or Paper l Dispenser Paper Towels l Cleaning Tissue Dispenser Sanitary Napkin Dispenser

Convair 22-94804-1

A Division of General Dynamics Corporation San Diego, California

SPEC NO: ZD-22-00	3	DATE: 15 November 1957
CUSTOMER: Delta Ai	r Lines	MCLDtd
CHANGE NO: 19C		MODEL: (880) 22-2
TITLE: Manufactur	er's Name and/or	Part Number
ORIGIN: Customer-a	pproved specific of equipment as noted	lesignation for items of Contractor-
		oment items listed in APPENDIX I-C.
	EFFECT ON WEIGH	T * EFFECT ON BALANCE *
Guar. Wt. Empty	Oper. Wt. Empty	
0	0	0 Inch Lb.
EFFECT ON GUARANTE	ED PERFORMANCE: * Hor	10
* Negligible Change Totals Reflected	es Will be Accumul in a Future Chang	ated and e Proposal
Acceptance of thi	is Change is not rured only to recor	equired
	proved by CAC proc	
LATEST DATE OF ACCE	EPTANCE:	AIRPLANES AFFECTED:
SPECIAL PROVISIONS:		EFFECT ON PRICE PER AIRPLANE: Recurring: Non-Recurring
		Total:
ACCEPTED:		CONVAIR, A Div. of Gen. Dyn. Corp.
BY:		BY:
DATE:		Chief of Contract Administration Commercial

Delta Air Lines Change No. 190 15 November 1957 Page 1 of 4

Hanufacturer's Name and/or Part Number Title:

Origin: Customer-approved specific designations for items of Contractor-furnished equipment as noted.

Reason for Change: To identify Equipment items listed in APPENDIX I-C.

Description of Change:

APPENDIX I-C: Change or add Manufacturer's Names and/or Part Numbers to items noted so as to read as follows:

nge No.	Quan. Aegd	Description FUEL SYSTEM EQUIPMENT Pressure Refueling Adapter Cap-Pressure Fuel Servicing(Plush) (WAS 4 Underwing Refueling	Manufacturer Parker Aircraft Parker Aircraft	Part or Spec. Number 1327-575699 1327-575806
	4	Units) Emergency Fuel Shut-off Valve (WAS 4 Firewall Shut-off Valve)	General Contr.	AV16B1421B
-1	i _t	Cator (WAS 4 Engine Oil Temperature Gage)	Lewis Engr.	162023
-3	1	ELECTRICAL EQUIPMENT External Power Receptacle (AC)	Cannon Electric Burton Electric Joy Mfg. Co. A.& J.M.Anderson	AN 3114-1B: 17175-106 255 A6-437M6 4627
	1 1 2	Loadmeters (DC) Loadmeters (AC) Voltmeter (DC) Voltmeter (AC) Transformer, 1-Phase Stepdown	Gen. Electric Gen. Electric Gen. Electric Cen. Electric Osborne	8 DW 84AAB2 8 AW 61AAB2 8 DW 84VVB2 8 AW 61VVB2 6781

Delta Air Lines Change No. 190 15 November 1957 Page 2 of 4

ge Quar		Manufacturer	Part or Spec.
3 2 2 1 4 4 4 4 4	Transformer, 3-Phase Power Failure Warning Unit Ignition Switch Transformer Rectifier Line and Bus Tie Contactor	Osborne Hartman Micro Chatham Gen.Electric	6784 AV:1-869 V3-1 28VS50 B-124A
14	(WAS 8 A-C Tie Breakers) Control Panel-Regulator (AC) (WAS 4 A-C Control Panel) 4 A-C Voltage Regulator)	Gen. Electric	382781F125A1
1 1 1	The same of the same was to the same of th	Gen. Electric Gen. Electric Hartman Hartman	A-874F 2CH211A1 A-718K A-876
<u>_</u> 4	HF COMMUNICATION		
3	Antenna Coupler (WAS 1 Load Coil)	Collins	180 R-4
L-5		Telephonics Telephonics Quam	R8-38E TC136B 4A07Z45
1-5	PASSENGER ENTERTAINMENT (PA) S		(00
	Pape Reproducer Presto per ARINC 539	Presto	MPB 600
A-6	ATC TRANSPONDER ANTENNA Antenna - "L" Band Stub (WAS 1 Antenna)	Electronic Spec.	LB-147-A

Delta Air Lines Change No. 193 15 November 1957 Page 3 of 4

age	Quan.	Description	Manufacturer	Part or Spec.
-7		INSTRUMENTS AND PELATED EQUIPMENT		
	1 1 1	Cabin Temperature Indicator Outside Air Temperature Bulb Dual Cabin Altitude and Differ-	Lewis Engr. Lewis Engr.	162021 548-1
	4	ential Pressure Indicator (WAS 1 Cabin Altitude Indicator)	Kollsman	B26395-10-004
	1 2 1,	Cabin Rate of Climb Indicator Clock	Pioneer Cent. Wakeman	1653-6AB-A6-1 W33-7530-10
) ₊ 1 2	Exhaust Temperature Indicator Flap Position Indicator (Dual) Magnetic Compass	Honeywell Gen. Electric U.S. Gauge	JG 116A Type 8DJ91LAB-1 C-4B
	2	Pressure Indicator (Hydraulic)	U.S. Gauge	SRL-07 Plus Range Marking:
	1	Ram Air Temperature Indicator (WAS 1 Cutside Air Temp. Indicator)	Lewis Engr.	161BCL2
	NANA	Rate of Climb Indicator Techometer Indicator Turn and Bank Indicator (Elec.)	Pioneer Cent. Gen. Electric Pioneer Cent.	1653-6AB-A6-1 8DJ81-LAB 3920-1AD-A1-1
	4	Fuel Quantity Indicator Repeater: 2 Fuel Quantity Indicator 2 Fuel Quantity Indicator (WAS AR Fuel Quantity Ind.,	Simmonds Simmonds	383093-01581 383093-01582
	ц	direct reading) Fuel Quantity Ind. (Counter- Pointer type):		allanda ondin
		2 Fuel Quantity Indicator 2 Fuel Quantity Indicator (WAS 4 Fuel Quantity Indicator)	Simmonds Simmonds	383053-01581 383053-01582
	14	Fuel Quantity Totalizator Ind. Fuel Quantity Compensators Fuel Quantity Probe:	Simmonds Simmonds	383053-04585 300047-13001
		2 Fuel Quantity Probe 2 n n n	Simmonds	381056-01277 381056-02278 381056-02279
		2 H H H H 2 H	31 31	381056-02279 381056-02280 381056-02281 381056-02282 381056-02284 381056-02285 381056-02286 381056-02288 381056-02288 381056-02288
		2 H H H H	11 11 11	381056-02283 381056-02284 381056-02285
	ese:	2 n n n	H H	381056-02286 381056-02287
		2 n n n 2 n n n	11 11	381056-02288 381056-02289 381056-02290
		2 H H H	11	381056-02291 381056-02292

Delta Air Lines Change No. 190 15 November 1957 Page 4 of 4

age	Quan.	Description	Manufacturer	Part or Spec.
-9		FLIGHT INSTRUMENTS Followen Integrated Instrument Sy	stem	
	2	Altimeter Scale Error and Corrector Package (WAS 2 Altimeter)	Kollsman	A30410-00-001
	2.	Indicator, Airspeed - Angle of Attack	Kollsman	A29297-10 Plus Range Harkings
	1	Indicator, Master Static Air. Temp. (WAS 1 Ind. True Outside Air	Kollsman	A29257-10-001
	1	Temp.) Indicator, Master True Air Speed Indicator, Mach No. Synchotel, Transmitter Type	Kollsman	A29277-10-001
			Kollsman	A29247-10-001
-10	L _i .	HYDRAULIC EQUIPMENT Main System Pumps		
	2 6 4	(Variable displacement type) Accumulator (100 cu. in) Accumulator	Ham. Standard Redco Tool P/N tobbe supplied	521415 8404-001, Type A
	8	Spoiler Actuating Cylinders Spoiler Actuating Cylinders	Peacock Engr.	51165
	242414	Outboard Main Relief Valves Filter, Low Pressure Filter, High Pressure, 5 GPM Filter, High Pressure, 16 GPM Anti-Skid Control Valve Anti-Skid Control Valve	Peacock Engr. Dole Valve Aircraft Porous Purolator Prod. Aircraft Porous Hydro Aire	51170 80037 A0-1373-16 -60878 AC-1574-12 38-103 38-099
10	4		Hydro Aire	30-033
-12		FURNISHINGS Buffet (4 Units) #1	Convair	22-93002
		#2 and #3	Convair	22-93005 22-93009
-16		PYROTECHNICS		
	2	Flares	Kilgore Mfg.	Wiley Type S.A.8

A Division of General Dynamics Corporation San bloco, California

COMMUNICIAL CHARGE PROPOSAL

EFEC No:ED-22-00	3	DAUN:						
Mis 7 Man: Delta Air	Lines Inc.	MCL 10,055 Dtd 16 May 1957						
CHANGE NO: 18B		MODEL: (880) 22-2						
Increase of Landing Weight to 130,000 pounds.								
Meeting of 24 April 1957 between Convair and Delta Representatives. CLASCON FOR CHANGE: Customer request to replace existing brakes with larger brakes to suit revised landing weight and specified types of tires. (Revision to CCP No. 18A dated 16 May 1957.)								
	SPENCT ON WEIG							
Guar. Wt. Empty	Oper. Wt. Empt	Ly Committee of the Com						
-68.2 lbs	-68.2 lbs	-115,519 Inch Lb.						
Noted on attached exhibit.								
* Mosligible Change Lotals Reflected	es Will be Accumu in a Future Chan	ulated and nge Proposal						
Prior Acceptance								
		Engineering Approval						
BASEST DATE OF ACC	PTANCE:	AIRPLANUS AFFECTED:						
COMMITTED PROVISIONS:		EFFECT ON PRICE PER AIRPLANE: Recurring: Non-Recurring Total:						
ACCENTED:		CONVAIR, A Div. of Gen. Dyn. Corp.						
BY: David :		BY: Chief of Contract Administration Commercial						

Delta Air Lines Inc. Change No. 16B

130,000."

Page 1 of 2

1b

Increase of Landing Weight to 130,000 Pounds Title:

Meeting of 24 April 1957 between Delta and Contractor Repre-Origin:

sentatives.

Reason for Change: Customer request to replace existing brakes with

larger brakes to suit revised landing weight and specified types of tires. (Revision to CCP No. 18A dated 16 May 1957.)

Description of Change:

Page 10, Paragraph 3.1.1 GUARANTEED PERFORMANCE:

Change the following paragraph:

From:	"CAA landing distance (intended destination) at sea level over 50 ft obstacle in accordance with CAR 4b with weight			
	of 123,500 lb	ft	±5%	5,650."
To:	"CAA landing distance (intended destination) at sea level over 50 ft obstacle in accordance with CAR 4b with weight			
	of 130,000 lb	ft	±5%	5,900."
From:	"Maximum allowable landing weight at sea level in accordance with CAR 4b			
	climb requirements	1b		123,500."
To:	"Maximum allowable landing weight at sea level in accordance with CAR 4b			120 000 #

Page 17, Paragraph 3.4.1 STRENGTH:

Change: Maximum Landing Weight 123,500**

climb requirements

Maximum Landing Weight 130,000." To:

Delete note at bottom of page on Maximum Structural Landing Weight.

Delta Air Lines Inc. Change No. 18B

Page 2 of 2

Page All - APPENDIX I-C, LANDING GEAR EQUIPMENT:

Delete entire page and replace with the following:

28888	Main Main	Oleo Shock Strut Wheels Wheel Brakes Wheel Tires (39 x 13)	Goodyear Goodyear U.S. Rubber	9541333 PD860 9560388 PD860 20 P.R. Type VII HP
1 2 2	Nose	Oleo Shock Strut Wheels Wheel Tires (29 x 7.7)	Goodyear U.S. Rubber	9541334 PD875 12 P.R. Type VII HP
1	Nose	Wheel Brake	Goodyear	9560389 PD875

LANDING GEAR WHEEL, BRAKE, AND TIRE, DESIGN WEIGHT

MAIN GEAR

8	Wheels	(a)	65.2	lb	ea	Ŧ	=	-	**	~~	-	-	-	-	-		521.6	lb
8	Brakes	(2)	120.3	16	ea	=	-	=	-	-	-	-	**	-	-		962.4	lb
8	Tires (Tubele		84.1	lb	ea	-	-	-	-	~	-	-		1	-	-2	672.8 2156.8	lb lb
NOSE	GEAR																	
2	Wheels	@	35.7	1b	ea	***	-	-	-	=	-	un.			-		71.4	16
2	Brakes	@	84.0	1b	ea	-	_	-	-	-	-	=	-	-	-		168.0	1b
2	Tires (Tubele		33.8	1b	ea	10	-	-	1	1	-	=	-	=	-	-	67.6	

The above weights are those allotted for the specific items noted. Any change requested by the Buyer that alters these weights will affect the airplane empty weight guarantee and be subject to negotiation."

Effect on Weight Empty: -68.2 pounds
Effect on Balance: -115,519 inch-pounds
Effect on Performance: Noted on Exhibit

SPISC NO: ZD-22-00		_ DATE: 15 April 1957						
CUSTOMER: DELTA AI	R LINES	MCL 10,005 Dtd 20 Feb. 1957						
CHANGE NO: 17		MODEL: (880) 22-2						
TITLE: CRAF Provisions: Deletion of:								
ORIGIN: Reference: DAL Ltr. dated 7 January 1957								
REASON FOR CHANGE: Customer requested deletion of all reference to CRAF provisions.								
	EFFECT ON WEIG							
Guar. Wt. Empty	Oper. Wt. Empt	y						
. 0	0	0 Inch Lb.						
EFFECT ON GUARANTEED PERFORMANCE: *								
	in a Future Chan	ge Proposal						
Acceptance of the Prior Acceptance	is Change is Deper of the Following	ndent Upon Changes:						
		Engineering Approval						
LATEST DATE OF ACCI	EPTANCE:	AIRPLANES AFFECTED:						
And the second second								
SPECIAL PROVISIONS		EFFECT ON PRICE PER AIRPLANE: Recurring: Non-Recurring Total:						
SPECIAL PROVISIONS ACCEPTED:		Recurring: Non-Recurring						
		Recurring: Non-Recurring Total:						

15 April 1957 Change No. 17

CONVAIR: SD

Title: CRAF Provisions, Deleted of:

Origin: Reference: DAL Ltr. dated 7 January 1957

Reason for Change: Customer requested deletion of all reference to CRAF provisions.

Description of Change:

Page 79, Paragraph 3.16.10.2 SIGNAL LIGHT (CRAF)
Delete paragraph.

Page 90, Paragraph 3.17.1 EQUIPMENT:
Delete the following:
Radar Identification System (CRAF)
Radar Altimeter (CRAF)

Page 91, Paragraph 3.17.1.1 CONTROL PANKLS:
Delete:
Radar Identification Control (CRAF)

Page 102, Paragraph 3.17.4.2 IDENTIFICATION RADAR (CRAF):

Effect on Weight: 0 Effect on Balance: 0 Effect on Performance: 0 Not Charge 710. 16
(Cancelled)

SPEC NO: ZD-22-00		DATE:	4 June	1957				
CUSTOMER: Delta Air	Lines, Inc.	MCL_ 10	077 Dtd_					
CHANGE NO: 15		MODEL:	(880) 22-	2				
TITLE: Performance Data; Revisions to								
ORIGIN: Contractor Initiated								
REASON FOR CHANGE: To furnished Customer with latest available performance data.								
3	EFFECT ON WEIGHT		EFFECT ON	BALANCE *				
Guar. Wt. Empty	Oper. Wt. Empty							
None	None		None	Inch Lb.				
EFFECT ON GUARANTEED PERFORMANCE: *								
	The second secon	Noted						
	in a Future Chang	e Proposal						
Prior Acceptance	is Change is Depen of the Following	Changes:						
			Engineer	ing Approval				
LATEST DATE OF ACC	EPTANCE:	AIRPLANES AI	FECTED:					
LATEST DATE OF ACCOUNTS OF ACC		ATRPLANES AND EFFECT ON PROPERTY OF PROPER	RICE PER AIF					
SPECIAL PROVISIONS		EFFECT ON PI Recurring:_ Non-Recurring Total:	RICE PER AIF					
SPECIAL PROVISIONS		EFFECT ON PI Recurring:_ Non-Recurring Total:_ CONVAIR, A I	RICE PER AIF	Dyn. Corp.				

CONVAIR: SD

Delta Air Lines, Inc. Change No. 15 4 June 1957

Title: Performance Data; Revisions to

Origin: Contractor Initiated

Reason for Change: To furnish Customer with latest available

performance data.

Description of Change:

Page 9, Paragraph 3.1.1.1 - GUARANTEED PERFORMANCE:

Under "Take-off distance....", last three numbers on page, change:

8,600 to 4,845 8,600 to 8,170 9,650 to 9,170*.

Page 10, Paragraph 3.1.1.1 -

First item on page, change: "7,600" to "7,220".

Second item, change: "5,650" to "5930".

Third item, "Maximum allowable take-off weight", change:

".... shall not preclude operation at 174,025 1b.

to

shall not preclude operation at 179,025 lb. at 178,500*.

Effect on Weight Empty: None Effect on Balance: None Effect on Performance: Noted

SPEC NO: ZD-22-00		DATE:	3 May 1957					
CUSTOMER: Delta Air	Lines, Inc.	MCL	Dtd					
CHANGE NO: 14		MODEL:_	(880) 22-2					
TITLE: Revised (Adminis	Description of Windshi strative Type Change)	eld Rain	Removal System					
ORIGIN: Contractor Initiated								
REASON FOR CHANGE: To clarify intent of Detail Specification.								
	EFFECT ON WEIGHT *		EFFECT ON BALANCE *					
Guar. Wt. Empty	Oper. Wt. Empty							
None	None		None Inch Lb.					
EFFECT ON GUARANTE	ED PERFORMANCE: *							
	None							
* Negligible Change Totals Reflected	es Will be Accumulated in a Future Change Pr	and oposal						
Acceptance of the Prior Acceptance	is Change is Dependent of the Following Chan	Upon ges:						
			Engineering Approval					
LATEST DATE OF ACCEPTANCE: AIRPLANES AFFECTED:								
		white the same of						
SPECIAL PROVISIONS		THE RESERVE TO SERVE THE PERSON	ICE PER AIRPLANE:					
SPECIAL PROVISIONS	Recu Non-	rring:	ICE PER AIRPLANE:					
SPECIAL PROVISIONS	Recu Non- Tota	rring:_ Recurrin l:	g					
	Recu Non- Tota CONV	rring:_Recurrin 1:	iv. of Gen. Dyn. Corp.					
ACCEPTED:	Recu Non- Tota CONV BY:	rring:_Recurrin 1:	g					

Title: Revised Description of Windshield Rain Removal System (Administrative Type Change)

Origin: Contractor Initiated

Reason for Change: To clarify intent of Detail Specification.

Description of Change:

Page 28, Paragraph 3.7.1.2.2 - RAIN REMOVAL:

Delete second and third sentences and substitute following:

"Removal of rain shall be accomplished by air blast. This system shall utilize engine bleed air directed at high velocity across the pilot's and copilet's forward windshield penels. Overheat control and adequate protection from the hot air blast shall be provided for the windshield panels."

Effect on Weight Empty: None Effect on Balance: None Effect on Performance: None

SPEC NO: ZD-22-00;	3	DATE:
CUSTOMER: Delta Ai:	r Lines Inc.	MCL Dtd_
CHANGE NO: 13A		MODEL: (880) 22-2
TITLE: Provisions in Baggage Conf		o Door for use with Preloaded
		C No. 3.19+31 and Item 4, Part IV nd Contractor proposed for Delta.
REASON FOR CHANGE:	To allow for late containers.	er incorporation of preloaded baggage
	EFFECT ON WEIGH	
Guar. Wt. Empty	Oper. Wt. Empty	
0	0	0 Inch I.b.
EFFECT ON GUARANTEE	D PERFORMANCE: *	None
* Negligible Change Totals Reflected	es Will be Accumul in a Future Chang	lated and ge Proposal
Acceptance of thi Prior Acceptance	is Change is Deper of the Following	ndent Upon Changes:
		Engineering Approval
LATEST DATE OF ACCE	EPTANCE:	AIRPLANES AFFECTED:
SPECIAL PROVISIONS		EFFECT ON PRICE PER AIRPLANE:
		Recurring: Non-Recurring
		Total:
ACCEPTED:		CONVAIR, A Div. of Gen. Dyn. Corp.
BY:		BY:
DATE:		Chief of Contract Administration Commercial

Title: Provisions for Enlarged Cargo Door for use with Preloaded Baggage Containers

Origin: TWA requested, Reference: RFC No. 3.19-31 and Item 4
Part IV of TWA Change Order No. 1, and Contractor proposed
for Delta

Reason for Change: To allow for later incorporation of preloaded baggage containers

Page 30, Paragraph 3.7.1.5.4 - CARGO DOORS:

Add the following sentences to the end of paragraph:

"Ducting, tubing, wiring, etc., shall be routed to allow for the later addition of an enlarged forward cargo door compatible with a preloaded baggage container system. The door opening need not exceed approximately inches fore and aft, and approximately to inches measured vertically from the cargo floor".

38" per 3.0-2-51

Effect on Weight Empty: 0
Effect on Balance: 0
Effect on Performance: None

Dal-Change 20.12
(Rejected)

SPEC NO: ZD-22-00	3	DATE: 6 May 1957						
CUSTOMER: Delta A1	r Lines, Inc.	MCL 10,042 Dtd 19 April 1957						
CHANGE NO: 11		MODEL: (880) 22- 2						
TITLE: Oil Tempe	rature Gages, Change	from Dual to Single Instruments						
ORIGIN: Contractor Initiated								
REASON FOR CHANGE: To comply with instrument arrangement and description as presented and agreed to in Mock-Up Minutes. Ref.: Mock-Up Minutes Dated 25, 26 February 1957, and 30 April 1957								
	EFFECT ON WEIGHT *	EFFECT ON BALANCE *						
Guar. Wt. Empty	Oper. Wt. Empty							
+ 1.0 1b	+ 1.0 1b	Negligible Inch Lb.						
EFFECT ON GUARANTE	ED PERFORMANCE: * None							
* Negligible Change Totals Reflected	es Will be Accumulate in a Future Change P	d and roposal						
Acceptance of the Prior Acceptance	is Change is Dependen of the Following Cha	t Upon nges:						
		Engineering Approval						
LATEST DATE OF ACCE	EPTANCE: AIR	PLANES AFFECTED:						
SPECIAL PROVISIONS:	Reci Non-	CCT ON PRICE PER AIRPLANE: arring: -Recurring al:						
ACCEPTED:	CON	VAIR, A Div. of Gen. Dyn. Corp.						
BY:	BY:							
DATE:		Chief of Contract Administration Commercial						

Title: Oil Temperature Gages, Change from Dual to Single Instruments

Origin: Contractor Initiated

Reason for Change: To comply with instrument arrangement and Description as presented and agreed to in Mock-Up Minutes. Ref.:
Nock-Up Minutes Dated 25, 26 February 1957, and 36
April 1957

Description of Change:

Page 59, Paragraph 3.14.1.4 - FLIGHT ENGINEER'S INSTRUMENTS

Change: 4 Oil Temperature Gages (2 Dual)

To: 4 011 Temperature Gages

Page A-1, APPENDIX I-C - OIL SYSTEM EQUIPMENT

Change: 2 Off Temperature Gages (Dual)

To: 4 011 Temperature dages

Effect on Weight Empty: +1.0 lb Effect on Balance: Negligible Effect on Performance: None

SPEC NO: ZD-22-003		DATE: 15 March 1957						
CUSTOMER: DELTA AIRL	INES	MCL 22-10,007 Dtd 20 Feb. 1957						
CHANGE NO: 10		MODEL: (880) 22-2						
TITLE: Pitot Static Tubing Size - Change to 3/8" Diameter Section								
ORIGIN: Contractor Initiated								
REASON FOR CHANGE: Contractor wishes to notify that use of 3/8" Pitot static tubing will prevent retention of moisture by capillary action.								
Guar. Wt. Empty	EFFECT ON WEIGHT *	EFFECT ON BALANCE *						
dual . W. Emply	Oper. Wt. Empty							
Negligible	Negligible	Negligible Inch Lb.						
	EFFECT ON GUARANTEED PERFORMANCE: * None							
* Negligible Changes Totals Reflected in	Will be Accumulated a a Future Change Pr	and oposal						
Acceptance of this Prior Acceptance of	Change is Dependent the Following Chan	Upon ges:						
		Engineering Approval						
LATEST DATE OF ACCEPT	ANCE: AIRP	LANES AFFECTED:						
SPECIAL PROVISIONS: Acceptance by all currents required.	rent Recui	CT ON PRICE PER AIRPLANE: rring: Recurring						
Acceptance by all cur	rent Recui Non-I Total	rring:Recurring						
Acceptance by all currents required.	rent Recur Non-H Total CONVA	Recurring L:AIR, A Div. of Gen. Dyn. Corp.						

15 March 1957 Change No. 10

CONVAIR: SD

Title: Pitot Static Tubing Size - Change to 3/8" Diameter Section

Origin: Contractor Initiated

Reason for Change: Contractor wishes to notify that use of 3/8" pitot static tubing will prevent retention of moisture by capillary action.

Description of Change:

Page 62, Paragraph 3.14.3.6 INSTRUMENT LINES AND CONNECTIONS:
At end of sentence "nor less than 1/4" on the pitot side"
Add: "except that pitot lines shall be 3/8 inch for a
minimum of 3 feet inboard of the pitot tube connector
fitting."

Effect on Weight: Negligible Effect on Balance: Negligible Effect on Performance: None

SPEC NO: ZD-22-003		DATE:_	o May 197					
CUSTOMER: Delta A1	r Lines, Inc.	MCL_	Dtd					
CHANGE NO: 9			(880) 22-	2				
TITLE: Air Conditioning System; Relief Valve Setting								
ORIGIN: Contractor Initiated REASON FOR CHANGE: Administrative Type Change to correct and clarify intent of specification.								
	EFFECT ON WEIGH	HT *	EFFECT O	N BALANCE *				
Guar. Wt. Empty None	Oper. Wt. Empty		None	Inch Lb.				
EFFECT ON GUARANTE	EFFECT ON GUARANTEED PERFORMANCE: * None							
* Negligible Changes Will be Accumulated and Totals Reflected in a Future Change Proposal Acceptance of this Change is Dependent Upon Prior Acceptance of the Following Changes: Engineering Approval								
LATEST DATE OF ACC	EPTANCE:	AIRPLANES A	AFFECTED:					
SPECIAL PROVISIONS		Recurring: Non-Recurr	PRICE PER Al					
ACCEPTED:		CONVAIR, A	Div. of Ger	n. Dyn. Corp.				
BY: DATE:		BY: Chief of	f Contract Commerc	Administration ial				

Title: Air Conditioning System; Relief Valve Setting

Origin: Contractor Initiated

Reason for Change: Administrative Type Change to correct and clarify lintent of specification.

Description of Change:

Page 122, Paragraph 3.20.3.2 - RELIEF VALVE SETTING: In second line, change 8.2 psi to 8.6 psi.

> Effect on Weight Empty: None Effect on Balance: None Effect on performance: None

SPEC NO: ZD-22-00	2	DATE: 15 March 1957	
CUSTOMER: DELTA AI	RLINES	MCLDtd	
CHANGE NO: 8		MODEL: (880) 22-2	
TITLE: Cable Con	trol of Brake Meteria	ng Valves	
ORIGIN: Contractor	r Initiated		
REASON FOR CHANGE:	To clarify intent	of paragraph in specification.	
	EFFECT ON WEIGHT	* EFFECT ON BALANCE *	
Guar. Wt. Empty	Oper. Wt. Empty		
None .	None	None Inch Lb.	
EFFECT ON GUARANTE	ED PERFORMANCE: *		
	1	None	
* Negligible Change Totals Reflected	es Will be Accumulate in a Future Change l	ed and Proposal	
Acceptance of the Prior Acceptance	is Change is Depender of the Following Cha	nt Upon anges:	
		Engineering Approval	
LATEST DATE OF ACC	EPTANCE: AI	RPLANES AFFECTED:	
SPECIAL PROVISIONS	Rec No	ECT ON PRICE PER AIRPLANE: urring: -Recurring al:	
	To	CAT:	
ACCEPTED:	"l'o	NVAIR, A Div. of Gen. Dyn. Corp.	
ACCEPTED: BY:	COI		

15 March 1957 Change No. 8

CONVAIR: SD

Title: Cable Control of Brake Metering Valves

Origin: Contractor Initiated

Reason for Change: To clarify intent of paragraph in specification.

Description of Change:

Page 64, Paragraph 3.15.1.11 BRAKE VALVE:

Change paragraph to read as follows: "The brake metering valves shall be controlled by a dual cable system from the brake pedals. The brakes on the main wheels and the nose wheels shall be operated by hydraulic system No. 2.

Effect on Weight: None Effect on Balance: None Effect on Performance: None · Dal - Change No. 7

(Concelled)

SPEC NO: ZD-22-003		DATE:	13 March 1957
CUSTOMER: Delta Ai	r Lines	MCL_	Dtd
CHANGE NO: 6		MODEL:_	(880) 22-2
	g temperature requirem		inclusion of ANA
ORIGIN: Contract	or Initated		
REASON FOR CHANGE:	REASON FOR CHANGE: To more accurately define standard hot and cold atmospheric properties.		
	EFFECT ON WEIGH	T *	EFFECT ON BALANCE *
Guar. Wt. Empty.	Oper. Wt. Empty		
None	None		None Inch Lb.
EFFECT ON GUARANTE	ED PERFORMANCE: *		
		None	
* Negligible Change Totals Reflected	es Will be Accumul in a Future Chang	ated and se Proposal	
Acceptance of thi Prior Acceptance	is Change is Depen of the Following	dent Upon Changes:	
			Engineering Approval
LATEST DATE OF ACCEPTANCE: AIRPLANES AFFECTED:			FECTED:
Acceptance by all current Customers required.		EFFECT ON PRICE PER AIRPLANE: Recurring: Non-Recurring Total:	
ACCEPTED:		CONVAIR, A D	iv. of Gen. Dyn. Corp.
BY:		BY:	Contract Administration
		Chief of	Contract Administration

13 March 1957 Change No. 6

Title:

Operating Temperature Requirements and Inclusion of ANA Bulleting No. 421 Requirements

Origin:

Contractor Initiated

Reason for Change: To more accurately define standard hot and cold

atmospheric properties.

Description of Change:

Page 16, Paragraph 3.2.5 OPERATING TEMPERATURE:

Change to read as follows:

"The airplane and its equipment shall operate satisfactorily after being soaked at temperatures from -+0°F to +120°F and when flown in ambient temperatures in accordance with the extreme hot and cold atmospheres cited in ANA Bulletin No. 421 for maximum endurance possible at these temperatures."

Effect on Weight: None Effect on Balance: None Effect on Performance: None

DATE: 19 March 1997					
MCL 10,002 Dtd 20 Feb. 1957					
MODEL: (880) 22-2					
TITLE: Definition of use of "Ermeto" and "Wig-O-Flex" Fittings					
ORIGIN: Contractor Initated					
REASON FOR CHANGE: To reduce weight and accommodate requirements of wing flexing and allow length and alignment tolerances.					
EFFECT ON BALANCE *					
Negligible Inch Lb.					
* Negligible Changes Will be Accumulated and Totals Reflected in a Future Change Proposal					
nt Upon inges:					
Engineering Approval					
LATEST DATE OF ACCEPTANCE: AIRPLANES AFFECTED:					
EFFECT ON PRICE PER AIRPLANE: Recurring: Non-Recurring Total:					
WAIR, A Div. of Gen. Dyn. Corp.					

15 March 1957 Change No. 5

CONVAIR: SD

Title: Definition of Use of "Ermeto" and "Wig-O-Flex" Fittings

Origin: Contractor Initiated

Reason for Change: To reduce weight and accommodate requirements of wing flexing and allow length and alignment tolerances.

Description of Change:

Page 51, Paragrapy 3.12.9.6 PIPING AND FITTINGS:
Change 5th sentence regarding Ermeto fittings to read as
follows: "Fittings shall be of the ermeto type except for
sizes 1.00" and larger located inside the fuel tanks which
shall be of the Wiggins Wig-O-Flex type".

Effect on Weight: -102.

Effect on Balance: Negli

Effect on Performance: None

-102.0 lb Negligible

SPEC NO: ZD-22-00		DATE:_	17 June	1957	
CUSTOMER: Delta Air	Lines, Inc.	MCL 10	.071 Dtd_	23 May 1957	
CHANGE NO: 4		MODEL:	(880) 22-	2	
TITLE: Differen	tial Switches, B	leed Air Duc	ts; Deletion	a of	
ORIGIN: Contract	or Initiated				
REASON FOR CHANGE: It is not practical to use differential switches in system, therefore an alternate sensing system must be provided.					
	EFFECT ON WEIG		EFFECT C	N BALANCE *	
Guar. Wt. Empty	Oper. Wt. Empt	y			
None	None		None	Inch Lb.	
EFFECT ON GUARANTE					
		None			
* Negligible Change Totals Reflected	es Will be Accumu in a Future Char	lated and age Proposal			
Acceptance of thi Prior Acceptance	is Change is Depe of the Following	endent Upon Changes:			
			Enginee	ring Approval	
LATEST DATE OF ACCE	EPTANCE:	AIRPLANES A	FFECTED:		
SPECIAL PROVISIONS:		EFFECT ON P			
		Recurring: Non-Recurri	ng		
Addrowen					
ACCEPTED:		CONVAIR, A	Div. of Gen	. Dyn. Corp.	
BY:		BY:	Cambrash	dministration	
DATE:		Chiei oi	Commerci		

Delta Air Lines, Inc. Change No. 4 17 June 1957

Title: Differential Switches, Bleed Air Ducts; Deletion of

Origin: Contractor Initiated

Reason for Change: It is not practical to use differential switches in system, therefore an alternate sensing system must be provided.

Description of Change:

Page 121, Paragraph 3.20.2.1 - ANTI-ICING OF NONTRANSPARENT AREAS:

Delete last sentence from paragraph "(Each light shall be connected)", and substitute the following:

"Each light shall be operated by a continuous overheat detection system in order to sense bleed air dust leakage or failure."

Effect on Weight Empty: None Effect on Balance: None Effect on Performance: None

			Revised 28 October 1957 19 June 1957	
CHANGE NO: 3A			: (880) 22-2	
TITLE: Hydraulic System				
ORIGIN: Contractor Initiated REASON FOR CHANGE: To incorporate description of latest hydraulic system design into Specification				
	EFFECT ON WEIGH	IT *	EFFECT ON BALANCE *	
Guar. Wt. Empty	Oper. Wt. Empty		O Inch Lb.	
EFFECT ON GUARANTEED PERFORMANCE: * None				
* Negligible Changes Will be Accumulated and Totals Reflected in a Future Change Proposal				
	Acceptance of this Change is Dependent Upon Prior Acceptance of the Following Changes:			
Engineering Approval				
LATEST DATE OF ACCEPTANCE: AIRPLANES AFFECTED:				
Re No		Recurring: Non-Recurr	FECT ON PRICE PER AIRPLANE: curring: n-Recurring tal:	
		CONVAIR, A	WAIR, A Div. of Gen. Dyn. Corp.	
BY: DATE:		BY: Chief o	f Contract Administration Commercial	

CONVAIR: SD

Revised 28 October 1957 19 June 1957 Change No. 3A

Title: Hydraulic System

Origin: Contractor Initiated

Reason for Change: To incorporate description of latest hydraulic system

design into specification

Description of Change:

Page 64, Paragraph 3.15.1.7 - RESERVOIRS:

Revise paragraph to read as follows:

"Two hydraulic reservoirs, interconnected at approximately the refill level, shall be installed aft of the main wheel well area to supply the systems. The interconnection of the reservoirs provides for common filling and common level indication. The installation of the reservoirs shall be such that the tanks may be filled by maintenance, personnel at ground working level. One fluid level indicator shall be provided on the flight engineer's panel. The transmitter for this indicator shall be installed in System No. 2 reservoir and shall indicate the common level of both systems above the interconnection as well as System No. 2 level below the refill point. One sight gage shall be installed in System No. 1 reservoir and shall be accessible for daily preflight checks, and for routine maintenance use".

Figures 3.8-1 and 3.15-1
To be revised to reflect subject change.

Page A-10, APPENDIX I-C - HYDRAULIC EQUIPMENT:

Twenty-fourth item, Hydraulic Fluid Quantity Transmitter; Change Quantity Required from 4 to 1.

Effect on Weight Empty: Effect on Balance: Effect on Performance: 0 None

SPEC NO: ZD-22-002		DATE: 15 March 1957	
CUSTOMER: DELTA AIRI	LINES	MCL/Dtd/	
CHANGE NO: 2		MODEL: (880) 22-2	
TITLE: Fuel Pum	p - Control Relay, Por	wer Source	
ORIGIN: Contractor Initiated			
REASON FOR CHANGE:	To clarify original is	ntent of specification.	
	EFFECT ON WEIGHT *	EFFECT ON BALANCE *	
Guar. Wt. Empty	Oper. Wt. Empty		
None	None	None Inch Lb.	
EFFECT ON GUARANTEE			
	Non	6	
* Negligible Change Totals Reflected	s Will be Accumulated in a Future Change Pr	and oposal	
Acceptance of thi Prior Acceptance	s Change is Dependent of the Following Chan	Upon ges:	
		Engineering Approval	
LATEST DATE OF ACCE	PTANCE: AIRF	LANES AFFECTED:	
SPECIAL PROVISIONS: . EFFECT ON PRICE PER AIRPLANE:			
	Non-	rring:Recurring	
	Tota		
ACCEPTED:	CONT	VAIR, A Div. of Gen. Dyn. Corp.	
BY:	BY:	Chief of Contract Administration	
DATE:		Commercial	

CONVAIR: SD

Title: Fuel Pump - Control Relay, Power Source

Origin: Contractor Initiated

Reason for Change: To clarify original intent of specification.

Description of Change:

Page 49, Paragraph 3.12.9.2 PUMPS:
13th Line - Change sentence beginning on this line to
read as follows: "Each pump and its control relay shall
receive power from the same source."

SPEC NO: ZD-22-00 3 DATE:		DATE:		
CUSTOMER: Delta Ai	r Lines Inc.	MCL 10.147 Ptd 10 October 1957		
CHANGE NO: 1		MODEL: (880) 22-2		
TITLE: Airplane Co	nfiguration,	Detailed Revision to		
ORIGIN: Contractor	initiated			
REASON FOR CHANGE: To incorporate the latest external configuration of the airplane into the specification				
	EFFECT ON V	WEIGHT * EFFECT ON BALANCE *		
Guar. Wt. Empty	Oper. Wt. 1	empty o Inch Lb.		
EFFECT ON GUARANTEE	D PERFORMANC	E: *		
N	one			
* Negligible Change Totals Reflected				
Acceptance of thi Prior Acceptance	s Change is of the Follow	Dependent Upon wing Changes:		
		Engineering Approval		
LATEST DATE OF ACCE	CPTANCE:	AIRPLANES AFFECTED:		
DILIOINI THOVED TOND		EFFECT ON PRICE PER AIRPLANE: Recurring: Non-Recurring		
	- Andrews - Charles	Total:		
ACCEPTED:		CONVAIR, A Div. of Gen. Dyn. Corp.		
BY:		BY: Chief of Contract Administration		
DATE:				

CONVAIR: SD

Delta Air Lines Inc. Change No. 1

Page 1 of 4

Title: Airplane configuration, detailed revision to

Origin: Contractor initiated

Reason for Change: To incorporate the latest external configuration

of the airplane into the specification

Description of Change:

Page 13, Replace all data on the page with the following:

"3.1 CHARACTERISTICS (Cont)

3.1.3 DIMENSIONS AND DATA:

3.1.3.1 WING:

Airfoil Section Designation Root (Extended Chord) 31.51% semi-span (break) Tip Incidence: Root Span (Aerodynamic) Span (Overall) Area - Total (basic trapezoid) Root chord (basic) (extended) Tip Chord Dihedral (MCP) Aspect Ratio (basic trapezoid) Sweep (30% Chord) Mean Aerodynamic Chord (basic true) Flaps - Type

NACA 0011-64 Mod NACA 0009.08-64 Mod NACA 0008-64 Mod 2.0° 117'11.9" 120' 0" 2000 sq. ft. 27'0.7" 35'8.4" '6'9.0" 7.0° 7

Double Slotted

Delta Air Lines Inc. Change No. 1

Page 2 of 4

3.1.3.2	TAIL:	
3.1.3.2.1	HORIZONTAL Area Dihedral Sweep (30% Chord)	395 sq. ft. 7°30' 35.0°
3.1.3.2.2	VERTICAL: Area Sweep (30% Chord)	295 sq. ft. 35.0°
3.1.3.3	BODY: Maximum Width Maximum Height Length Height - Overall Maximum Cabin Interior (width) at constant Section	11'6" 12'5" 124'2" 36'0.3" 10'8"
(3.1-D2) (3.1-D4)	Cargo Compartment Capacities: Forward Aft	448 cu ft. 402 cu ft.

Page 37, Paragraph 3.8.4.7 STEERING CONTROL:

In fourth line, change the following:

From: 18 feet 9 inches

To: 19 feet 5 inches

In ninth line, change the following:

From: 81 feet 7 inches

To: 82 feet 10 inches

Pages 39 through 42, Paragraph 3.10, SURFACE CONTROL SYSTEM:

Revise the following subparagraphs to read as follows:

"3.10.1.2 AILERON SYSTEM: Ailerons and spoilers shall be used for lateral control. The ailerons shall be manually controlled by a separate cable system from each wheel and a separate cable system in each wing connecting to the aileron flight tab. The ailerons shall be interconnected by push pull tubes. The spoilers shall be hydraulically operated and shall be used at all speeds for lateral control as well as speed brakes. The spoiler

CONVAIR, S. D.

Delta Air Lines Inc. Change No. 1

Page 3 of 4

system shall have two independent hydraulic power systems. Lateral trim shall be accomplished by an irreversible trim tab located on each aileron and operated by a control wheel in the flight deck.

- RUDDER SYSTEM: The rudder shall be manually controlled by sets of rudder pedals provided for the pilot and copilot. A cable and push pull tube system shall interconnect the rudder and a spring tab on the rudder. Each set of rudder pedals shall be adjustable, fore and aft to accommodate pilots of different stature. Trim control shall be accomplished by an irreversible trim tab operated by a control wheel on the pedestal.
- 3.10.1.4 ELEVATOR SYSTEM: The elevator shall be manually controlled by wheel type control columns for the pilot and copilot.
 A cable push pull tube system shall interconnect the control columns and operate spring tabs on each elevator.
- 3.10.1.4.1 GUST LOCKS: Change title to "GUST PROTECTION" and revise paragraph as follows:

Hydraulic dampers shall be installed at each aileron, elevator and the rudder surfaces to prevent structural damage due to gusts. The dampers shall not adversely affect normal control forces in flight.

- 3.10.1.5 STABILIZER SYSTEM: The stabilizer shall be controllable to provide longitudinal trim. Movement shall be accomplished by hydraulic power (with a standby mechanical system). A red warning light will indicate an incorrect stabilizer setting for takeoff whenever the airplane is on the ground.
- LIFT AND DRAG INCREASING DEVICE SYSTEMS: The flaps shall be operated by a hydraulic motor driven gear box located in the fuselage powered by both hydraulic systems. Torque tubes shall connect the gear box to mechanical actuators at each flap section. The system shall be irreversible to prevent flap motion from airloads. The flaps shall be controlled by a lever on the pilots' pedestal. Flap position indication shall be provided. Full flap deflection shall be obtainable from either hydraulic system. A monitoring system shall be provided to prevent asymmetrical flap positioning in the event of mechanical failure.

CONVAIR, S. D.

Delta Air Lines Inc. Change No. 1

Page 4 of 4

3.10.2.2 SPEED BRAKES: (See Paragraphs 3.5.4.3 and 3.5.4.4) A separate speed brake control shall be provided in the pilots' compartment to extend the spoilers for use as speed brakes. Extension of the spoilers shall be permissible up to the VD speeds at all altitudes.

3.10.5

YAW DAMPER: A yaw damper shall be provided to improve riding qualities and handling characteristics of the basic airplane. The airplane shall be basically stable (non-divergent) under all normal flight conditions with the yaw damper inoperative. The yaw damper shall be designed so that it will fail safe and shall not induce unsafe loads in the event of malfunctioning".

Figure 1-1 GENERAL ARRANGEMENT, MODEL 22 JET TRANSPORT

Delete present figure from specification and substitute Enclosure: (A)

Figure 1-2, INBOARD PROFILE AND PLAN VIEW

Change figure to show revised forward and aft cargo compartment capacities and revise compartment shape.

Figure 1-3, ALTERNATE SEATING ARRANGEMENT

Change figure to show revised shape of cargo compartment spaces, in accordance with Enclosure (B)

Figure 3.1-1, C.G. DESIGN LIMITS

Replace present figure in Specification with Enclosure (C)

Enclosure: (A) Four (4) copies Figure 1-1, GENERAL ARRANGEMENT OF MODEL .
22 JET TRANSPORT

Enclosure: (B) Four (4) copies of sketch showing cross section of revised cargo compartment shape

Enclosure: (C) Four (4) copies Figure 3.1-1, C.G. DESIGN LIMITS

Effect on Weight Empty: 0
Effect on Balance: 0
Effect on Performance: None






FIGURE 1-1

GENERAL ARRANGEMENT MODEL 22 JET TRANSPORT



PAGE 12a REPORT NO ZD-22-003 MODEL 22



500 5A

FIGURE 3.1-1

C. G. Design Limits